

Weekly Engineering Report

Week 8
18 - 24 August



INDEX

- 1 Departmental Overview (HEAL)
- 2 Shafts & Winders Performance
- 3 Gloria Performance Overview
- 4 Nchwaning 2 Performance Overview
- 5 Nchwaning 3 Performance Overview
- 6 BEV Performance Overview

DEPARTMENTAL OVERVIEW (HEAL)

📈 Highlights

- ✅ **[Gloria]** Average availability ~90%
- ✅ **[Gloria]** Chute capital application submitted
- ✅ **[Gloria]** Capital Application — 1× 2-post basefree submitted
- ✅ **[Gloria]** New mini sub in 9 West section connected
- ✅ **[Nchwaning 2]** Progress on recruitment (shortlisting complete; adverts live)

📉 Lowlights

- ⚠️ **[Gloria]** Mining Cruiser availabilities low due to U-bolt part shortage
- ⚠️ **[Gloria]** RT0046 prop shaft/damages; HD0060 drifter oil leaks; HD0059 water hose reel
- ⚠️ **[Nchwaning 2]** DT181 failed quality inspection (returned feedback to supplier)
- ⚠️ **[Nchwaning 2]** Grader still on breakdown; Aard grader site evaluation arranged

+1 more

🕒 Emerging Issues

- 🕒 **[Gloria]** Plant labour shortage; acting artisans; TNC PPE gaps; audits due to N3 fire/DMRE
- 🕒 **[Nchwaning 2]** Sampling UVs still down (UV123 auto-levelling fault; UV77 harness lead time ~2 weeks); RT50 axle seized
- 🕒 **[Nchwaning 3]** Recovery actions from fire

🔧 Priorities

- 🔧 **[Gloria]** Plan conveyor belt type change (K→F); enforce RCA actions; WTW actions; Cruiser spares; UV conversion
- 🔧 **[Nchwaning 2]** Complete HD & RT audits by 25 Aug; submit HOD capital presentation
- 🔧 **[Nchwaning 3]** Inspect all S2 drill rigs; 3rd-party fire suppression inspections; repair all defects

Shafts & Winders Performance

Weekly Tons/Hr

Target: 523

377

Weekly RW Availability (%)

Target: 95%

93%

✓ Highlights

- First dewatering hole completed (@110m)

⚠ Lowlights

- Employee engagement/resignations; engagement with SGM due to culture issues identified in section
- DMPR visit findings

🕒 Emerging Issues

- Low complement of fitters and riggers in Mechanical Section is putting pressure on the section
- Large effort to provide full maintenance of changehouses of all 3 shafts

🔑 Priorities

- DMRE actions (attachments)
- Shaft repair work with Solrock team (weekend No.8)
- Implement recommendations from NLT FAC investigation
- Implement DMPR findings

Nchwaning 3 Weekly Availability Trend

Week Slicer

☐ Last Week

☒ This Week

Shift

N3


Prod Day

YES

Earliest Date Latest Date

18 Aug 2025 23 Aug 2025

Fleet Weekly Availability



DT Weekly Average

75%

Availability



FL Weekly Average

97%

Availability



HD Weekly Average

74%

Availability



RT Weekly Average

86%

Availability



SR Weekly Average

68%

Availability



Nchwaning 3 Performance Overview

⚠️ Safety

HD0054 catastrophic fire;
Section 54 stop to mining

Weekly Avg.

81%

(Target: 85%)

🔧 Compliance

DT 67%; FL 100%; HD 60%; RT 60%; SR 80%;
UV 100%; Support Equip
Utility Foreman 80%; DT
BEV 100%; FL BEV none
scheduled

Equipment Availability

DT

75%



FL

97%



HD

74%



RT

86%



SR

68%



Key Breakdowns / Issues




HD

- HD0062 2x drifters
- HD0051 power cable
- HD0052 seals

SR

- SR0024 boom broken
- SR0038 engine excessive smoke

Nchwaning 2 Weekly Availability Trend



Nchwaning 2 Performance Overview

✓ Safety

Weekly Avg.

88%

(Target: 85%)

⚙ Compliance

DT/FL/HD/RT 100%;
Support Equip 100%; SR
inspection 100%; SR
service none scheduled

Equipment Availability

DT

91%



FL

81%



HD

96%



RT

79%



SR

92%



Key Breakdowns / Issues

UV

- Sampling UVs down (UV123 auto-levelling fault; UV77 harness lead time ~2 weeks; borrowing from survey vehicles)

RT

- RT50 axle seized shortly after replacement

DT

- DT181 failed quality inspection (supplier notified)

Support

- Grader still on breakdown; Aard grad

Gloria Weekly Availability Trend

Week Slicer

☐ Last Week

☒ This Week

Shift

Gloria

Prod Day

YES

Earliest Date Latest Date

18 Aug 2025 23 Aug 2025

Fleet Weekly Availability



DT Weekly Average

99%


Availability



FL Weekly Average

98%

Availability



HD Weekly Average

79%

Availability



RT Weekly Average

49%

Availability



SR Weekly Average

89%

Availability



Gloria Performance Overview

✓ Safety

Weekly Avg.


89%

(Target: 85%)

⚙ Compliance

FL 100%; HD 100%; RT 50%; Support Equip 100%;
DT/SR/UV none scheduled

Equipment Availability



Key Breakdowns / Issues

HD

- HD0060 drifter-related faults and repairs (≈24.8 h across 20–21 Aug)
- HD0059 water hose reel repairs (≈5.3 h)
- HD0066 hoses/electrical issues (≈2.5–3 h)

RT

- RT0046 prop shaft breakdowns (≈34.9 h over 20–21 Aug)
- RT0045 fire suppression pin fault (≈6.8 h); electrical start issue (short)

BEV Fleet

📦 BEV Availability (Wk 8)

- DT BEV: 78% (Below Target)
- FL BEV: 91% (Above Target)

⚡ BEV Service Compliance

- DT BEV: 100%
- FL BEV: None scheduled

BEV Availability by Equipment Type

DT BEV

Target: 85%

78%

FL BEV

Target: 85%

91%

Key BEV & Battery Themes

Key Breakdowns:

DT BEV

- Top causes: Hydraulic oil leak @ battery bay: 144.00 h; Overheating @ battery bay: 36.15 h; Gears faulty @ battery bay: 32.62 h

FL BEV

- Top causes: Change 2 tyres – TBay (awaiting second tyre): 39.32 h; Window damaged: 38.60 h; Dashboard lights: 9.30 h

Key Battery Themes:

- STRATA 24v auto-electrical recurring faults
- 800v inverter unit failures
- Wipers/aux 24v electrical faults
- DT BEV batteries weekly average availability ≈ 90% (100, 96, 79, 92, 83%)
- FL BEV batteries weekly average availability ≈ 81% (78, 83, 79, 88, 75%)