

Production Engineering Weekly Overview Report

Week 36
02 Mar - 06 Mar 2026



INDEX

- 1 Departmental Overview (HEAL)
- 2 Nchwaning 3 Performance Overview
- 3 Nchwaning 2 Performance Overview
- 4 Gloria Performance Overview
- 5 BEV Performance Overview
- 6 Utility Performance

DEPARTMENTAL OVERVIEW (HEAL)

↗ Highlights

- ✓ [N3] Successfully hosted the ARM leadership at the BEV workshops
- ✓ [N2] The average availability is above 85% for the week on all TMMs
- ✓ [N2] Commissioned a new load FL0122 for capital development
- ✓ [Gloria] Zennith serviced three compressors
- ✓ [Gloria] Good improvement in CPS level 9

↘ Lowlights

- ⚠ [N3] LTI Case – Index Finger fracture
- ⚠ [N3] Overall sustained machines availability
- ⚠ [N3] Overall work attendance below par
- ⚠ [Gloria] Experiencing CV0052 safe line breakdowns resulting to remove guard limit switch and install locks
- ⚠ [Gloria] DTs availability was 79% - DT0174 Powelses, DT0152 Engine cut off
- ⚠ [Gloria] FLs availability was 77% - FL0119 No turbo available, FL0064 Overheating


🕒 Emerging Issues

- ⚠ [N3] CAS L9: LD's and UV's impacting productivity (Reliability of system)
- ⚠ [N3] Water management and balancing of the system at mining areas
- ⚠ [N2] OEM companies are not consistent in keeping PP360 compliant
- ⚠ [N2] DT121 and 122 indicated possible fuel dilution on Perfect Filtration report

🔑 Priorities

- ⚙ [N3] Complete GES and Forman's appointments
- ⚙ [N2] Enforce compliance through action plans
- ⚙ [N2] Align the team on factors affecting production
- ⚙ [Gloria] CV0088 and 51H Conveyor replacement
- ⚙ [Gloria] UV0129 axle to be delivered and replaced

Nchwaning 3 Weekly Availability Trend



Nchwaning 3 Performance Overview



Safety

LTI - Finger injury while moving a KSB pump



Weekly Avg.

83%

(Target: 85%)



Compliance

DT Diesel: 50%, SR: 60%,
All others: 100%

Equipment Availability

DT

76%



FL

77%



HD

87%



RT

87%



SR

78%



Key Breakdowns

Dump Trucks (76%): DT148 No Aircon/Mainswitch, DT131 Transmission Casing Cracked, DT118 Aircon

Front Loaders (77%): FL103 Starting Problem, FL101 Steering problem/Fire Supp/Bucket Control

Roof Bolters (87%): RT47 Radiator, RT51 Compressor


Scalers (78%): SR35 Engine Smoke, SR26 Boom Cylinder Broken, SR51 Fire Supp, SR38 Boom Nuts Broken

SR0035 engine installed commissioning to be done this week. DT0148 repairs to be focused on this week. FL0101 fixed, FL0103: Epiroc is assisting this week

Nchwaning 2 Weekly Availability Trend

Availability
88.09%


Earliest Date	Latest Date
3/2/2026	3/6/2026




DT
80.73%
Availability



FL
91.12%
Availability



HD
80.90%
Availability



RT
96.10%
Availability



SR
94.68%
Availability



Nchwaning 2 Performance Overview

✓ Safety

Zero incidents this week

Weekly Avg.

88.09%

(Target: 85%)

🔧 Compliance

FL: 100%, HD: 100%, SR:
100%, RT: 75%, Support:
67%

Equipment Availability

DT

81%



FL

91%



HD

81%



RT

96%



SR

95%




Key Breakdowns

Dump Trucks (80.73%): Below 85% target - DT121 Ignition issues, DT122 OEM to attend. Performance impacted Wed-Thu with drops to 74-75%

Haul Dumps (80.90%): Below 85% target - HD68 Feed sling. Lowest performance on Friday

Gloria Weekly Availability Trend



Gloria Performance Overview

✓ Safety

Zero incidents this week

Weekly Avg.

87%

(Target: 85%)

Compliance

FL: 100%, SR: 100%,
Support: 100%, DT: 0%,
HD: 50%, RT: 67%

Equipment Availability

DT

77%



FL

86%



HD

93%



RT

93%



SR

96%



Key Breakdowns

Dump Trucks (77%): Below 85% target - DT0174 Powelses, DT0152 Engine cut off

Front Loaders (86%): FL0093 Steering

MTD Fleet Average: 87%. CV0052 safe line breakdowns continue.

BEV Performance Overview (Nchwaning 3)

🔌 BEV Availability (Wk 36)

- DT BEV: 83% (Below Target)
- FL BEV: 87% (Above Target)

⚡ BEV Service Compliance

- DT BEV: 100%
- FL BEV: 0%

BEV Availability by Equipment Type

DT BEV

Target: 85%

83%

FL BEV

Target: 85%

87%

Key BEV & Battery Themes

Performance Summary:

- DT BEV at 83% - below target by 2%. DT0147 inverter error (24hrs), DT0149 no contact to modules (24hrs), DT0150 battery insulation fault (21hrs), DT0172 HVIL fault (10hrs).
- FL BEV at 87% - above target by 2%. FL0098 red stop lamp + battery not connecting (29hrs), FL0112 red stop lamp + oil leak (13hrs), FL0113 battery not connecting (11hrs).

Battery & Charger Status:

- B4 Batteries: 10 Working, 1 Breakdown (VPY-00034 TMS replaced, cooling pump issues) | B5 Batteries: 11 Working, 1 Breakdown (VPX-00010 TMS fault), 1 on DT-171 (out of production)
- All chargers operational. Charger 2 Module 2 faulty - other modules working. Charger 7 Module 4 switched on.
- TMS hyper care underway. Battery overheating: VPY-00011 condenser cleaned, VPY-00051 cooling pump failed, VPY-


DT: AVAILABILITY & BREAKDOWNS

⚠ BEV Availability

83%

Goal: 85% (-2.0%)

BEV Availability by Unit



Breakdown Details

Type	Machine_id	Comment	Hours
Mechanical	DT0147	Inverter error @ battery bay	24.38
Operational	DT0149	No one to change battery	15.45
Operational	DT0150	No one to change battery (battery bay)	10.22
Electrical	DT0172	HVIL fault not moving @ 13N	9.5
Auto Electrical	DT0149	No contact to modules (11e s2n)	8.37


FL: AVAILABILITY & BREAKDOWNS

✓ BEV Availability

87%

Goal: 85% (+2.0%)

BEV Availability by Unit



Breakdown Details

Type	Machine_id	Comment	Hours
Electrical	FL0098	Red stop lamp @ NW	17.27
Auto Electrical	FL0098	Batt not connecting @ S2N 5w Wplace	11.7
Mechanical	FL0112	Oil leak @ battery bay	6.87
Electrical	FL0112	Red stop lamp @ 10E/20N S2N	5.07
Operational	FL0107	Charge battery	2.4
Mechanical	FL0108	Replace transmission rubbers @ batt bay	2.1

UTILITY SECTION PERFORMANCE OVERVIEW



61

Available

Overall Fleet Availability

94%

61 of 65 units available



4

Unavailable

Area / Owner	Mon	Tue	Wed	Thu	Fri	Weekly Av. Avail.
Main West	1/2	1/2	1/2	1/2	2/2	70.0%
Boilermaker	2/3	2/3	2/3	2/3	2/3	66.7%
BEV	2/2	2/2	1/2	1/2	2/2	80.0%
Security	1/1	1/1	1/1	1/1	1/1	100.0%
Logistics	6/7	6/7	6/7	6/7	6/7	85.7%
Hyd Fitter	6/6	6/6	6/6	6/6	6/6	100.0%
Electricians	3/4	4/4	4/4	4/4	4/4	95.0%
Mechanics	3/3	3/3	3/3	3/3	3/3	100.0%
Sampling	2/2	2/2	2/2	2/2	2/2	100.0%
Construction	3/3	3/3	3/3	3/3	3/3	100.0%
Plant Fitter	6/7	6/7	6/7	6/7	6/7	85.7%
Central	1/2	1/2	1/2	1/2	2/2	70.0%
Explosive	1/1	1/1	1/1	1/1	1/1	100.0%
X Cut	1/1	1/1	1/1	1/1	1/1	100.0%
Utility TMM	2/2	2/2	2/2	2/2	2/2	100.0%
Other	18/18	18/18	18/18	18/18	18/18	100.0%
TOTAL	61/65	55/66	54/66	61/65	61/65	89.3%

UTILITY SECTION: UNAVAILABILITY DETAILS

Week 36 - All Unavailable Units

⚠ Weekly Breakdown Summary

Area/Owner	TMM No.	Model	Description - EOS / Breakdown	Remarks / Comment
Main West / Central	LD0520, LD0572	Maverick	Weekly Avg 77.8%	LD0520: Not Starting/Warning Signs (Tue-Wed), LD0572: Tag box damaged (Tue-Wed)
Boilermaker	LD0405	Maverick	Weekly Avg 66.7%	Engine commission - No communication between engine and machine (All week)
Logistics	UV0078, UV0081, UV0116	RORO	Weekly Avg 68%	UV0078: Rear axle/Steering cylinder (Mon-Fri), UV0081: Not selecting gears (Wed), UV0116: Front axle (Tue-Wed)
Construction / Seam 2	LD0574, LD0606, LD0622	Toyota	Weekly Avg 93.9%	LD0574: Not Starting (Tue-Wed), LD0606: Hub broken off (Tue-Wed), LD0622: Transfer box leaking (Tue-Wed)

Note: 1 unit(s) require OEM assistance

UTILITY SECTION CURRENT STATUS

Friday, 27 February 2026

⚠️ Unavailable Units by Area/Owner

Area/Owner	Unavailable	Details (Unit - Reason/Comment)
Boilermaker	1	LD0405 - Engine commission (No communication between engine and machine) - No solution from Fermel (Deutz EMR4 upgrade to EMR5)
Plant Fitter	1	LD0620 - Strata (Surface decline & No access to the gate, its locked) - (SOS - EOS)
Logistics	2	UV0078 - Rear axle - (SOS - EOS)

Total Unavailable: 4 units across 3 areas