

HYUNDAI MOTOR INDIA LTD.

GSTIN: 33AAACH2364M1ZM

No. 7, 4th Morrison Shired NOAd MOTEOR INDIANG MITTED 6771 60111 / 777 / 888.

Repair Estimate

Printing Time : 26/03/2018 10:08

Estimate No

S201800978

Date

: 26/03/2018

R/O No

Reg No

TN49AD8529

VIN

: MALAA51HR9M453586

Work Type

Model

SANTRO

Engine No : G4HG9M805901

Vehicel Color : B Red

Type

Insurance

Insurance Company

: Shriram General Insurance Company Limited

KARTHICK K

flat no:S7A,apt no 84,Ashok Manor apartments,alandur CHENNAL

Part Detail

Seq.	Part Description	Part No	Part Amt	Qty	Тах	Total	
1	PANEL-FENDER,LH*	6631105060	1,371.91	1	384.13	1,756.04	
2	COVER-FR BUMPER	8651105600	1,295.36	. 1	362,70	1,658.06	
3	LAMP ASSY-HEAD,LH	9210105530	3,048.85	1	548.79	3,597.64	

Labour Detail

Seq.	Operation Description	Labour Amt	Qty	Tax	Total
1	COVER-FR BUMPER	405.00	1	72.90	477.90 /
2	PANEL ASSY-FNDR LH	345.00	1	62.10	407.10
3	LH Fendor - Each (Water Borne Paint)	3,860.00	1	694.80	4,554.80

Total Amt

: 12,451.54

Part Amt

7.011.74

Labour Amt

: 5,439.80

1

Estimate Prepared by (name of Dealer Personnel)



I hereby authorised for the above repairs to be executed using necessary materials, and I am affixing my BIGRAPHPevidence of agreeing to the terms & conditions, given in reverse side of this estimate.

Date

Customer Signature