

ZSP-000001 — Electrical & Energy-Loss Risk Assessment

Electrical & Energy-Loss Risk Assessment | ZSP-000001

Project Details

Project: Electrical & Energy-Loss Risk Assessment
Project Reference: ZSP-000001
Client: ZORAYS KHALID
Site: Main Industrial Facility
Location: 56 K ST 3 PHASE 5 DHA LAHORE
Project Status: active
Start Date: 26 Jul 2026
Expected Completion: 26 Oct 2026
Overall Progress: 4%
Rectification: 0% | Evidence: 7% | Testing: 0% | Action Plan: 0%

Report Summary

Total Tasks: 15
In Progress: 15
Complete: 0
Before Evidence: 1
After Evidence: 1
Completion: 0%

Sr. No. 1

Description:
Panel door locks are damaged, allowing rainwater to enter the panel.

Status: In Progress
Before Evidence: 1 | After Evidence: 1

Sr. No. 2**Description:**

Component rating does not comply with the approved Single Line Diagram (SLD).

Status: In Progress

Before Evidence: 0 | After Evidence: 0

Sr. No. 3**Description:**

Breaker or single-pole MCB is faulty and requires replacement.

Status: In Progress

Before Evidence: 0 | After Evidence: 0

Sr. No. 4**Description:**

Earth Leakage Circuit (ELC) protection is not installed.

Status: In Progress

Before Evidence: 0 | After Evidence: 0

Sr. No. 5**Description:**

Neutral link is open/loose, resulting in unintended current flow.

Status: In Progress

Before Evidence: 0 | After Evidence: 0

Sr. No. 6**Description:**

Busbar is corroded and overheating, creating a potential risk of sparking.

Status: In Progress

Before Evidence: 0 | After Evidence: 0

Sr. No. 7**Description:**

Red and Yellow phase cables are undersized and do not meet the required current rating.

Status: In Progress

Before Evidence: 0 | After Evidence: 0

Sr. No. 8**Description:**

Push button is faulty, due to which the circuit has been connected in bypass mode.

Status: In Progress

Before Evidence: 0 | After Evidence: 0

Sr. No. 9**Description:**

Overload protection ratings are mismatched, causing circuit and load imbalance.

Status: In Progress

Before Evidence: 0 | After Evidence: 0

Sr. No. 10**Description:**

DOL starter and timer are bypassed, with the circuit connected directly.

Status: In Progress

Before Evidence: 0 | After Evidence: 0

Sr. No. 11**Description:**

Selector switches are faulty and require repair or replacement.

Status: In Progress

Before Evidence: 0 | After Evidence: 0

Sr. No. 12**Description:**

Terminal block requires replacement.

Status: In Progress

Before Evidence: 0 | After Evidence: 0

Sr. No. 13**Description:**

Basement Entrance Right – Ground Floor DB-01.

Status: In Progress

Before Evidence: 0 | After Evidence: 0

Sr. No. 14**Description:**

AC drain water is directly entering the DB, causing an earth leakage fault and resulting in smoke from the DB.

Status: In Progress

Before Evidence: 0 | After Evidence: 0

Sr. No. 15**Description:**

MCB breaker is faulty and requires replacement.

Status: In Progress

Before Evidence: 0 | After Evidence: 0

