

SiteCheck AI — Inspection Report

Session: 3a05d096591f

Date: 2026-06-11 03:20

Ruleset: IS456 | Units: metric

Compliance Score: 75.0/100

Checked: 8 elements — Pass 5, Warning 1, Fail 1, Inconclusive 1

Critical Issues


- wall failed check: wall: vertical deviation 6.26 cm/m (3.6° from plumb).

Element Findings

Element	Measurement	Expected	Deviation	Status
wall	plumb_angle_deg: 0.04 deg,...	—	0.07 cm/m	PASS
door	gap_asymmetry: 2.6 mm	—	2.65 mm	PASS
wall	plumb_angle_deg: 1.71 deg,...	—	—	INCONCLUSIVE
wall	plumb_angle_deg: 3.58 deg,...	—	6.26 cm/m	FAIL
door	gap_asymmetry: 2.6 mm	—	2.65 mm	PASS
beam	level_angle_deg: 0.06 deg,...	—	1.02 mm/m	PASS
door	gap_asymmetry: 9.7 mm	—	9.71 mm	PASS
door	gap_asymmetry: 29.8 mm	—	29.77 mm	WARNING


Photos Analysed

- case1_wall_plumb_pass.jpg — 2 elements
- Photo may be too dark — consider re-uploading with better lighting.
- Photo appears blurry — measurements may be unreliable.




- case2_wall_plumb_uncalibrated.jpg — 1 elements
- Photo may be too dark — consider re-uploading with better lighting.


- Photo appears blurry — measurements may be unreliable.



- case3_wall_plumb_fail.jpg — 2 elements
- Photo may be too dark — consider re-uploading with better lighting.
- Photo appears blurry — measurements may be unreliable.



- case4_beam_level_warning.jpg — 2 elements
- Photo may be too dark — consider re-uploading with better lighting.
- Photo appears blurry — measurements may be unreliable.



- case5_door_alignment_fail.jpg — 1 elements
- Photo may be too dark — consider re-uploading with better lighting.
- Photo appears blurry — measurements may be unreliable.

door ??? WARNING ??? 29.8mm



Recommendations

- Re-capture photo for wall — measurement inconclusive.
- Rectify wall deviation before proceeding.
- Review door: Door frame gap asymmetry ≈ 29.8 mm.

Note: Measurements are computed from pixel-level geometry. Values without scale calibration are marked estimated/inconclusive.