


heating received so far



electronics send the firing time
down the wires

blanket and bag may fail;
a freed sphere drifts outward up to 9 cm

Kevlar wire

wires pass the temperature at which
they keep their strength (-0.24 s)

each sphere's clock fires its detonator
(tens of ms)