	1.211					
		abla				
16x2 LCD RS	(XCK/T0) PB0 □	1 4	0 PA0 (ADC0)	ADC0		
16x2 LCD R/W	(T1) PB1 □	2 3	9 PA1 (ADC1)	ADC1		
16x2 LCD EN	(INT2/AIN0) PB2 □	3 3	8 PA2 (ADC2)	ADC2		
Push Button Switch	(OCO/AIN1) PB3 [4 3	7 PA3 (ADC3)	ADC3		
16x2 LCD BIT 4	(SS) PB4 □	5 3	6 PA4 (ADC4)	ADC4		
16x2 LCD BIT 5	(MOSI) PB5 🗆	6 3	5 PA5 (ADC5)	ADC5		
16x2 LCD BIT 6	(MISO) PB6 □	7 3	4 PA6 (ADC6)	LED Bit0		
16x2 LCD BIT 7	(SCK) PB7 □	8 3	3 PA7 (ADC7)	LED Bit1		
Power on Reset with push button	RESET [9 3	2 AREF	Trim Pot		
5V from LDO	VCC [10 3	1 GND	Gnd		
Gnd	GND □	11 3	0 AVCC	5V from LDO		
Xtal 16Mhz	XTAL2	12 2	9 PC7 (TOSC2)	Sensor 7		
Xtal 16Mhz	XTAL1 □	13 2	8 PC6 (TOSC1)	Sensor 6		
Program and Debug Tx	(RXD) PD0 □	14 2	7 DC5 (TDI)	Sensor 5		
Program and Debug Rx	(TXD) PD1 □	15 2	6 PC4 (TDO)	Sensor 4		
Left Motor Logic Bit 1	(INT0) PD2 □	16 2	5 PC3 (TMS)	Sensor 3		
Left Motor Logic Bit 2	(INT1) PD3 \square	17 2	4 DC2 (TCK)	Sensor 2		
Left Motor PWM	(OC1B) PD4 □	18 2	3 PC1 (SDA)	Sensor 1		
Right Motor PWM	(OC1A) PD5 🗆	19 2	2 PC0 (SCL)	Sensor 0		
Right Motor Logic Bit 1	(ICP1) PD6 □	20 2	1 PD7 (OC2)	Right Motor Logic Bit 2		