Fault Code Detail

Jul 7, 2020 - 6:50 AM EDT

Date Jul 6, 2020

1001

| Fault Code | FMI | Description | Source | First Detected | Last Observed | Туре | Status |
|------------|-----|----------------------------------------------------------------------|--------------------------------|----------------|-----------------|--------------|--------|
| SPN-4364 | 18 | Aftertreatment 1 SCR Conversion Efficiency | Exhaust Emission Controller | Jul 6, 5:50 PM | Jul 6, 11:59 PM | Constant | Open |
| SPN-3364 | 2 | Aftertreatment 1 Diesel Exhaust Fluid Tank Quality | Exhaust Emission Controller | Jul 6, 5:50 PM | Jul 6, 11:59 PM | Constant | Open |
| SPN-3226 | 20 | Aftertreatment 1 Outlet NOx 1 | Exhaust Emission Controller | Jul 6, 5:51 PM | Jul 6, 11:59 PM | Constant | Open |
| SPN-5397 | 31 | Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent | Exhaust Emission Controller | Jul 6, 8:56 PM | Jul 6, 11:59 PM | Constant | Open |
| SPN-5246 | 16 | Aftertreatment SCR Operator Inducement Severity | Exhaust Emission Controller | Jul 6, 5:50 PM | Jul 6, 10:32 PM | Intermittent | Open |
| SPN-5246 | 0 | Aftertreatment SCR Operator Inducement Severity | Exhaust Emission Controller | Jul 6, 8:11 PM | Jul 6, 10:32 PM | Intermittent | Open |
| SPN-5246 | 15 | Aftertreatment SCR Operator Inducement Severity | Exhaust Emission Controller | Jul 6, 5:50 PM | Jul 6, 10:32 PM | Intermittent | Open |