

#	Unit	Problem	Repair Required	Materials	Responsible Party	Mat. Cost	Labour	Total Cost	Status
B602									
1	B602	Kitchen sink blocked		—	Management / Property Owner <i>FORMER CLIENT</i>	—	—	—	New
2	B602	Bottle trap faulty/blocked		—	Management / Property Owner <i>FORMER CLIENT</i>	—	—	—	New
A401									
3	A401	Guest toilet shaking		—	Pending Assessment	—	—	—	New
4	A401	Bad/awful smell from the toilet		—	Pending Assessment	—	—	—	New
5	A401	Hand-washing basin blocked		—	Tenant	—	—	—	New
6	A401	Sitting room light faulty		—	Pending Assessment	—	—	—	New
7	A401	Kitchen drawers faulty		—	Pending Assessment	—	—	—	New
8	A401	Paint peeling off		—	Management / Property Owner	—	—	—	New
9	A401	Living room light faulty		—	Management / Property Owner <i>general maintenance</i>	—	1,200	1,200	New
A102									
10	A102	Bottle trap issue		—	Tenant	—	—	—	New
A602									
11	A602	Hand-washing basin bottle trap issue		—	Tenant	—	—	—	New
12	A602	Tap faulty		—	Management / Property Owner <i>general maintainance</i>	—	—	—	New
A302									
13	A302	Hand-washing basin tap faulty		—	Tenant	—	—	—	New
C102									

#	Unit	Problem	Repair Required	Materials	Responsible Party	Mat. Cost	Labour	Total Cost	Status
14	C102	Bottle trap issue		—	Tenant	—	—	—	New
15	C102	Kitchen sink leaking		—	Tenant	—	—	—	New
A502									
16	A502	Shower & soap holder faulty/broken		—	Management / Property Owner FORMER CLIENT	—	—	—	New
17	A502	Shower issue & kitchen malpas		—	Management / Property Owner FORMER CLIENT	—	—	—	New
C402									
18	C402	Bottle trap issue		—	Tenant	—	—	—	New
B202									
19	B202	Bottle trap issue		—	Tenant	—	—	—	New
C201									
20	C201	Socket stuck/faulty		—	Pending Assessment	—	—	—	New
21	C201	Bottle trap issue		—	Pending Assessment	—	—	—	New
B601									
22	B601	Low water pressure in the toilets		—	Pending Assessment	—	—	—	New
23	B601	Water pressure is insufficient, affecting the shower operation		—	Management / Property Owner general maintainance	—	—	—	New
B102									
24	B102	Shower faulty		—	Pending Assessment	—	—	—	New
C302									
25	C302	Kitchen drawers faulty		—	Pending Assessment	—	—	—	New
B401									
26	B401	Shower not working		—	Pending Assessment	—	—	—	New
27	B401	Sink leaking		—	Tenant	—	300	300	New
C601									
28	C601	Tap broken		—	Management / Property Owner genaral maintainane	—	750	750	New
29	C601	Roof leaking		—	Management / Property Owner genaral maintainane	—	—	—	New
A301									
30	A301	Low flushing pressure		—	Management / Property Owner genaral maintainane	—	—	—	New
31	A301	Sitting room light faulty		—	Management / Property Owner genaral maintainane	—	1,200	1,200	New
GB01									
32	GB01	Soap dish broken		—	Tenant	—	1,000	1,000	New
C501									
33	C501	Kitchen tap/sink tap		—	Management / Property Owner genaral maintainane	—	750	750	New

#	Unit	Problem	Repair Required	Materials	Responsible Party	Mat. Cost	Labour	Total Cost	Status
		not emitting water							
34	C501	Tiles next to the kitchen sink have detached		—	Pending Assessment	—	—	—	New
35	C501	All kitchen cabinet handles are faulty		—	Pending Assessment	—	—	—	New

Labour involved: —

TOTAL MATERIAL COST	KES 0
TOTAL LABOUR COST	KES 5,200
TOTAL REPAIR COST	KES 5,200

This work order authorizes the listed repairs. The corresponding maintenance invoice is raised on completion.