

#	Unit	Problem	Repair Required	Materials	Responsible Party	Mat. Cost	Labour	Total Cost	Status
A401									
1	A401	Living room light faulty		—	Management / Property Owner <i>general maintenance</i>	—	—	—	New
2	A401	Kitchen drawers faulty		—	Tenant	—	—	—	New
3	A401	Paint peeling off		—	Management / Property Owner <i>general maintenance</i>	—	—	—	New
A502									
4	A502	Shower soap holder faulty/broken		—	Management / Property Owner <i>FORMER CLIENT</i>	—	—	—	New
5	A502	Kitchen cabinet malpas/hinges are rusted and require replacement		—	Management / Property Owner <i>FORMER CLIENT</i>	—	—	—	New
C201									
6	C201	Socket stuck/faulty		—	Tenant	—	—	—	New
C302									
7	C302	Kitchen drawers faulty		—	Tenant	—	—	—	New
B102									
8	B102	Shower faulty		—	Management / Property Owner <i>general maintenance</i>	—	—	—	New
B401									
9	B401	Shower not working		—	Management / Property Owner <i>general maintenance</i>	—	—	—	New
C601									
10	C601	Roof leaking		—	Management / Property Owner <i>general maintenance</i>	—	—	—	New
A301									
11	A301	Living room light faulty		—	Management / Property Owner <i>general maintenance</i>	—	—	—	New
GB01									

#	Unit	Problem	Repair Required	Materials	Responsible Party	Mat. Cost	Labour	Total Cost	Status
12	GB01	Soap dish broken		—	Tenant	—	—	—	New
C501									
13	C501	Tiles next to the kitchen sink have detached		—	Pending Assessment	—	—	—	New
14	C501	All cabinet handles are faulty		—	Tenant	—	—	—	New
A202									
15	A202	When power was restored, there was an electrical surge/abnormally high voltage that caused some sockets to explode and stop functioning		—	Pending Assessment	—	—	—	New
16	A202	Some electrical appliances, including the refrigerator and television, were damaged as a result of the electrical surge		—	Pending Assessment	—	—	—	New
17	A202	The affected sockets require replacement		—	Pending Assessment	—	—	—	New
18	A202	Electrical cables/wiring should also be inspected to determine whether they were damaged and require replacement		—	Pending Assessment	—	—	—	New
a602									
19	a602	-shower faulty		—	Management / Property Owner general maintenance	—	—	—	New

Labour involved: —

TOTAL MATERIAL COST	KES 0
TOTAL LABOUR COST	KES 0
TOTAL REPAIR COST	KES 0

This work order authorizes the listed repairs. The corresponding maintenance invoice is raised on completion.