







AC01-R1-C1 AC01 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC01-R1-C2 AC01 fn=stock fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK




AC01-R1-C3 AC01 fn=stock chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC01-R2-C1 AC01 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC01-R2-C2 AC01 fn=8 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK




AC01-R2-C3 AC01 fn=8 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC01-R3-C1 AC01 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC01-R3-C2 AC01 fn=19 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK




AC01-R3-C3 AC01 fn=19 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC01-R4-C1 AC01 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC01-R4-C2 AC01 fn=32 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK




AC01-R4-C3 AC01 fn=32 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC01-R5-C1 AC01 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC01-R5-C2 AC01 fn=64 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK




AC01-R5-C3 AC01 fn=64 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC02-R1-C1 AC02 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC02-R1-C2 AC02 fn=stock fillet
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=1 none=2
VALID warnings=0 OK




AC02-R1-C3 AC02 fn=stock chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC02-R2-C1 AC02 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC02-R2-C2 AC02 fn=8 fillet
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=1 none=2
VALID warnings=0 OK




AC02-R2-C3 AC02 fn=8 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC02-R3-C1 AC02 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC02-R3-C2 AC02 fn=19 fillet
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=1 none=2
VALID warnings=0 OK




AC02-R3-C3 AC02 fn=19 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC02-R4-C1 AC02 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC02-R4-C2 AC02 fn=32 fillet
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=1 none=2
VALID warnings=0 OK




AC02-R4-C3 AC02 fn=32 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC02-R5-C1 AC02 fn=64 original
- folds=0 -
VALID warnings=0 OK



AC02-R5-C2 AC02 fn=64 fillet
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=1 none=2
VALID warnings=0 OK




AC02-R5-C3 AC02 fn=64 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC03-R1-C1 AC03 fn=stock original
- folds=0 -
VALID warnings=0 OK



AC03-R1-C2 AC03 fn=stock fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=12 none=0
VALID warnings=0 OK



AC03-R1-C3 AC03 fn=stock chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=12 none=0
VALID warnings=0 OK




AC03-R2-C1 AC03 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC03-R2-C2 AC03 fn=8 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=12 none=0
VALID warnings=0 OK



AC03-R2-C3 AC03 fn=8 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=12 none=0
VALID warnings=0 OK




AC03-R3-C1 AC03 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC03-R3-C2 AC03 fn=19 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=12 none=0
VALID warnings=0 OK



AC03-R3-C3 AC03 fn=19 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=12 none=0
VALID warnings=0 OK




AC03-R4-C1 AC03 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC03-R4-C2 AC03 fn=32 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=12 none=0
VALID warnings=0 OK



AC03-R4-C3 AC03 fn=32 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=12 none=0
VALID warnings=0 OK




AC03-R5-C1 AC03 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC03-R5-C2 AC03 fn=64 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=12 none=0
VALID warnings=0 OK




AC03-R5-C3 AC03 fn=64 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=12 none=0
VALID warnings=0 OK




AC04-R1-C1 AC04 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC04-R1-C2 AC04 fn=stock fillet
capTri folds=0 tube=0 capTri=1 cap=0 coons=0 saddle=0 flat=3 fan=0 weld=3 none=0
VALID warnings=0 OK



AC04-R1-C3 AC04 fn=stock chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=4 weld=3 none=0
VALID warnings=0 OK




AC04-R2-C1 AC04 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC04-R2-C2 AC04 fn=8 fillet
capTri folds=0 tube=0 capTri=1 cap=0 coons=0 saddle=0 flat=3 fan=0 weld=3 none=0
VALID warnings=0 OK




AC04-R2-C3 AC04 fn=8 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=4 weld=3 none=0
VALID warnings=0 OK




AC04-R3-C1 AC04 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC04-R3-C2 AC04 fn=19 fillet
capTri folds=0 tube=0 capTri=1 cap=0 coons=0 saddle=0 flat=3 fan=0 weld=3 none=0
VALID warnings=0 OK




AC04-R3-C3 AC04 fn=19 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=4 weld=3 none=0
VALID warnings=0 OK




AC04-R4-C1 AC04 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC04-R4-C2 AC04 fn=32 fillet
capTri folds=0 tube=0 capTri=1 cap=0 coons=0 saddle=0 flat=3 fan=0 weld=3 none=0
VALID warnings=0 OK




AC04-R4-C3 AC04 fn=32 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=4 weld=3 none=0
VALID warnings=0 OK




AC04-R5-C1 AC04 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC04-R5-C2 AC04 fn=64 fillet
capTri folds=0 tube=0 capTri=1 cap=0 coons=0 saddle=0 flat=3 fan=0 weld=3 none=0
VALID warnings=0 OK




AC04-R5-C3 AC04 fn=64 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=4 weld=3 none=0
VALID warnings=0 OK




AC05-R1-C1 AC05 fn=stock original
- folds=0 -
VALID warnings=0 OK



AC05-R1-C2 AC05 fn=stock fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=14 none=0
VALID warnings=0 OK




AC05-R1-C3 AC05 fn=stock chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=14 none=0
VALID warnings=0 OK




AC05-R2-C1 AC05 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC05-R2-C2 AC05 fn=8 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=14 none=0
VALID warnings=0 OK




AC05-R2-C3 AC05 fn=8 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=14 none=0
VALID warnings=0 OK




AC05-R3-C1 AC05 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC05-R3-C2 AC05 fn=19 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=1 weld=13 none=0
VALID warnings=0 OK




AC05-R3-C3 AC05 fn=19 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=14 none=0
VALID warnings=0 OK




AC05-R4-C1 AC05 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC05-R4-C2 AC05 fn=32 fillet
capTri folds=2 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=1 weld=13 none=0
VALID warnings=0 OK




AC05-R4-C3 AC05 fn=32 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=14 none=0
VALID warnings=0 OK




AC05-R5-C1 AC05 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC05-R5-C2 AC05 fn=64 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=12 none=0
VALID warnings=0 OK




AC05-R5-C3 AC05 fn=64 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=14 none=0
VALID warnings=0 OK




AC06-R1-C1 AC06 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC06-R1-C2 AC06 fn=stock fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC06-R1-C3 AC06 fn=stock chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=16 none=0
VALID warnings=0 OK




AC06-R2-C1 AC06 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC06-R2-C2 AC06 fn=8 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC06-R2-C3 AC06 fn=8 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=16 none=0
VALID warnings=0 OK




AC06-R3-C1 AC06 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC06-R3-C2 AC06 fn=19 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC06-R3-C3 AC06 fn=19 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=16 none=0
VALID warnings=0 OK




AC06-R4-C1 AC06 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC06-R4-C2 AC06 fn=32 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC06-R4-C3 AC06 fn=32 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=16 none=0
VALID warnings=0 OK



AC06-R5-C1 AC06 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC06-R5-C2 AC06 fn=64 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC06-R5-C3 AC06 fn=64 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=16 none=0
VALID warnings=0 OK




AC07-R1-C1 AC07 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC07-R1-C2 AC07 fn=stock fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC07-R1-C3 AC07 fn=stock chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=26 none=0
VALID warnings=0 OK




AC07-R2-C1 AC07 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC07-R2-C2 AC07 fn=8 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC07-R2-C3 AC07 fn=8 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=26 none=0
VALID warnings=0 OK




AC07-R3-C1 AC07 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC07-R3-C2 AC07 fn=19 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC07-R3-C3 AC07 fn=19 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=26 none=0
VALID warnings=0 OK




AC07-R4-C1 AC07 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC07-R4-C2 AC07 fn=32 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC07-R4-C3 AC07 fn=32 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=26 none=0
VALID warnings=0 OK




AC07-R5-C1 AC07 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC07-R5-C2 AC07 fn=64 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC07-R5-C3 AC07 fn=64 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=26 none=0
VALID warnings=0 OK




AC08-R1-C1 AC08 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC08-R1-C2 AC08 fn=stock fillet
capTri folds=0 tube=0 capTri=12 cap=0 coons=0 saddle=0 flat=2 fan=2 weld=30 none=0
VALID warnings=0 OK




AC08-R1-C3 AC08 fn=stock chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=30 none=0
VALID warnings=1 OK




AC08-R2-C1 AC08 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC08-R2-C2 AC08 fn=8 fillet
capTri folds=0 tube=0 capTri=12 cap=0 coons=0 saddle=0 flat=2 fan=2 weld=30 none=0
VALID warnings=0 OK




AC08-R2-C3 AC08 fn=8 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=30 none=0
VALID warnings=1 OK




AC08-R3-C1 AC08 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC08-R3-C2 AC08 fn=19 fillet
tube folds=0 tube=2 capTri=10 cap=2 coons=0 saddle=0 flat=1 fan=1 weld=26 none=0
VALID warnings=1 OK




AC08-R3-C3 AC08 fn=19 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=30 none=0
VALID warnings=1 OK




AC08-R4-C1 AC08 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC08-R4-C2 AC08 fn=32 fillet
tube folds=0 tube=2 capTri=10 cap=2 coons=0 saddle=0 flat=1 fan=1 weld=26 none=0
VALID warnings=1 OK




AC08-R4-C3 AC08 fn=32 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=30 none=0
VALID warnings=1 OK




AC08-R5-C1 AC08 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC08-R5-C2 AC08 fn=64 fillet
tube folds=0 tube=2 capTri=10 cap=2 coons=0 saddle=0 flat=1 fan=1 weld=26 none=0
VALID warnings=1 OK




AC08-R5-C3 AC08 fn=64 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=30 none=0
VALID warnings=1 OK




AC09-R1-C1 AC09 fn=stock original
- folds=0 -
VALID warnings=0 OK



AC09-R1-C2 AC09 fn=stock fillet
tube folds=0 tube=4 capTri=12 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=28 none=0
VALID warnings=0 OK




AC09-R1-C3 AC09 fn=stock chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=12 weld=28 none=0
VALID warnings=0 OK




AC09-R2-C1 AC09 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC09-R2-C2 AC09 fn=8 fillet
tube folds=0 tube=4 capTri=12 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=28 none=0
VALID warnings=0 OK




AC09-R2-C3 AC09 fn=8 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=12 weld=28 none=0
VALID warnings=0 OK




AC09-R3-C1 AC09 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC09-R3-C2 AC09 fn=19 fillet
tube folds=0 tube=4 capTri=12 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=28 none=0
VALID warnings=0 OK




AC09-R3-C3 AC09 fn=19 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=12 weld=28 none=0
VALID warnings=0 OK




AC09-R4-C1 AC09 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC09-R4-C2 AC09 fn=32 fillet
tube folds=0 tube=4 capTri=12 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=28 none=0
VALID warnings=0 OK




AC09-R4-C3 AC09 fn=32 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=12 weld=28 none=0
VALID warnings=0 OK




AC09-R5-C1 AC09 fn=64 original
- folds=0 -
VALID warnings=0 OK



AC09-R5-C2 AC09 fn=64 fillet
tube folds=0 tube=4 capTri=12 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=28 none=0
VALID warnings=0 OK




AC09-R5-C3 AC09 fn=64 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=12 weld=28 none=0
VALID warnings=0 OK




AC10-R1-C1 AC10 fn=stock original
- folds=0 -
VALID warnings=0 OK



AC10-R1-C2 AC10 fn=stock fillet
tube folds=2 tube=4 capTri=12 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK



AC10-R1-C3 AC10 fn=stock chamfer
fan folds=2 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=16 weld=26 none=0
VALID warnings=0 OK




AC10-R2-C1 AC10 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC10-R2-C2 AC10 fn=8 fillet
tube folds=2 tube=4 capTri=12 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC10-R2-C3 AC10 fn=8 chamfer
fan folds=2 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=16 weld=26 none=0
VALID warnings=0 OK




AC10-R3-C1 AC10 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC10-R3-C2 AC10 fn=19 fillet
tube folds=2 tube=4 capTri=12 cap=0 coons=0 saddle=0 flat=1 fan=0 weld=25 none=0
VALID warnings=0 OK



AC10-R3-C3 AC10 fn=19 chamfer
fan folds=2 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=16 weld=26 none=0
VALID warnings=0 OK




AC10-R4-C1 AC10 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC10-R4-C2 AC10 fn=32 fillet
tube folds=2 tube=4 capTri=12 cap=0 coons=0 saddle=0 flat=1 fan=0 weld=25 none=0
VALID warnings=0 OK



AC10-R4-C3 AC10 fn=32 chamfer
fan folds=2 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=16 weld=26 none=0
VALID warnings=0 OK




AC10-R5-C1 AC10 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC10-R5-C2 AC10 fn=64 fillet
tube folds=2 tube=4 capTri=15 cap=0 coons=0 saddle=0 flat=1 fan=0 weld=25 none=0
VALID warnings=0 OK




AC10-R5-C3 AC10 fn=64 chamfer
fan folds=2 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=16 weld=26 none=0
VALID warnings=0 OK




AC10b-R1-C1 AC10b fn=stock original
- folds=0 -
VALID warnings=0 OK




AC10b-R1-C2 AC10b fn=stock fillet
tube folds=0 tube=2 capTri=12 cap=1 coons=0 saddle=0 flat=1 fan=1 weld=34 none=0
VALID warnings=1 OK




AC10b-R1-C3 AC10b fn=stock chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=17 weld=37 none=0
VALID warnings=1 OK




AC10b-R2-C1 AC10b fn=8 original
- folds=0 -
VALID warnings=0 OK




AC10b-R2-C2 AC10b fn=8 fillet
tube folds=0 tube=2 capTri=12 cap=1 coons=0 saddle=0 flat=1 fan=1 weld=34 none=0
VALID warnings=1 OK




AC10b-R2-C3 AC10b fn=8 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=17 weld=37 none=0
VALID warnings=1 OK




AC10b-R3-C1 AC10b fn=19 original
- folds=0 -
VALID warnings=0 OK




AC10b-R3-C2 AC10b fn=19 fillet
capTri folds=0 tube=0 capTri=12 cap=0 coons=2 saddle=0 flat=0 fan=4 weld=31 none=0
VALID warnings=1 OK




AC10b-R3-C3 AC10b fn=19 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=17 weld=37 none=0
VALID warnings=1 OK




AC10b-R4-C1 AC10b fn=32 original
- folds=0 -
VALID warnings=0 OK




AC10b-R4-C2 AC10b fn=32 fillet
tube folds=1 tube=2 capTri=12 cap=0 coons=0 saddle=1 flat=0 fan=3 weld=34 none=0
VALID warnings=1 OK




AC10b-R4-C3 AC10b fn=32 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=17 weld=37 none=0
VALID warnings=1 OK




AC10b-R5-C1 AC10b fn=64 original
- folds=0 -
VALID warnings=0 OK




AC10b-R5-C2 AC10b fn=64 fillet
capTri folds=0 tube=0 capTri=12 cap=0 coons=0 saddle=1 flat=0 fan=5 weld=31 none=0
VALID warnings=1 OK




AC10b-R5-C3 AC10b fn=64 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=17 weld=37 none=0
VALID warnings=1 OK




AC11-R1-C1 AC11 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC11-R1-C2 AC11 fn=stock fillet
tube folds=0 tube=3 capTri=11 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC11-R1-C3 AC11 fn=stock chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=3 fan=11 weld=26 none=0
VALID warnings=0 OK




AC11-R2-C1 AC11 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC11-R2-C2 AC11 fn=8 fillet
tube folds=0 tube=3 capTri=11 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC11-R2-C3 AC11 fn=8 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=3 fan=11 weld=26 none=0
VALID warnings=0 OK




AC11-R3-C1 AC11 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC11-R3-C2 AC11 fn=19 fillet
tube folds=0 tube=3 capTri=11 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC11-R3-C3 AC11 fn=19 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=3 fan=11 weld=26 none=0
VALID warnings=0 OK




AC11-R4-C1 AC11 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC11-R4-C2 AC11 fn=32 fillet
tube folds=0 tube=3 capTri=11 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC11-R4-C3 AC11 fn=32 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=3 fan=11 weld=26 none=0
VALID warnings=0 OK




AC11-R5-C1 AC11 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC11-R5-C2 AC11 fn=64 fillet
tube folds=0 tube=3 capTri=11 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC11-R5-C3 AC11 fn=64 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=3 fan=11 weld=26 none=0
VALID warnings=0 OK




AC12-R1-C1 AC12 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC12-R1-C2 AC12 fn=stock fillet
capTri folds=0 tube=0 capTri=12 cap=0 coons=0 saddle=0 flat=0 fan=4 weld=0 none=0
VALID warnings=0 OK




AC12-R1-C3 AC12 fn=stock chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=16 weld=0 none=0
VALID warnings=0 OK




AC12-R2-C1 AC12 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC12-R2-C2 AC12 fn=8 fillet
capTri folds=0 tube=0 capTri=12 cap=0 coons=0 saddle=0 flat=0 fan=4 weld=0 none=0
VALID warnings=0 OK




AC12-R2-C3 AC12 fn=8 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=16 weld=0 none=0
VALID warnings=0 OK




AC12-R3-C1 AC12 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC12-R3-C2 AC12 fn=19 fillet
capTri folds=0 tube=0 capTri=12 cap=0 coons=2 saddle=0 flat=0 fan=2 weld=0 none=0
VALID warnings=0 OK




AC12-R3-C3 AC12 fn=19 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=16 weld=0 none=0
VALID warnings=0 OK




AC12-R4-C1 AC12 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC12-R4-C2 AC12 fn=32 fillet
capTri folds=2 tube=0 capTri=12 cap=0 coons=0 saddle=2 flat=0 fan=2 weld=0 none=0
VALID warnings=0 OK




AC12-R4-C3 AC12 fn=32 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=16 weld=0 none=0
VALID warnings=0 OK




AC12-R5-C1 AC12 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC12-R5-C2 AC12 fn=64 fillet
capTri folds=2 tube=0 capTri=12 cap=0 coons=0 saddle=2 flat=0 fan=2 weld=0 none=0
VALID warnings=0 OK




AC12-R5-C3 AC12 fn=64 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=16 weld=0 none=0
VALID warnings=0 OK




AC13-R1-C1 AC13 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC13-R1-C2 AC13 fn=stock fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=0 weld=144 none=0 fan folds=0
VALID warnings=0 OK




AC13-R1-C3 AC13 fn=stock chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=4 weld=144 none=0 fan folds=0
VALID warnings=0 OK




AC13-R2-C1 AC13 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC13-R2-C2 AC13 fn=8 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=0 weld=144 none=0 fan folds=0
VALID warnings=0 OK




AC13-R2-C3 AC13 fn=8 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=4 weld=144 none=0 fan folds=0
VALID warnings=0 OK




AC13-R3-C1 AC13 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC13-R3-C2 AC13 fn=19 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=0 weld=144 none=0 fan folds=0
VALID warnings=0 OK




AC13-R3-C3 AC13 fn=19 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=4 weld=144 none=0 fan folds=0
VALID warnings=0 OK




AC13-R4-C1 AC13 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC13-R4-C2 AC13 fn=32 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=0 weld=144 none=0 fan folds=0
VALID warnings=0 OK




AC13-R4-C3 AC13 fn=32 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=4 weld=144 none=0 fan folds=0
VALID warnings=0 OK



AC13-R5-C1 AC13 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC13-R5-C2 AC13 fn=64 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=0 weld=144 none=0 fan folds=0
VALID warnings=0 OK




AC13-R5-C3 AC13 fn=64 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=4 weld=144 none=0 fan folds=0
VALID warnings=0 OK


atomic bench -- AC14: the trough wall is a coarsely faceted cylinder; the crease is a arc



AC14-R1-C1 AC14 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC14-R1-C2 AC14 fn=stock fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=2 flat=2 fan=2 weld=44 none=0 fan folds=0
VALID warnings=1 OK




AC14-R1-C3 AC14 fn=stock chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=12 weld=56 none=0 fan folds=0
VALID warnings=0 OK




AC14-R2-C1 AC14 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC14-R2-C2 AC14 fn=8 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=1 weld=54 none=0 fan folds=0
VALID warnings=0 OK




AC14-R2-C3 AC14 fn=8 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=56 none=0 fan folds=0
VALID warnings=0 OK




AC14-R3-C1 AC14 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC14-R3-C2 AC14 fn=19 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=54 none=0 fan folds=0
VALID warnings=0 OK




AC14-R3-C3 AC14 fn=19 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=54 none=0 fan folds=0
VALID warnings=0 OK




AC14-R4-C1 AC14 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC14-R4-C2 AC14 fn=32 fillet
tube folds=0 tube=2 capTri=8 cap=0 coons=0 saddle=0 flat=2 fan=9 weld=53 none=0 fan folds=0
VALID warnings=0 OK




AC14-R4-C3 AC14 fn=32 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=19 weld=53 none=0 fan folds=0
VALID warnings=0 OK




AC14-R5-C1 AC14 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC14-R5-C2 AC14 fn=64 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=56 none=0 fan folds=0
VALID warnings=0 OK




AC14-R5-C3 AC14 fn=64 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=12 weld=56 none=0 fan folds=0
VALID warnings=0 OK




AC15-R1-C1 AC15 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC15-R1-C2 AC15 fn=stock fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=2 none=0
VALID warnings=1 OK




AC15-R1-C3 AC15 fn=stock chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=2 none=0
VALID warnings=1 OK




AC15-R2-C1 AC15 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC15-R2-C2 AC15 fn=8 fillet
cap folds=0 tube=0 capTri=0 cap=13 coons=0 saddle=2 flat=0 fan=0 weld=4 none=0
VALID warnings=1 OK




AC15-R2-C3 AC15 fn=8 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=2 weld=26 none=0
VALID warnings=0 OK




AC15-R3-C1 AC15 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC15-R3-C2 AC15 fn=19 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=2 weld=11 none=0
VALID warnings=1 OK




AC15-R3-C3 AC15 fn=19 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=2 weld=50 none=0
VALID warnings=0 OK




AC15-R4-C1 AC15 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC15-R4-C2 AC15 fn=32 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=2 none=0
VALID warnings=1 OK




AC15-R4-C3 AC15 fn=32 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=2 none=0
VALID warnings=1 OK




AC15-R5-C1 AC15 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC15-R5-C2 AC15 fn=64 fillet
capTri folds=2 tube=0 capTri=2 cap=0 coons=0 saddle=0 flat=0 fan=6 weld=136 none=0
VALID warnings=0 OK




AC15-R5-C3 AC15 fn=64 chamfer
flat folds=2 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=2 weld=134 none=0
VALID warnings=0 OK




AC16-R1-C1 AC16 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC16-R1-C2 AC16 fn=stock fillet
tube folds=0 tube=1 capTri=10 cap=0 coons=1 saddle=0 flat=0 fan=0 weld=55 none=0
VALID warnings=0 OK




AC16-R1-C3 AC16 fn=stock chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=55 none=0
VALID warnings=0 OK




AC16-R2-C1 AC16 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC16-R2-C2 AC16 fn=8 fillet
tube folds=0 tube=1 capTri=10 cap=0 coons=1 saddle=0 flat=0 fan=0 weld=55 none=0
VALID warnings=0 OK




AC16-R2-C3 AC16 fn=8 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=55 none=0
VALID warnings=0 OK




AC16-R3-C1 AC16 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC16-R3-C2 AC16 fn=19 fillet
tube folds=0 tube=1 capTri=10 cap=0 coons=1 saddle=0 flat=0 fan=0 weld=55 none=0
VALID warnings=0 OK




AC16-R3-C3 AC16 fn=19 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=55 none=0
VALID warnings=0 OK




AC16-R4-C1 AC16 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC16-R4-C2 AC16 fn=32 fillet
tube folds=0 tube=1 capTri=10 cap=0 coons=1 saddle=0 flat=0 fan=0 weld=55 none=0
VALID warnings=0 OK




AC16-R4-C3 AC16 fn=32 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=55 none=0
VALID warnings=0 OK



AC16-R5-C1 AC16 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC16-R5-C2 AC16 fn=64 fillet
tube folds=0 tube=1 capTri=10 cap=0 coons=1 saddle=0 flat=0 fan=0 weld=55 none=0
VALID warnings=0 OK




AC16-R5-C3 AC16 fn=64 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=55 none=0
VALID warnings=0 OK


atomic bench -- AC17: the standing arm is 3 thick against 2R = 4




AC17-R1-C1 AC17 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC17-R1-C2 AC17 fn=stock fillet
capTri folds=0 tube=0 capTri=4 cap=2 coons=0 saddle=2 flat=0 fan=0 weld=18 none=4
VALID warnings=1 OK




AC17-R1-C3 AC17 fn=stock chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=10 weld=20 none=0
VALID warnings=1 OK




AC17-R2-C1 AC17 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC17-R2-C2 AC17 fn=8 fillet
capTri folds=0 tube=0 capTri=4 cap=2 coons=0 saddle=2 flat=0 fan=0 weld=18 none=4
VALID warnings=1 OK




AC17-R2-C3 AC17 fn=8 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=10 weld=20 none=0
VALID warnings=1 OK




AC17-R3-C1 AC17 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC17-R3-C2 AC17 fn=19 fillet
capTri folds=0 tube=0 capTri=4 cap=2 coons=2 saddle=0 flat=0 fan=0 weld=18 none=4
VALID warnings=1 OK




AC17-R3-C3 AC17 fn=19 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=10 weld=20 none=0
VALID warnings=1 OK




AC17-R4-C1 AC17 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC17-R4-C2 AC17 fn=32 fillet
capTri folds=0 tube=0 capTri=4 cap=2 coons=1 saddle=0 flat=1 fan=0 weld=18 none=4
VALID warnings=1 OK




AC17-R4-C3 AC17 fn=32 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=10 weld=20 none=0
VALID warnings=1 OK




AC17-R5-C1 AC17 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC17-R5-C2 AC17 fn=64 fillet
capTri folds=0 tube=0 capTri=4 cap=2 coons=0 saddle=0 flat=2 fan=0 weld=18 none=4
VALID warnings=1 OK




AC17-R5-C3 AC17 fn=64 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=10 weld=20 none=0
VALID warnings=1 OK




AC18-R1-C1 AC18 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC18-R1-C2 AC18 fn=stock fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC18-R1-C3 AC18 fn=stock chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=16 none=0
VALID warnings=0 OK




AC18-R2-C1 AC18 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC18-R2-C2 AC18 fn=8 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC18-R2-C3 AC18 fn=8 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=16 none=0
VALID warnings=0 OK




AC18-R3-C1 AC18 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC18-R3-C2 AC18 fn=19 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC18-R3-C3 AC18 fn=19 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=16 none=0
VALID warnings=0 OK




AC18-R4-C1 AC18 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC18-R4-C2 AC18 fn=32 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC18-R4-C3 AC18 fn=32 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=16 none=0
VALID warnings=0 OK




AC18-R5-C1 AC18 fn=64 original
- folds=0 -
VALID warnings=0 OK



AC18-R5-C2 AC18 fn=64 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC18-R5-C3 AC18 fn=64 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=16 none=0
VALID warnings=0 OK




AC19-R1-C1 AC19 fn=stock original
- folds=0 -
VALID warnings=0 OK



AC19-R1-C2 AC19 fn=stock fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=0 none=10
VALID warnings=1 OK




AC19-R1-C3 AC19 fn=stock chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=12 weld=0 none=0
VALID warnings=1 OK




AC19-R2-C1 AC19 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC19-R2-C2 AC19 fn=8 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=0 none=10
VALID warnings=1 OK




AC19-R2-C3 AC19 fn=8 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=12 weld=0 none=0
VALID warnings=1 OK




AC19-R3-C1 AC19 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC19-R3-C2 AC19 fn=19 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=0 none=10
VALID warnings=1 OK




AC19-R3-C3 AC19 fn=19 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=12 weld=0 none=0
VALID warnings=1 OK




AC19-R4-C1 AC19 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC19-R4-C2 AC19 fn=32 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=0 none=10
VALID warnings=1 OK




AC19-R4-C3 AC19 fn=32 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=12 weld=0 none=0
VALID warnings=1 OK




AC19-R5-C1 AC19 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC19-R5-C2 AC19 fn=64 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=0 none=10
VALID warnings=1 OK




AC19-R5-C3 AC19 fn=64 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=12 weld=0 none=0
VALID warnings=1 OK




AC20-R1-C1 AC20 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC20-R1-C2 AC20 fn=stock fillet
capTri folds=0 tube=0 capTri=14 cap=0 coons=0 saddle=5 flat=1 fan=0 weld=122 none=0 fan folds=0
VALID warnings=0 OK




AC20-R1-C3 AC20 fn=stock chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=20 weld=122 none=0 fan folds=0
VALID warnings=0 OK




AC20-R2-C1 AC20 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC20-R2-C2 AC20 fn=8 fillet
capTri folds=0 tube=0 capTri=14 cap=0 coons=0 saddle=5 flat=1 fan=0 weld=122 none=0 fan folds=0
VALID warnings=0 OK




AC20-R2-C3 AC20 fn=8 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=20 weld=122 none=0 fan folds=0
VALID warnings=0 OK




AC20-R3-C1 AC20 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC20-R3-C2 AC20 fn=19 fillet
capTri folds=0 tube=0 capTri=14 cap=0 coons=0 saddle=5 flat=0 fan=1 weld=122 none=0 fan folds=0
VALID warnings=0 OK




AC20-R3-C3 AC20 fn=19 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=20 weld=122 none=0 fan folds=0
VALID warnings=0 OK




AC20-R4-C1 AC20 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC20-R4-C2 AC20 fn=32 fillet
capTri folds=0 tube=0 capTri=14 cap=0 coons=1 saddle=2 flat=3 fan=0 weld=122 none=0 fan folds=0
VALID warnings=1 OK




AC20-R4-C3 AC20 fn=32 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=20 weld=122 none=0 fan folds=0
VALID warnings=0 OK




AC20-R5-C1 AC20 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC20-R5-C2 AC20 fn=64 fillet
capTri folds=0 tube=0 capTri=14 cap=0 coons=0 saddle=2 flat=4 fan=0 weld=122 none=0 fan folds=0
VALID warnings=1 OK




AC20-R5-C3 AC20 fn=64 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=20 weld=122 none=0 fan folds=0
VALID warnings=0 OK




AC21-R1-C1 AC21 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC21-R1-C2 AC21 fn=stock fillet
capTri folds=0 tube=0 capTri=10 cap=0 coons=0 saddle=1 flat=0 fan=1 weld=14 none=0 fan folds=0
VALID warnings=0 OK




AC21-R1-C3 AC21 fn=stock chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=10 none=0 fan folds=0
VALID warnings=0 OK




AC21-R2-C1 AC21 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC21-R2-C2 AC21 fn=8 fillet
capTri folds=0 tube=0 capTri=10 cap=0 coons=0 saddle=1 flat=0 fan=1 weld=14 none=0 fan folds=0
VALID warnings=0 OK




AC21-R2-C3 AC21 fn=8 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=10 none=0 fan folds=0
VALID warnings=0 OK




AC21-R3-C1 AC21 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC21-R3-C2 AC21 fn=19 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=10 none=0 fan folds=0
VALID warnings=0 OK




AC21-R3-C3 AC21 fn=19 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=10 none=0 fan folds=0
VALID warnings=0 OK




AC21-R4-C1 AC21 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC21-R4-C2 AC21 fn=32 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=10 none=0 fan folds=0
VALID warnings=0 OK




AC21-R4-C3 AC21 fn=32 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=10 none=0 fan folds=0
VALID warnings=0 OK




AC21-R5-C1 AC21 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC21-R5-C2 AC21 fn=64 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=10 none=0 fan folds=0
VALID warnings=0 OK




AC21-R5-C3 AC21 fn=64 chamfer
tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=10 none=0 fan folds=0
VALID warnings=0 OK




AC22-R1-C1 AC22 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC22-R1-C2 AC22 fn=stock fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=40 none=0
VALID warnings=0 OK




AC22-R1-C3 AC22 fn=stock chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=40 none=0
VALID warnings=0 OK




AC22-R2-C1 AC22 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC22-R2-C2 AC22 fn=8 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=40 none=0
VALID warnings=0 OK




AC22-R2-C3 AC22 fn=8 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=40 none=0
VALID warnings=0 OK




AC22-R3-C1 AC22 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC22-R3-C2 AC22 fn=19 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=40 none=0
VALID warnings=0 OK




AC22-R3-C3 AC22 fn=19 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=40 none=0
VALID warnings=0 OK




AC22-R4-C1 AC22 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC22-R4-C2 AC22 fn=32 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=40 none=0
VALID warnings=0 OK




AC22-R4-C3 AC22 fn=32 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=40 none=0
VALID warnings=0 OK




AC22-R5-C1 AC22 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC22-R5-C2 AC22 fn=64 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=40 none=0
VALID warnings=0 OK




AC22-R5-C3 AC22 fn=64 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=40 none=0
VALID warnings=0 OK




AC22b-R1-C1 AC22b fn=stock original
- folds=0 -
VALID warnings=0 OK




AC22b-R1-C2 AC22b fn=stock fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=40 none=0
VALID warnings=0 OK




AC22b-R1-C3 AC22b fn=stock chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=40 none=0
VALID warnings=0 OK




AC22b-R2-C1 AC22b fn=8 original
- folds=0 -
VALID warnings=0 OK




AC22b-R2-C2 AC22b fn=8 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=40 none=0
VALID warnings=0 OK



AC22b-R2-C3 AC22b fn=8 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=40 none=0
VALID warnings=0 OK




AC22b-R3-C1 AC22b fn=19 original
- folds=0 -
VALID warnings=0 OK




AC22b-R3-C2 AC22b fn=19 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=40 none=0
VALID warnings=0 OK




AC22b-R3-C3 AC22b fn=19 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=40 none=0
VALID warnings=0 OK




AC22b-R4-C1 AC22b fn=32 original
- folds=0 -
VALID warnings=0 OK




AC22b-R4-C2 AC22b fn=32 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=40 none=0
VALID warnings=0 OK




AC22b-R4-C3 AC22b fn=32 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=40 none=0
VALID warnings=0 OK



AC22b-R5-C1 AC22b fn=64 original
- folds=0 -
VALID warnings=0 OK




AC22b-R5-C2 AC22b fn=64 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=40 none=0
VALID warnings=0 OK




AC22b-R5-C3 AC22b fn=64 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=40 none=0
VALID warnings=0 OK


atomic bench -- AC23: a rib running out of a cylindrical boss: the arriving crease is an arc




AC23-R1-C1 AC23 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC23-R1-C2 AC23 fn=stock fillet
cap folds=0 tube=0 capTri=0 cap=4 coons=0 saddle=0 flat=2 fan=0 weld=28 none=0
VALID warnings=1 OK




AC23-R1-C3 AC23 fn=stock chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=32 none=0
VALID warnings=1 OK




AC23-R2-C1 AC23 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC23-R2-C2 AC23 fn=8 fillet
cap folds=0 tube=0 capTri=0 cap=8 coons=0 saddle=0 flat=0 fan=7 weld=30 none=0
VALID warnings=0 OK




AC23-R2-C3 AC23 fn=8 chamfer
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=45 none=0
VALID warnings=0 OK




AC23-R3-C1 AC23 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC23-R3-C2 AC23 fn=19 fillet
cap folds=0 tube=0 capTri=0 cap=8 coons=0 saddle=0 flat=0 fan=0 weld=46 none=0
VALID warnings=0 OK




AC23-R3-C3 AC23 fn=19 chamfer
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=54 none=0
VALID warnings=0 OK




AC23-R4-C1 AC23 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC23-R4-C2 AC23 fn=32 fillet
cap folds=0 tube=0 capTri=0 cap=7 coons=0 saddle=0 flat=1 fan=0 weld=84 none=0
VALID warnings=1 OK




AC23-R4-C3 AC23 fn=32 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=32 none=0
VALID warnings=1 OK




AC23-R5-C1 AC23 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC23-R5-C2 AC23 fn=64 fillet
cap folds=0 tube=0 capTri=0 cap=4 coons=0 saddle=0 flat=2 fan=0 weld=84 none=0
VALID warnings=0 OK




AC23-R5-C3 AC23 fn=64 chamfer
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=95 none=0
VALID warnings=0 OK




AC24-R1-C1 AC24 fn=stock original
- folds=0 -
VALID warnings=0 OK




AC24-R1-C2 AC24 fn=stock fillet
tube folds=0 tube=4 capTri=13 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=15 none=0
VALID warnings=0 OK




AC24-R1-C3 AC24 fn=stock chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=13 weld=15 none=0
VALID warnings=0 OK




AC24-R2-C1 AC24 fn=8 original
- folds=0 -
VALID warnings=0 OK




AC24-R2-C2 AC24 fn=8 fillet
tube folds=0 tube=4 capTri=13 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=15 none=0
VALID warnings=0 OK




AC24-R2-C3 AC24 fn=8 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=13 weld=15 none=0
VALID warnings=0 OK




AC24-R3-C1 AC24 fn=19 original
- folds=0 -
VALID warnings=0 OK




AC24-R3-C2 AC24 fn=19 fillet
tube folds=0 tube=3 capTri=13 cap=0 coons=0 saddle=1 flat=0 fan=0 weld=15 none=0
VALID warnings=0 OK




AC24-R3-C3 AC24 fn=19 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=13 weld=15 none=0
VALID warnings=0 OK




AC24-R4-C1 AC24 fn=32 original
- folds=0 -
VALID warnings=0 OK




AC24-R4-C2 AC24 fn=32 fillet
tube folds=0 tube=3 capTri=13 cap=0 coons=0 saddle=1 flat=0 fan=0 weld=15 none=0
VALID warnings=0 OK




AC24-R4-C3 AC24 fn=32 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=13 weld=15 none=0
VALID warnings=0 OK



AC24-R5-C1 AC24 fn=64 original
- folds=0 -
VALID warnings=0 OK




AC24-R5-C2 AC24 fn=64 fillet
tube folds=0 tube=3 capTri=13 cap=0 coons=0 saddle=1 flat=0 fan=0 weld=15 none=0
VALID warnings=0 OK




AC24-R5-C3 AC24 fn=64 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=4 fan=13 weld=15 none=0
VALID warnings=0 OK


atomic bench -- every corner the 'cap' construction actually closed (17 cell(s) measured, 12 shown)




AC08-R3-C2 AC08 fn=19 fillet
tube folds=0 tube=2 capTri=10 cap=2 coons=0 saddle=0 flat=1 fan=1 weld=26 none=0
VALID warnings=1 OK




AC08-R4-C2 AC08 fn=32 fillet
tube folds=0 tube=2 capTri=10 cap=2 coons=0 saddle=0 flat=1 fan=1 weld=26 none=0
VALID warnings=1 OK




AC08-R5-C2 AC08 fn=64 fillet
tube folds=0 tube=2 capTri=10 cap=2 coons=0 saddle=0 flat=1 fan=1 weld=26 none=0
VALID warnings=1 OK




AC10b-R1-C2 AC10b fn=stock fillet
tube=2 capTri=12 cap=1 coons=0 saddle=0 flat=1 fan=1 weld=34 none=0
VALID warnings=1 OK




AC10b-R2-C2 AC10b fn=8 fillet
tube folds=0 tube=2 capTri=12 cap=1 coons=0 saddle=0 flat=1 fan=1 weld=34 none=0
VALID warnings=1 OK




AC14-R2-C2 AC14 fn=8 fillet
tube folds=0 tube=2 capTri=10 cap=1 coons=0 saddle=0 flat=0 fan=1 weld=54 none=0
VALID warnings=0 OK




AC15-R2-C2 AC15 fn=8 fillet
cap folds=0 tube=0 capTri=0 cap=13 coons=0 saddle=2 flat=0 fan=0 weld=4 none=0
VALID warnings=1 OK




AC17-R1-C2 AC17 fn=stock fillet
tube=0 capTri=4 cap=2 coons=0 saddle=2 flat=0 fan=0 weld=18 none=4
VALID warnings=1 OK




AC17-R2-C2 AC17 fn=8 fillet
capTri folds=0 tube=0 capTri=4 cap=2 coons=0 saddle=2 flat=0 fan=0 weld=18 none=4
VALID warnings=1 OK



AC17-R3-C2 AC17 fn=19 fillet
capTri folds=0 tube=0 capTri=4 cap=2 coons=2 saddle=0 flat=0 fan=0 weld=18 none=4
VALID warnings=1 OK




AC17-R4-C2 AC17 fn=32 fillet
capTri folds=0 tube=0 capTri=4 cap=2 coons=1 saddle=0 flat=1 fan=0 weld=18 none=4
VALID warnings=1 OK




AC17-R5-C2 AC17 fn=64 fillet
capTri folds=0 tube=0 capTri=4 cap=2 coons=0 saddle=0 flat=2 fan=0 weld=18 none=4
VALID warnings=1 OK


atomic bench -- every corner the 'capTri' construction actually closed (101 cell(s) measured, 12 shown)




AC03-R1-C2 AC03 fn=stock fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 filat=0 fan=0 weld=12 none=0
VALID warnings=0 OK




AC03-R2-C2 AC03 fn=8 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 filat=0 fan=0 weld=12 none=0
VALID warnings=0 OK




AC03-R3-C2 AC03 fn=19 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 filat=0 fan=0 weld=12 none=0
VALID warnings=0 OK




AC03-R4-C2 AC03 fn=32 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 filat=0 fan=0 weld=12 none=0
VALID warnings=0 OK




AC03-R5-C2 AC03 fn=64 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 filat=0 fan=0 weld=12 none=0
VALID warnings=0 OK




AC04-R1-C2 AC04 fn=stock fillet
capTri folds=0 tube=0 capTri=1 cap=0 coons=0 saddle=0 filat=3 fan=0 weld=3 none=0
VALID warnings=0 OK




AC04-R2-C2 AC04 fn=8 fillet
capTri folds=0 tube=0 capTri=1 cap=0 coons=0 saddle=0 filat=3 fan=0 weld=3 none=0
VALID warnings=0 OK




AC04-R3-C2 AC04 fn=19 fillet
capTri folds=0 tube=0 capTri=1 cap=0 coons=0 saddle=0 filat=3 fan=0 weld=3 none=0
VALID warnings=0 OK




AC04-R4-C2 AC04 fn=32 fillet
capTri folds=0 tube=0 capTri=1 cap=0 coons=0 saddle=0 filat=3 fan=0 weld=3 none=0
VALID warnings=0 OK



AC04-R5-C2 AC04 fn=64 fillet
capTri folds=0 tube=0 capTri=1 cap=0 coons=0 saddle=0 filat=3 fan=0 weld=3 none=0
VALID warnings=0 OK




AC05-R1-C2 AC05 fn=stock fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 filat=0 fan=0 weld=14 none=0
VALID warnings=0 OK




AC05-R2-C2 AC05 fn=8 fillet
capTri folds=0 tube=0 capTri=8 cap=0 coons=0 saddle=0 filat=0 fan=0 weld=14 none=0
VALID warnings=0 OK


atomic bench -- every corner the 'coons' construction actually closed (10 cell(s) measured, 10 shown)




AC10b-R3-C2 AC10b fn=19 fillet
capTri folds=0 tube=0 capTri=12 cap=0 coons=2 saddle=0 flat=0 fan=4 weld=31 none=0
VALID warnings=1 OK




AC12-R3-C2 AC12 fn=19 fillet
capTri folds=0 tube=0 capTri=12 cap=0 coons=2 saddle=0 flat=0 fan=2 weld=0 none=0
VALID warnings=0 OK




AC16-R1-C2 AC16 fn=stock fillet
tube folds=0 tube=1 capTri=10 cap=0 coons=1 saddle=0 flat=0 fan=0 weld=55 none=0
VALID warnings=0 OK




AC16-R2-C2 AC16 fn=8 fillet
tube folds=0 tube=1 capTri=10 cap=0 coons=1 saddle=0 flat=0 fan=0 weld=55 none=0
VALID warnings=0 OK




AC16-R3-C2 AC16 fn=19 fillet
tube folds=0 tube=1 capTri=10 cap=0 coons=1 saddle=0 flat=0 fan=0 weld=55 none=0
VALID warnings=0 OK




AC16-R4-C2 AC16 fn=32 fillet
capTri folds=0 tube=1 capTri=10 cap=0 coons=1 saddle=0 flat=0 fan=0 weld=55 none=0
VALID warnings=0 OK




AC16-R5-C2 AC16 fn=64 fillet
tube folds=0 tube=1 capTri=10 cap=0 coons=1 saddle=0 flat=0 fan=0 weld=55 none=0
VALID warnings=0 OK



AC17-R3-C2 AC17 fn=19 fillet
capTri folds=0 tube=0 capTri=4 cap=2 coons=2 saddle=0 flat=0 fan=0 weld=18 none=4
VALID warnings=1 OK




AC17-R4-C2 AC17 fn=32 fillet
capTri folds=0 tube=0 capTri=4 cap=2 coons=1 saddle=0 flat=1 fan=0 weld=18 none=4
VALID warnings=1 OK




AC20-R4-C2 AC20 fn=32 fillet
capTri folds=0 tube=0 capTri=14 cap=0 coons=1 saddle=2 flat=3 fan=0 weld=122 none=0
VALID warnings=1 OK


atomic bench -- every corner the 'fan' construction actually closed (154 cell(s) measured, 12 shown)




AC01-R1-C3 AC01 fn=stock chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC01-R2-C3 AC01 fn=8 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC01-R3-C3 AC01 fn=19 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC01-R4-C3 AC01 fn=32 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC01-R5-C3 AC01 fn=64 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC02-R1-C3 AC02 fn=stock chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC02-R2-C3 AC02 fn=8 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC02-R3-C3 AC02 fn=19 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC02-R4-C3 AC02 fn=32 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK



AC02-R5-C3 AC02 fn=64 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC03-R1-C3 AC03 fn=stock chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=12 none=0
VALID warnings=0 OK




AC03-R2-C3 AC03 fn=8 chamfer
fan folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=8 weld=12 none=0
VALID warnings=0 OK


atomic bench -- every corner the 'flat' construction actually closed (95 cell(s) measured, 12 shown)




AC01-R1-C2 AC01 tn=stock fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK




AC01-R2-C2 AC01 tn=8 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK




AC01-R3-C2 AC01 tn=19 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK




AC01-R4-C2 AC01 tn=32 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK




AC01-R5-C2 AC01 tn=64 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK




AC04-R1-C2 AC04 tn=stock fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=3 fan=0 weld=3 none=0
VALID warnings=0 OK




AC04-R2-C2 AC04 tn=8 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=3 fan=0 weld=3 none=0
VALID warnings=0 OK




AC04-R3-C2 AC04 tn=19 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=3 fan=0 weld=3 none=0
VALID warnings=0 OK




AC04-R4-C2 AC04 tn=32 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=3 fan=0 weld=3 none=0
VALID warnings=0 OK



AC04-R5-C2 AC04 tn=64 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=3 fan=0 weld=3 none=0
VALID warnings=0 OK




AC06-R1-C3 AC06 tn=stock chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=16 none=0
VALID warnings=0 OK




AC06-R2-C3 AC06 tn=8 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=10 weld=16 none=0
VALID warnings=0 OK


atomic bench -- every corner the 'none' construction actually closed (15 cell(s) measured, 12 shown)




AC02-R1-C2 AC02 In=stock fillet
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=1 none=2
VALID warnings=0 OK




AC02-R2-C2 AC02 In=8 fillet
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=1 none=2
VALID warnings=0 OK




AC02-R3-C2 AC02 In=19 fillet
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=1 none=2
VALID warnings=0 OK




AC02-R4-C2 AC02 In=32 fillet
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=1 none=2
VALID warnings=0 OK




AC02-R5-C2 AC02 In=64 fillet
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=1 none=2
VALID warnings=0 OK




AC17-R1-C2 AC17 In=stock fillet
weld folds=0 tube=0 capTri=4 cap=2 coons=0 saddle=2 flat=0 fan=0 weld=18 none=4
VALID warnings=1 OK




AC17-R2-C2 AC17 In=8 fillet
weld folds=0 tube=0 capTri=4 cap=2 coons=0 saddle=2 flat=0 fan=0 weld=18 none=4
VALID warnings=1 OK




AC17-R3-C2 AC17 In=19 fillet
weld folds=0 tube=0 capTri=4 cap=2 coons=2 saddle=0 flat=0 fan=0 weld=18 none=4
VALID warnings=1 OK




AC17-R4-C2 AC17 In=32 fillet
weld folds=0 tube=0 capTri=4 cap=2 coons=1 saddle=0 flat=1 fan=0 weld=18 none=4
VALID warnings=1 OK



AC17-R5-C2 AC17 In=64 fillet
weld folds=0 tube=0 capTri=4 cap=2 coons=0 saddle=0 flat=2 fan=0 weld=18 none=4
VALID warnings=1 OK




AC19-R1-C2 AC19 In=stock fillet
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=0 none=10
VALID warnings=1 OK




AC19-R2-C2 AC19 In=8 fillet
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=0 none=10
VALID warnings=1 OK


atomic bench -- every corner the 'saddle' construction actually closed (17 cell(s) measured, 12 shown)




AC10b-R5-C2 AC10b fn=64 fillet
capTri folds=0 tube=0 capTri=12 cap=0 coons=0 saddle=1 filat=0 fan=5 weld=31 none=0
VALID warnings=1 OK




AC12-R4-C2 AC12 fn=32 fillet
capTri folds=2 tube=0 capTri=12 cap=0 coons=0 saddle=2 filat=0 fan=2 weld=0 none=0
VALID warnings=0 OK




AC12-R5-C2 AC12 fn=64 fillet
capTri folds=2 tube=0 capTri=12 cap=0 coons=0 saddle=2 filat=0 fan=2 weld=0 none=0
VALID warnings=0 OK




AC14-R1-C2 AC14 fn=stock fillet
capTri folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=2 filat=2 fan=2 weld=44 none=0
VALID warnings=1 OK




AC15-R2-C2 AC15 fn=8 fillet
cap folds=0 tube=0 capTri=0 cap=13 coons=0 saddle=2 filat=0 fan=0 weld=4 none=0
VALID warnings=1 OK




AC17-R1-C2 AC17 fn=stock fillet
capTri folds=0 tube=0 capTri=4 cap=2 coons=0 saddle=2 filat=0 fan=0 weld=18 none=4
VALID warnings=1 OK




AC17-R2-C2 AC17 fn=8 fillet
capTri folds=0 tube=0 capTri=4 cap=2 coons=0 saddle=2 filat=0 fan=0 weld=18 none=4
VALID warnings=1 OK




AC20-R1-C2 AC20 fn=stock fillet
capTri folds=0 tube=0 capTri=14 cap=0 coons=0 saddle=5 filat=1 fan=0 weld=122 none=0
VALID warnings=0 OK




AC20-R2-C2 AC20 fn=8 fillet
capTri folds=0 tube=0 capTri=14 cap=0 coons=0 saddle=5 filat=1 fan=0 weld=122 none=0
VALID warnings=0 OK



AC20-R3-C2 AC20 fn=19 fillet
capTri folds=0 tube=0 capTri=14 cap=0 coons=0 saddle=5 filat=0 fan=1 weld=122 none=0
VALID warnings=0 OK




AC20-R4-C2 AC20 fn=32 fillet
capTri folds=0 tube=0 capTri=14 cap=2 coons=1 saddle=2 filat=3 fan=0 weld=122 none=0
VALID warnings=1 OK




AC20-R5-C2 AC20 fn=64 fillet
capTri folds=0 tube=0 capTri=14 cap=0 coons=0 saddle=2 filat=4 fan=0 weld=122 none=0
VALID warnings=1 OK


atomic bench -- every corner the 'tube' construction actually closed (55 cell(s) measured, 12 shown)




AC06-R1-C2 AC06 fn=stock fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC06-R2-C2 AC06 fn=8 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC06-R3-C2 AC06 fn=19 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC06-R4-C2 AC06 fn=32 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC06-R5-C2 AC06 fn=64 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=16 none=0
VALID warnings=0 OK




AC07-R1-C2 AC07 fn=stock fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC07-R2-C2 AC07 fn=8 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC07-R3-C2 AC07 fn=19 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC07-R4-C2 AC07 fn=32 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK



AC07-R5-C2 AC07 fn=64 fillet
tube folds=0 tube=2 capTri=10 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=26 none=0
VALID warnings=0 OK




AC08-R3-C2 AC08 fn=19 fillet
tube folds=0 tube=2 capTri=10 cap=2 coons=0 saddle=0 flat=1 fan=1 weld=26 none=0
VALID warnings=1 OK




AC08-R4-C2 AC08 fn=32 fillet
tube folds=0 tube=2 capTri=10 cap=2 coons=0 saddle=0 flat=1 fan=1 weld=26 none=0
VALID warnings=1 OK


atomic bench -- every corner the 'weld' construction actually closed (240 cell(s) measured, 12 shown)




AC01-R1-C2 AC01 fn=stock fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK




AC01-R1-C3 AC01 fn=stock chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC01-R2-C2 AC01 fn=8 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK




AC01-R2-C3 AC01 fn=8 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC01-R3-C2 AC01 fn=19 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK




AC01-R3-C3 AC01 fn=19 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC01-R4-C2 AC01 fn=32 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK




AC01-R4-C3 AC01 fn=32 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK




AC01-R5-C2 AC01 fn=64 fillet
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=2 fan=0 weld=1 none=0
VALID warnings=0 OK



AC01-R5-C3 AC01 fn=64 chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK



AC02-R1-C2 AC02 fn=stock fillet
weld folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=0 weld=1 none=2
VALID warnings=0 OK



AC02-R1-C3 AC02 fn=stock chamfer
flat folds=0 tube=0 capTri=0 cap=0 coons=0 saddle=0 flat=0 fan=2 weld=1 none=0
VALID warnings=0 OK