Project Template for submission of Project by State Government to IDF-OI

8	Project Title	Conversion of the Incodes	
ļ 		Conversion of Dry Insanitary Latrines into Sanitary Toilets as well as for construction of bio toilets for remaining families at GP Sarmathura, Block Basedi of District DHOLPUR	
b	Aim of the Project	To attain ODF status at GP Sarmathura Disti :DHOLPUR, RAJASTHAN	
C	Short Justification for the project-	GP Sarmathura is the only place in the State where Dry latrines still exist which is against the provision of "Prohibition of employment as Manual scavengers and their rehabilitation Act 2013"	
ď.	Whether Existing or new Project -	New Project To support SBM & to attain ODF status in State as a whole	
€	Sector-	Sanitation	
f	Implementing Agency and NGO associated-	GP Sarmathura.	
g	Target beneficiaries- number and nature(eg women, children, tribal etc)-	3372 HH to be covered	
h	Target Geographic location(village, district etc)-	GP Sarmathura, Block Basedi of District DHOLPUR	
	Design of Project (methodology, intervention etc)-	Construction of Sanitary Toilets using recent technology as Bio Digesters.	
	Expected outcomes/ benefits proposed-	To attain ODF status at GP Sarmathura Distt: DHOLPUR RAJASTHAN	
	Project Timeline (Date of commencement and completion) -	To be completed within three months after commencement.	
	Estimated budget-	Rs .10.116 Crores for construction of 3372 sanitary toilets	
n	Whether the cost includes capital cost as well as maintenance cost-	Capital Cost	
	Images of proposed project (if any)-	Images of existing dry latrines are depicted in the detail project report enclosed.	

Note: The cost of construction of one toilet shall be Rs.0.30 lacs

PROJECT FOR

CATERIA CE DE LA SARTARE LA SARTARE LA TRUES DE LA SARTARES DE LA

AT

G.P: SARMATHURA

P.S. : BASEDI

DISTRICT: DHOLPUR


PROFILE

- 1. GP SARIMATHURA is part of Block BASEDI of District DHOULPUR in RAJASTHAN.
- 2. AS PER LATEST SURVEY THERE ARE REMAINING 247 HH WITH INSANITARY TOILETS DRY LATRINES WHICH ARE TO BE CONVERTED IN TO SANITARY TOILETS.


TOTAL	NO OF	NO OF HOUSEHOLDS	
HOUSEHO		•	TOTAL No OF
	HOUSEHOLD	HAVING INSANITARY	HOUSEHOLDS TO
LDS BLS-	S HAVING	TOILETS (DRY	
2012	NO TOILET	/ Large & s	BE PROVIDED
		LATRINES)	SANITARY TOILETS
1	2	3	
		5	4 (2+3)
3674	3125	Co Com	
		247	3372

<u>LSSUES</u>


- 1. PRESENCE OF ROCKY STRATA AS SHOWN IN PROTOGRAPH, CONVENSIONAL TWO LEACH PITS TOILETS MAY NOT BE FUCTIONAL BECAUSE OF FOLLOWING REASONS:
 - a) Difficult to excavate
 - b) Poor soaking capacity of sub base
- 2. AS IT IS EVEDIENT FROM THE PHOTOGRAPH, DISPOSAL OF EFFLUENT FROM SEFTIC TANK LEFT UNATTENDED MAY LEAD TO UNHYGENIC CONDITION.



INSIDE VIEW OF DRY LATRINE




OUTSIDE VIEW OF DRY LATRINE




ANOTHER TYPE OF DRY LATRINE




INSIDE VIEW OF DRY LATRINE




OUTSIDE VIEW OF DRY LATRINE



OUTSIDE VIEW OF DRY LATRINE



EFFLUENT FROM SEPTIC TANK LEFT UNATTENDED



EXCAVATIONS SHOWING TYPE OF STRATA

PEOPOSALS AND RECOMMENDATIONS

Based upon the problems and issues related with rocky strata and unhygienic conditions because of unattended effluent from septic tank, it will be better to treat the effluent before disposal.

New techniques are available like bio digester, may be adopted.

The effluent from these bio digesters are safe for open discharge and are environment friendly.