SERVICE NOTE SN-2291

Site: Nordhafen solar park, inverter row C
Technician: Jonas Feldmann

Inverter SI-60 number C-14 showed fault G44 after heavy rain. Insulation resistance measured 0.8 MOhm on string 3. The connector was replaced and the inverter was returned to service at 14:20.

Follow-up: re-measure string 3 in two weeks.