

OpeX Industries — Equipment Inspection Report

Equipment: Boiler Feed Pump BFP-12

Inspection date: 14 March 2026

Inspector: R. Sharma, Senior Reliability Engineer

Report reference: INSP-2026-0341

Findings

1. Outboard bearing housing temperature measured at 78 degrees Celsius, above the 70 degree Celsius alert threshold. Recommend thermographic follow-up within 30 days.
2. Mechanical seal weep rate measured at 3 drops per minute, within the acceptable range of under 5 drops per minute for this seal type.
3. Coupling alignment checked with laser alignment tool: angular misalignment 0.04 mm, parallel offset 0.06 mm, both within the 0.08 mm tolerance for this coupling class.
4. Baseplate grout shows a hairline crack approximately 40 mm long near the discharge-side anchor bolt. Not yet affecting alignment; recommend re-inspection at the next scheduled outage.

Overall condition rating: Fair — monitor bearing temperature trend.