



P/N: 11618-06517

CUSTOMER NAME		W.O. #	
Captive Socket Head Cap Screw		ORDER #	
Date Issued 2/09/15		Job #	
Part # 4823-M07-F09		David	
Material STAINLESS STEEL		Promised Date 0/00/00	
Diameter 0.303 - 0.312		Amount to Make	
		Finish NO FINISH	

Plunge Grind .130 Tolerance + / - .005



Base # 73418

Finish # 11618-06517

This Print is good.

Please Quote 50K PCS.

Can you confirm whether this method is similar to the factory's testing procedure? If so, the screws we currently have on hand are not achieving the factory's stated result of 135 in-lbs.

To answer your questions:

- **Fastenal has used this old print for these parts for the 8 years or so. Do you have anything more I could share?** The print you shared does not appear to be a UEA print that I recognize.
- **Do you have video of the testing?** No, if necessary, we can create one.
- **What equipment/gaging are you using?** Calibrated in-lb. torque wrench
- **What is the required torque for the application?**

These screws are used to secure panel access to an enclosure with clinching PEM nuts. Only minimal torque is required to seat the panel and foam gasket. We have not established a specific torque specification, as the screws should easily handle installation without failure. However, the current screws are snapping at the head before the panel is fully seated. This has now forced us to change our process and use hand tools to slowly secure them to prevent them from breaking.

We have used this same part in this application for years without issue, and no process changes have been made.

Please let me know if there is any additional information I can provide.

Thanks,



Mike Mangine *Assistant Quality Manager*
Direct: 319-596-7985 Main: 319-352-3946
2103 E Bremer Ave. Waverly, IA 50677
United Equipment Accessories, Inc. | www.uea-inc.com

From: IAWAV <iawav@stores.fastenal.com>

Sent: Tuesday, April 28, 2026 3:05 PM

To: Mike Mangine <MIKEM@uea-inc.com>

Cc: Jennifer Briggs-Moen <jbriggs-moen@uea-inc.com>; Angi Kueker <akueker@uea-inc.com>; Troy Weidler <tweidler@uea-inc.com>

Subject: Re: P5121032050PSS (11618-06517) 10-32X0.50",SOC.HD SS CAPTIVE

CAUTION: This email originated from outside your organization. Exercise caution when opening attachments or clicking links, especially from unknown senders.

Mike,

Would it be possible to get on a call with the manufacturer to discuss this? In the meantime, can you answer these questions from them?

Do you have video of the testing?

Can you tell us what equipment/gaging you're using?

What is the required torque for the application?

Fastenal has used this old print for these parts for the 8 years or so. Do you have anything more I could share?

Thanks,

Chelsey Wedeking

Fastenal Company | 700 Technology Pl. Waverly, IA 50677

Office: 319-352-4312

Fax: 319-352-5629

Email: iawav@stores.fastenal.com

Website: www.fastenal.com



From: Mike Magine <MIKEM@uea-inc.com>

Sent: Tuesday, April 28, 2026 11:57 AM

To: IAWAV <iawav@stores.fastenal.com>

Cc: Jennifer Briggs-Moen <jbriggs-moen@uea-inc.com>; Angi Kueker <akueker@uea-inc.com>; Troy Weidler <tweidler@uea-inc.com>

Subject: Re: P5121032050PSS (11618-06517) 10-32X0.50",SOC.HD SS CAPTIVE


CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Chelsey,

We just performed a quick test of the fasteners from two different boxes and could not come even close to the manufacturers stated value of "135 in-lbs. of torque and the screw was twisting below the head". I'm not sure what method was used to get this. We just quick double jam nut them at the base of the threads. Then used a torque wrench and found that the older box from PO# P300095231 twisted and brock at 55 in-lbs. The newer box cleanly just snapped at 80 in-lbs. See the images below. This was performed with a calibrated tool.

Was their measurement from the head of the fastener being seated to a surface (tightened down) or a fixed thread position as we performed?





Thanks,



Mike Mangine Assistant Quality Manager

Direct: 319-596-7985 Main: 319-352-3946

2103 E Bremer Ave. Waverly, IA 50677

United Equipment Accessories, Inc. | www.uea-inc.com

From: IAWAV <iawav@stores.fastenal.com>

Sent: Tuesday, April 28, 2026 11:20 AM

To: Angi Kueker <akueker@uea-inc.com>; Mike Mangine <MIKEM@uea-inc.com>; Troy Weidler <tweidler@uea-inc.com>

giridhar Addagudi

From: IAWAV <iawav@stores.fastenal.com>
Sent: 06 May 2026 09:21
To: PK-Prahasith Karimilla; giridhar Addagudi
Subject: Fw: P5121032050PSS (11618-06517) 10-32X0.50",SOC.HD SS CAPTIVE
Attachments: image002 (1).png

Below is the response I got.

Chelsey Wedeking
Fastenal Company | 700 Technology Pl. Waverly, IA 50677
Office: 319-352-4312
Fax: 319-352-5629
Email: iawav@stores.fastenal.com
Website: www.fastenal.com

Mark Hearnsh
MARTIN
04/11/2026



From: Mike Mangine <MIKEM@uea-inc.com>
Sent: Wednesday, May 6, 2026 8:48 AM
To: IAWAV <iawav@stores.fastenal.com>
Cc: Jennifer Briggs-Moen <jbriggs-moen@uea-inc.com>; Angi Kueker <akueker@uea-inc.com>; Nathan Leonard <nleonard@uea-inc.com>
Subject: Re: P5121032050PSS (11618-06517) 10-32X0.50",SOC.HD SS CAPTIVE

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Hello Chelsey,

I apologize for the delayed response; my schedule has been extremely full. Unfortunately, we do not have a video of the testing—only the data provided below.

For our testing method, we applied two jam nuts at the base of the threads and locked them together. The screw was then secured in a vise at the jam nuts. Using a calibrated in-lb. torque wrench, we applied torque in 5 in-lb. increments until failure. Images of each test were previously provided.

- PO# P300095231 failed at 55 in-lbs (twisted and broke)
- PO# P300097118 failed at 80 in-lbs (clean snap)