

From: Ms. Melissa Goh (HCSA) melissa.goh@HCSA.com
To: Catherine Lee (HCSA) <catherine.lee@HCSA.com>
Cc: Priya Sharma (HCSA) <priya.sharma@HCSA.com>
Date: Friday, 18 April 2025 11:15 AM
Subject: RE: Escalation - Level 2 dangerous occurrence Tower B

Catherine,

Thank you for the escalation. My directions:

1. Formal contract review is not to be initiated until the RCA investigation is complete and root cause of the clip failure is established. Contractor termination based on an incident potentially attributable to a manufacturing defect would be premature.
2. The contractor is to remain under enhanced supervision. All rope access work remains suspended until the equipment audit is completed and cleared.
3. The investigation must be completed within 10 business days. If root cause is contractor negligence (improper inspection, incorrect use), formal contract review proceeds immediately. If root cause is manufacturing defect, contractor score adjustment will be limited and we will consider proportionate action.
4. Legal and Procurement to be looped in given potential equipment liability. Catherine — please arrange this.

Please proceed accordingly and keep me informed.

Melissa Goh

Director (Health, Safety, and Environment (HSE)), HSE Department | HCSA

From: Catherine Lee (HCSA) <catherine.lee@HCSA.com>
To: Ms. Melissa Goh (HCSA) <melissa.goh@HCSA.com>
Cc: Priya Sharma (HCSA) <priya.sharma@HCSA.com>
Date: Friday, 18 April 2025 9:00 AM
Subject: Escalation - Level 2 dangerous occurrence Tower B + contractor status

Melissa,

Escalating for your awareness and direction on two matters arising from yesterday's incident.

1. Level 2 Dangerous Occurrence: A secondary lifeline clip failure at ~Floor 13 level was confirmed as Level 2. IR-62 has been submitted. Statutory notification is being prepared (14-day window). All rope access work is suspended pending investigation and equipment audit.
2. Contractor Status: Bintang Facade Solutions holds a CSA-72 score of 74 — within the enhanced supervision band. Based on the figures from the contractor records, their score will likely fall below 70 following adjustment, triggering formal contract review.

However, there is a complicating factor: the contractor's team is mid-project, the failed clip was recently certified, and investigation is ongoing. If the failure is attributed to a manufacturing defect rather than contractor negligence, there is an argument for a policy exception to avoid contract termination while investigation is pending.

I am seeking your direction on whether to initiate formal contract review now or hold pending investigation outcome.

Catherine Lee

HSE Senior Officer, HSE Department | HCSA

From: Jennifer Koh (HCSA) <jennifer.koh@HCSA.com>
To: Catherine Lee (HCSA) <catherine.lee@HCSA.com>
Cc: Priya Sharma (HCSA) <priya.sharma@HCSA.com>
Date: Thursday, 17 April 2025 6:15 PM
Subject: RE: Near-miss report - contractor performance records

Catherine,

Pulled the contractor records for Bintang Facade Solutions:

CSA-72 score (January 2025): 74/100 — within the 70–79 enhanced supervision band

Safety performance history (past 3 years): 1 minor injury, 0 dangerous occurrences prior to today

Training records: valid, all rope access workers hold WAH certification

Equipment inspection: last certified March 2025

The clip failure is notable because the equipment certification was recent. This suggests either a latent manufacturing defect or improper use — the investigation will need to determine which.

The contractor is currently in the enhanced supervision band. Today's incident, if confirmed as Level 2, will significantly impact their next quarterly score.

Jennifer Koh

HSE Senior Officer, HSE Department | HCSA

From: Catherine Lee (HCSA) <catherine.lee@HCSA.com>
To: Priya Sharma (HCSA) <priya.sharma@HCSA.com>
Cc: Jennifer Koh (HCSA) <jennifer.koh@HCSA.com>
Date: Thursday, 17 April 2025 5:30 PM
Subject: RE: Near-miss report - Tower B - classification confirmed

Priya,

Agreed. The energy level and potential consequence clearly meet the Level 2 threshold as a dangerous occurrence with potential for fatality. Reclassification to Level 2 is confirmed.

Immediate actions required:

1. Verbal notification to Regional HSE Director within the hour
2. Written IR-62 within 4 hours
3. All rope access work across all sites suspended pending equipment audit
4. Contractor to immediately audit all lifeline clips of the same model

Given this involves contractor equipment failure on a freshly approved permit, I am also flagging this for a contractor performance review. Jennifer — please pull the contractor's CSA-72 score and performance record.

Catherine Lee

HSE Senior Officer, HSE Department | HCSA

From: Priya Sharma (HCSA) <priya.sharma@HCSA.com>
To: Catherine Lee (HCSA) <catherine.lee@HCSA.com>
Cc: Jennifer Koh (HCSA) <jennifer.koh@HCSA.com>
Date: Thursday, 17 April 2025 5:00 PM
Subject: RE: Near-miss report - Tower B - borderline classification

Catherine,

Please see the near-miss report from David below. Initial classification is Level 5 (near-miss, no injury). However, I believe this warrants escalation to Level 2 consideration based on the energy level and potential consequence assessment per POL-CO-003 Section 5.2.

Rationale:

- Height: approximately 13 floors (~39m above ground)
- Failure type: secondary lifeline clip — if primary also failed, outcome would be fatal
- Energy level: extremely high gravitational energy
- POL-CO-003 Section 5.2: near-miss with potential for Level 1-2 outcome must trigger HSE Manager review within 1 hour

I am recommending reclassification to Level 2 (dangerous occurrence with potential for fatality). Please confirm.

Priya Sharma

HSE Senior Officer, HSE Department | HCSA

From: David Wong (HCSA) <david.wong@HCSA.com>
To: Priya Sharma (HCSA) <priya.sharma@HCSA.com>
Cc: Jennifer Koh (HCSA) <jennifer.koh@HCSA.com>
Date: Thursday, 17 April 2025 4:10 PM
Subject: Near-miss report - Tower B rope access crew

Priya, Jennifer,

Reporting a near-miss incident at Tower B today at approximately 2:45 PM. One of the rope access workers (Bintang Facade Solutions crew) experienced a secondary lifeline clip failure while descending at approximately Floor 13 level. The primary lifeline held. No fall occurred, no injury.

The failed clip was the same model specified in the rescue plan submitted with the permit. Worker was shaken but uninjured. I have flagged the site supervisor and suspended rope access work pending review. The failed clip has been preserved.

Initial classification: Level 5 near-miss. However, given the height (>13 floors) and potential consequence of a secondary system failure, this may warrant review for reclassification.

Please advise.

David Wong

HSE Officer, HSE Department | HCSA

From: Jennifer Koh (HCSA) <jennifer.koh@HCSA.com>
To: Linh Nguyen <linhnguyen.infra@hotmail.com>
Cc: Aaron Ng (HCSA) <aaron.ng@HCSA.com>
Date: Tuesday, 15 April 2025 2:30 PM
Subject: RE: WAH permit - APPROVED for 16 April

Dear Linh,

We are pleased to confirm that your Working at Height permit (PTW-WAH-84) for rope access façade work at Tower B has been approved for commencement on Wednesday, 16 April 2025.

Please note the following conditions:

1. Permit is valid for daily use only — reissuance required each day before work commences.
2. Work must cease immediately if wind speed exceeds 40 km/h.
3. As a condition of approval, please arrange for a calibrated anemometer on site within 5 working days (by 23 April 2025).
4. Permit displayed at the work base; copy held with the Safety Officer at all times.

Please ensure your team is briefed on all permit conditions before commencing work.

Jennifer Koh

HSE Senior Officer, HSE Department | HCSA

From: Linh Nguyen <linhnguyen.infra@hotmail.com>
To: Jennifer Koh (HCSA) <jennifer.koh@HCSA.com>
Date: Tuesday, 15 April 2025 9:15 AM
Subject: RE: WAH permit - resubmission with updated docs

Hi Jennifer,

We updated everything. Attaching:

- Anchor cert (roof anchor points A1-A4, certified March 2025)
- Rescue plan (3-person ground team, hospital within 8km)
- Wind protocol: work stops at 40kmh, site foreman checks weather app every 2 hrs
- Updated RA-55 with rope access section added

We really need to start Wed. Team already in transit.

Linh

Project Coordinator, Bintang Facade Solutions

From: Jennifer Koh (HCSA) <jennifer.koh@HCSA.com>
To: Linh Nguyen <linhnguyen.infra@hotmail.com>
Date: Monday, 14 April 2025 1:00 PM
Subject: RE: WAH permit - suspended access work this week

Dear Linh,

Thank you for submitting your Working at Height permit request. We have reviewed the submission (Document PTW-WAH-84) and identified several items that must be completed before approval:

1. Fall protection system — please provide anchor point certification and confirmation of secondary lifeline provision.
2. Rescue plan — currently marked TBC. A completed rescue plan is mandatory before approval.
3. Weather monitoring — please confirm your wind speed monitoring protocol. Work must cease if wind exceeds 40 km/h.
4. Risk assessment (RA-55) — does not address rope access-specific hazards at heights above 10 floors. Please revise.

Please resubmit with these items addressed. Note that the Wednesday start date may need to be pushed back depending on when the revised submission is received.

Jennifer Koh

HSE Senior Officer, HSE Department | HCSA

From: Linh Nguyen <linhnguyen.infra@hotmail.com>
To: Jennifer Koh (HCSA) <jennifer.koh@HCSA.com>
Date: Monday, 14 April 2025 8:45 AM
Subject: WAH permit - suspended access work this week

Hi Jennifer,

We are doing facade inspection and waterproofing repair on Tower B from this Wednesday (16 Apr 2025). The work is at 12–15 floors using rope access from the roof. We submit PTW 2 days ago (Saturday 12 Apr 2025) online.

Can you confirm it will be ready for Wednesday? The team is flying in from KL.

Linh Nguyen

Project Coordinator, Bintang Facade Solutions

linhnguyen.infra@hotmail.com