

Boiler B-102 Annual Shutdown Inspection Report

Equipment Tag: B-102 (Package Boiler)

Inspected by: Priya Sharma, Inspection Engineer

Inspection Date: 2026-03-10

Standard Reference: PESO / Indian Boiler Regulations (IBR)

Related Work Order: WO-2041

1. SCOPE

Annual internal and external shutdown inspection covering shell, tubes, safety valves, and refractory.

2. FINDINGS

- Minor surface corrosion observed on external shell (non-critical).
- Tube wall thickness measured within acceptable limits (min 4.2mm).
- Safety relief valve tested and set-pressure verified at 10.5 bar.
- Refractory lining in good condition, no spalling observed.
- No evidence of tube leakage or scaling beyond normal limits.

3. RECOMMENDATIONS

- Repaint external shell surface within 3 months.
- Continue current water treatment program.
- Re-inspect per statutory schedule in 12 months (2027-03-10).

4. SIGN-OFF

Inspector: Priya Sharma Date: 2026-03-10

Approved by: Rajesh Kumar, Maintenance Engineer