

SAFETY DATA SHEET HUNTEX TV-001



Substance classified as hazardous and hazardous pictograms



Corrosive -Harmful



Prevention and practices



- Avoid release to the environment.
- Do not eat, drink or smoke when working. Wash hands before and after work.
- Use appropriate protective equipment when working with chemicals.
- Do not inhale gases/ vapours/ aerosols. Avoid contact with eyes and skin.
- Wash contaminated clothing and other protective equipment before storage or re-use.

Measures to handle in case of emergency

On fire:

- 1. Fire fighting with water water spray, foam, dry powder, CO₂.
- 2. In the event of fire the following can be released: Carbon monoxide (CO), Carbon dioxide (CO₂).
- 3. Fire fighter should wear self-contained breathing apparatus and suitable protective clothing if risk of exposure to vapor or product of combustion.

Leak or break:

- 1. Avoid contacting, touching, or walking over spilled material.
- 2. Take up and fill into a closable container.
- 3. Prevent run off into drains and waterways.
- 4. Take up liquid spill into absorbent material, eg: soil, sand and other non-flammable absorbent material.


First aid measures



Inhalation: Remove the victim from exposure or move to well- ventilated area.

Skin contact: Wash with plenty of soap and water. Remove contaminated clothing,

shoes and leather accessories.



if present and easy to do. Continue rinsing.

Ingestion: Rinse mouth with water, drink plenty of water.

If feel unwell, seek medical advice.





Storage

Keep container tightly closed and store in a cool, temperature 15-25°c, dry well- ventilated location.

Store away from heat, flames, ignition sources and incompatibles.

Avoid contact with alkalis, oxidizing agents. Check regularly for leaks..

Waste treatment

Waste from residue: Disposal should be in accordance with local regulations and legislation. Contaminated packaging: Dispose of empty contaminated containers in accordance with regulations and legislation.

