THE MARITIME SAFETY COMMITTEE, RECALLING Article 28(b) of the Convention on the International Maritime Organization concerning the functions of the Committee, RECALLING ALSO that the Assembly, at its seventeenth session, when adopting resolution A.686(17) on the Code on alarms and indicators, authorized the Committee to amend or extend the Code as may be necessary, RECOGNIZING the need for extension of the above Code to cover the Code for the Construction and Equipment of Mobile Offshore Drilling Units, 1989 (1989 MODU Code) and the Code of Safety for Diving Systems, with aview to ensuring their uniform application, HAVING CONSIDERED at its sixty-third session the text of proposed amendments to the Code on alarms and indicators, developed by the Sub-Committee on Ship Design and Equipment, 1. ADOPTS amendments to the Code on alarms and indicators, the text of which is set out in the Annex to the present resolution; - amendments to the Code on alarms and indicators, developed by the Sub-Committee on Ship Design and Equipment, 1. ADOPTS amendments to the Code on alarms and indicators, the text of which is set out in the Annex to the present resolution; 2. RECOMMENDS Governments to take appropriate steps to give effect to the said amendments. W/1649n/EWP RESOLUTION MSC.39(63) (adopted on 19 May 1994) ADOPTION OF AMENDMENTS TO THE CODE ON ALARMS AND INDICATORS MSC 63/23/Add.1 ANNEX 23 Page 2 ANNEX AMENDMENTS TO THE CODE ON ALARMS AND INDICATORS TO COVER THE 1989 MODU CODE AND THE CODE OF SAFETY FOR DIVING SYSTEMS 1 Add anew paragraph 5.6 to section 5 of the Code: ' .. "5.6 On MODUs, where supplemental visual alarms are installed for general emergency alarms, the colour of these supplemental alarms may be amber, provided they flash with apulse frequency of at least 4 Hz." 2 In paragraph 9.1, replace "9.1.8" by "9.1.9". 3 In the box containing notes below paragraph 9.2, replace "9.1.8" by "9.1.9". 4 Add the following to Table 9.1.1 - Location: navigating bridge Priority S S P P P P P P IHO Instrument 1989 MODU Code 7.4.1 7.4.2.5 8.5.5 7.4.2.7 7.4.2.8 - "9.1.9". 4 Add the following to Table 9.1.1 - Location: navigating bridge Priority S S P P P P P P IHO Instrument 1989 MODU Code 7.4.1 7.4.2.5 8.5.5 7.4.2.7 7.4.2.8 7.4.2.9 7.5.1.17 7.6.1 7.6.3 Fund ion Propeller pitch indicator Propulsion station in control indication Propulsion machinery remote control failure Propell er speed/ direction/pitch Low starting air pressure Rudder angle indicator Steering gear running Steering gear phase failure/overload alarm * Cross reference to SOLAS regulation W/1649n/EWP Type I I A,V HI A,V A,V I A,V Notes Column 2, table 8.1 Columns 1&3, table 8.2 II-l/31.2.S'" II-l/49.3'" Column 1, table 8.2 II-l/31.2.7* Column 1, table ~.2 II-l/31.2.8* Columns 1&3 table 8.2 II-l/31.2.9* Column 1, table 8.1 II-1129.11* Columns 1 & !3, table 8.1 II-l/30.1* Column 1, table 8.3 II-l/30.3* RESOLUTION MSC.39(63) (adopted on 19 May 1994) ADOPTION OF AMENDMENTS TO TH