<EXAMPLE>
<If the maintenance
and service time,
specified by the
manufacturer, is
exceeded, the risk of
biofouling is elevated,
and contingency
actions should be
implemented.>
<EXAMPLE>
<An inspection
should be carried out
for the relevant niche
area where MGPS is
installed.
Maintenance,
calibration, or
adjustment of

---CHUNK---

SOURCE: MEPC.378%2880%29.pdf
actions should be
implemented.>
<EXAMPLE>
<An inspection
should be carried out
for the relevant niche
area where MGPS is
installed.
Maintenance,
calibration, or
adjustment of
treatment dosages
for a MGPS should
be performed at
earliest possible
opportunity.>
<EXAMPLE>
<Regular
maintenance and
service (e.g.) may be
necessary actions
for proper protection
by the AFS.
Evaluate the need to
update maintenance
programme>

I:\MEPC\80\MEPC 80-17-Add.1.docx
Biofouling risk
parameters to
monitor
Evaluation of a
deviation including
deviation limit of the
risk parameter
Contingency
actions
Long-term actions
<EXAMPLE>
<Downtime/malfunction
of MGPS>
<EXAMPLE>
<Observed downtime
of an MGPS could
have a direct impact
on risk of biofouling

---CHUNK---

SOURCE: MEPC.378%2880%29.pdf
risk parameter
Contingency
actions
Long-term actions
<EXAMPLE>
<Downtime/malfunction
of MGPS>
<EXAMPLE>
<Observed downtime
of an MGPS could
have a direct impact
on risk of biofouling
accumulation.
The impact will
depend on the
duration of
malfunction and
operating areas
(coastal area).>
<EXAMPLE>
<More frequent
inspections of
relevant area should
be implemented until
the MGPS is back in
operation.>

<EXAMPLE>
<Downtime/malfunction
of other AFS>

<EXAMPLE>
<Reduced operation
time of other AFS
may increase
biofouling
accumulation in areas
where it is usually
applied.>
<EXAMPLE>
<More frequent
inspections of
relevant area should
be implemented until
the AFS is back in
operation.>

<EXAMPLE>
<Exceeding expected
lifetime of AFS>
<EXAMPLE>
<Once an AFS has
exceeded its lifetime,
as specified by the
manufacturer, the
biofouling risk is
increased.>
<EXAMPLE>
<More frequent
inspections should
be implemented until
the AFS is back in

---CHUNK---

SOURCE: MEPC.378%2880%29.pdf
exceeded its lifetime,
as specified by the
manufacturer, the
biofouling risk is
increased.>
<EXAMPLE>
<More frequent
inspections should
be implemented until
the AFS is back in
operation.>
<EXAMPLE>
<The performance of
the AFS, and any
necessary change in
maintenance or
inspection schedule,
based on
experience, should

be included in the next update of this BWMP.>
<EXAMPLE>
<Deviation from regular proactive cleaning>
<EXAMPLE>
<When proactive cleaning is implemented as part of the AFS, deviation from regular use could lead to increased risk of biofouling growth onto relevant submerged areas.>
<EXAMPLE>
<An inspection should be carried out. If there is macrofouling (fouling rating 2) in the