6.1.6 After between 60 and 72 hours, a message should automatically be erased from the memory storage. If the number of received messages exceeds the capacity of the storage, the
---
SOURCE: MSC.569(109).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.569(109).pdf
memory storage. If the number of received messages exceeds the capacity of the storage, the oldest message should be erased.
6.1.7 Only messages satisfactorily received (i.e. BER is better than 10-4) should be stored.
6.2 Programmable control memories
6.2.1 Information identifying the transmitter service area and the code of each subject message in programmable memory should not be erased by interruptions in the power supply of less than 24 hours.
6.2.2 The NAVDAT receiver equipment should be able to display, delete and query stored messages, and be able to output messages manually or automatically to appropriate ship equipment (e.g. ECDIS).
7 ALERT
7.1 Upon receipt of new search and rescue related information messages with distress or urgency priority, the NAVDAT receiver equipment should give an alert, including information for decision-making.
7.2 The position information contained in the messages with distress and urgency
---
SOURCE: MSC.569(109).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.569(109).pdf
for decision-making.
7.2 The position information contained in the messages with distress and urgency priorities should be automatically transmitted to other navigation equipment (e.g. ECDIS, ENC plotter).
7.3 The NAVDAT receiver equipment should comply with the Performance standards for bridge alert management (resolution MSC.302(87)).
8 TEST FACILITIES
The NAVDAT receiver equipment should be provided with a facility to test the radio receiver, the display and the non-volatile memory and to display the results of the test.
9 DATA INTERFACES
9.1 The NAVDAT receiver equipment should include at least one interface for the transfer of all messages to other navigation or communication equipment.
9.2 All interfaces provided for communication with other navigation or communication equipment should comply with the relevant international standards.5
9.3 The NAVDAT receiver equipment may include a standard printer interface.
10 POWER SUPPLY

SOURCE: MSC.569(109).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.569(109).pdf
9.3 The NAVDAT receiver equipment may include a standard printer interface.
10 POWER SUPPLY
10.1 The NAVDAT receiver equipment should normally be powered from the ship's main or emergency sources of electrical energy. In addition, it should be possible to operate the equipment and all equipment necessary for its normal functioning from the reserve so urce or sources of energy in accordance with SOLAS regulation IV/13.

5 Refer to IEC 61162.
RESOLUTION MSC.569(109) (adopted on 6 December 2024)
PERFORMANCE STANDARDS FOR THE RECEPTION OF MARITIME SAFETY
INFORMATION AND SEARCH AND RESCUE RELATED INFORMATION
BY MF AND HF DIGITAL NAVIGATIONAL
DATA (NAVDAT) SYSTEM
MSC 109/22/Add.1
Annex 12, page 7
I:\MSC\109\22\MSC 109-22-Add.1.docx
10.2 The NAVDAT receiver equipment should continue to operate without any loss of software parameters or received messages stored in the memory in the presence of power supply variations normally to be expected in a ship.

SOURCE: MSC.569(109).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.569(109).pdf
software parameters or received messages stored in the memory in the presence of power supply variations normally to be expected in a ship.
11 RECEIVER IDENTIFICATION
It should be possible to configure the NAVDAT receiver equipment with:
.1 the identity (MMSI) of the ship (according to Recommendation ITU-R M.585); or
.2 the group identity (MMSI) (according to Recommendation ITU-R M.585); or
.3 additional lists of identities (MMSIs).
12 STORED TABLES
The NAVDAT receiver equipment should have the possibility of memorizing some tables. For example:
.1 The list of coast stations with:
Area;
Country;
Longitude;
Latitude;
Name;
Slots; and
Frequency used.
This stored table is queried when the identities of a NAVDAT coast station are received and the complete parameters of this NAVDAT coast station should be displayed in plain text.
.2 The list of subject messages:
Table with subject message 01 to 63 (see the most recent versions of
---
SOURCE: MSC.569(109).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.569(109).pdf
should be displayed in plain text.
.2 The list of subject messages:
Table with subject message 01 to 63 (see the most recent versions of
Recommendations ITU-R M.2010 and ITU-R M.2058).
***
RESOLUTION MSC.569(109) (adopted on 6 December 2024)
PERFORMANCE STANDARDS FOR THE RECEPTION OF MARITIME SAFETY
INFORMATION AND SEARCH AND RESCUE RELATED INFORMATION
BY MF AND HF DIGITAL NAVIGATIONAL

DATA (NAVDAT) SYSTEM
RESOLUTION MSC.569(109) (adopted on 6 December 2024)
PERFORMANCE STANDARDS FOR THE RECEPTION OF MARITIME SAFETY
INFORMATION AND SEARCH AND RESCUE RELATED INFORMATION
BY MF AND HF DIGITAL NAVIGATIONAL
DATA (NAVDAT) SYSTEM

SOURCE: MSC.573(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.573(110).pdf
RESOLUTION MSC.573(110) (adopted on 26 June 2025)
AMENDMENTS TO THE INTERNATIONAL CODE OF SAFETY
FOR HIGH-SPEED CRAFT, 1994 (1994 HSC CODE)
RESOLUTION MSC.573(110)
(adopted on 26 June 2025)
AMENDMENTS TO THE INTERNATIONAL CODE OF SAFETY
FOR HIGH-SPEED CRAFT, 1994 (1994 HSC CODE)
THE MARITIME SAFETY COMMITTEE,
RECALLING Article 28(b) of the Convention on the International Maritime Organization concerning the functions of the Committee,
NOTING resolution MSC.36(63), by which it adopted the International Code of Safety for High-Speed Craft ("the 1994 HSC Code"), which has become mandatory under chapter X of the International Convention for the Safety of Life at Sea, 1974 ("the Convention"),
NOTING ALSO article VIII(b) and regulation X/1.1 of the Convention concerning the procedure for amending the 1994 HSC Code,
HAVING CONSIDERED, at its 110th session, amendments to the 1994 HSC Code proposed and circulated in accordance with article VIII(b)(i) of the Convention,
---
SOURCE: MSC.573(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.573(110).pdf
and circulated in accordance with article VIII(b)(i) of the Convention,
1 ADOPTS, in accordance with article VIII(b)(iv) of the Convention, amendments to the 1994 HSC Code, the text of which is set out in the annex to the present resolution;
2 DETERMINES, in accordance with article VIII(b)(vi)(2)(bb) of the Convention, that the said amendments shall be deemed to have been accepted on 1 July 2027, unless, prior to that date, more than one third of the Contracting Governments to the Convention or Contracting Governments the combined merchant fleets of which constitute not less than 50% of the gross tonnage of the world's merchant fleet have notified the Secretary -General of their objections to the amendments;
3 INVITES Contracting Governments to the Convention to note that, in accordance with article VIII(b)(vii)(2) of the Convention, the amendments shall enter into force on 1 January 2028 upon their acceptance in accordance with paragraph 2 above;

SOURCE: MSC.573(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.573(110).pdf
on 1 January 2028 upon their acceptance in accordance with paragraph 2 above;
4 REQUESTS the Secretary -General, for the purposes of article VIII(b)(v) of the Convention, to transmit certified copies of the present resolution and the text of the

amendments contained in the annex to all Contracting Governments to the Convention;
5 ALSO REQUESTS the Secretary-General to transmit copies of this resolution and its annex to Members of the Organization which are not Contracting Governments to the Convention.
RESOLUTION MSC.573(110) (adopted on 26 June 2025)
AMENDMENTS TO THE INTERNATIONAL CODE OF SAFETY FOR HIGH-SPEED CRAFT, 1994 (1994 HSC CODE)
- 2 -
ANNEX
AMENDMENTS TO THE INTERNATIONAL CODE OF SAFETY FOR HIGH-SPEED CRAFT, 1994 (1994 HSC CODE)
CHAPTER 8
LIFE-SAVING APPLIANCES AND ARRANGEMENTS
8.3 Personal life-saving appliances
1 Paragraph 8.3.5 is replaced by the following:
"8.3.5 A lifejacket complying with the requirements of regulation III/32.1 or
---
SOURCE: MSC.573(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.573(110).pdf
1 Paragraph 8.3.5 is replaced by the following:
"8.3.5 A lifejacket complying with the requirements of regulation III/32.1 or
III/32.2 of the Convention should be provided for every person on board the craft and, in addition:
.1 a number of lifejackets suitable for children equal to at least 10% of the number of passengers on board should be provided or such greater number as may be required to provide a lifejacket for each child;
.2 every passenger craft should carry lifejackets for not less than 5% of the total number of persons on board. These lifejackets should be stowed in conspicuous places on deck or at muster stations;
.3 a sufficient number of lifejackets should be carried for persons on watch and for use at remotely located survival craft and rescue boat stations;
.4 all lifejackets should be fitted with a light, which complies with the requirements of regulation III/32.3 of the Convention; and
---
SOURCE: MSC.573(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.573(110).pdf
.4 all lifejackets should be fitted with a light, which complies with the