2 At the end of paragraph 9, the following new paragraph 9.1 is inserted:

“9.1 In instances where the previous flag St ate has not forwarded, within three months from the date of change of flag, the CSR file of the ship covering the period during which the ship was entitled to fly its flag, to the ne w flag State, then the new flag State should issue to the ship a CSR based on the CSR in formation received from onboard the ship. The sequential number to be allocated to the CSR document to be so issued should be the second sequential number after the last sequentially number shown on the CSR document found (i.e. leaving first sequential number unused). The new flag State should explain, in

---CHUNK---

SOURCE: MSC.198%2880%29.pdf
second sequential number after the last sequentially number shown on the CSR document found (i.e. leaving first sequential number unused). The new flag State should explain, in entry box 14, the reason for issuing the CSR document in such a manner.”

Possibility of inconsistencies

3 At the end of paragraph 13, the fo llowing new paragraph 13.1 is inserted:

“13.1 When inspecting the CSR file of ship s that have changed flag, those exercising control under SOLAS regulation I/19 or co ntrol and compliance measures under SOLAS regulation XI-2/9, should be guide d by the provisions of sections 8, 9 and 9.1, as well as the Remarks shown in entry box 14 of the CSR document. In the circumstances referred to in section 9.1 the missing sequential number should be c onsidered as constituting a deficiency against the previous flag State. Such a deficiency is due to the fact that the previous flag State did not fo rward the CSR file and thus failed to fulfil its obligations

---CHUNK---

SOURCE: MSC.198%2880%29.pdf
deficiency against the previous flag State. Such a deficiency is due to the fact that the previous flag State did not fo rward the CSR file and thus failed to fulfil its obligations under SOLAS regulation XI-1/5.”

4 The following new section is inserted after paragraph 13.1:

“The use of the “Remarks” entry box

14 The “Remarks” entry box should only be used by the flag State when encountering difficulties w ith the implementation of the provisions of SOLAS regulation XI-1/5 or of resolution A.959(23) as amended, such as in the case of bareboat registration and change of flag.”

RESOLUTION MSC.198(80)
(adopted on 20 May 2005)
ADOPTION OF AMENDMENTS TO THE FORMAT AND
GUIDELINES FOR THE MAINTENANCE OF THE CONTINUOUS
SYNOPSIS RECORD (CSR)MSC 80/24/Add.1
ANNEX 8
Page 4

I:\MSC\80\24-Add-1.doc

APPENDIX

FORM 1

5 At the end of the form the following new entry box is inserted:

14 Remarks (insert relevant information as
appropriate)

FORM 2

---CHUNK---

SOURCE: MSC.198%2880%29.pdf
I:\MSC\80\24-Add-1.doc
APPENDIX

FORM 1

5 At the end of the form the following new entry box is inserted:

14 Remarks (insert relevant information as
appropriate)

FORM 2

6 At the end of the form the following new entry box is inserted:

14 Remarks (insert relevant information as
appropriate)

RESOLUTION MSC.198(80)
(adopted on 20 May 2005)
ADOPTION OF AMENDMENTS TO THE FORMAT AND
GUIDELINES FOR THE MAINTENANCE OF THE CONTINUOUS
SYNOPSIS RECORD (CSR)MSC 80/24/Add.1
ANNEX 8
Page 5

I:\MSC\80\24-Add-1.doc
ANNEX 2

AMENDMENTS TO THE FORMAT AND GUIDELINES FOR THE MAINTENANCE

OF THE CONTINUOUS SYNOPSIS RECORD (CSR) (RESOLUTION A.959(23))

APPENDIX

FORM 1

1 After the existing entry box number 6 the following new entry box is inserted:

7 Registered owner identification number

2 The existing entry boxes numbers 7 and 8 are renumbered as 8 and 9.

---CHUNK---

SOURCE: MSC.198%2880%29.pdf
7 Registered owner identification number

2 The existing entry boxes numbers 7 and 8 are renumbered as 8 and 9.

3 After the existing box number 8, which is be ing renumbered as 9, the following new entry box is inserted:

10 Company identification number

4 The existing entry boxes numbers 9 to 14 are renumbered as 11 to 16.

FORM 2

5 After the existing entry box number 6 the following new entry box is inserted:

7 Registered owner identification number

6 The existing entry boxes numbers 7 and 8 are renumbered as 8 and 9.

7 After the existing box number 8, which is be ing renumbered as 9, the following new entry box is inserted:

10 Company identification number

8 The existing entry boxes numbers 9 to 14 are renumbered as 11 to 16.

***
RESOLUTION MSC.198(80)
(adopted on 20 May 2005)
ADOPTION OF AMENDMENTS TO THE FORMAT AND
GUIDELINES FOR THE MAINTENANCE OF THE CONTINUOUS
SYNOPSIS RECORD (CSR)RESOLUTION MSC.198(80)

---CHUNK---

SOURCE: MSC.198%2880%29.pdf
***
RESOLUTION MSC.198(80)
(adopted on 20 May 2005)
ADOPTION OF AMENDMENTS TO THE FORMAT AND
GUIDELINES FOR THE MAINTENANCE OF THE CONTINUOUS
SYNOPSIS RECORD (CSR)RESOLUTION MSC.198(80)
(adopted on 20 May 2005)
ADOPTION OF AMENDMENTS TO THE FORMAT AND
GUIDELINES FOR THE MAINTENANCE OF THE CONTINUOUS
SYNOPSIS RECORD (CSR)

---CHUNK---

SOURCE: MSC.68%2868%29.pdf
RESOLUTION MSC.68(68)
(adopted on 6 June 1997)
ADOPTION OF AMENDMENTS TO PERFORMANCE STANDARDS
FOR SHIPBORNE RADIOCOMMUNICATION EQUIPMENT)
ANNEX 10
RESOLUTION MSC.68(68)
(adopted on 6 June 1997)
MSC 68/23/ Add. 1