recommended performance standards of such equipment.
On crafts engaged on voyages in sea areas Al and A2, the availability should be ensured by using such methods as duplication of equipment, shore-based maintenance or at-sea electronic maintenance capability, or a combinat5 .on of these, as may be approved by the Administration.
On crafts engaged on voyages in sea areas A3 and A4, the availability should be ensured by using a combination of at least two methods such as duplication of equipment, shore-based maintenance or at-sea electronic maintenance capability, as may

---CHUNK---

SOURCE: MSC.36(63).pdf
On crafts engaged on voyages in sea areas A3 and A4, the availability should be ensured by using a combination of at least two methods such as duplication of equipment, shore-based maintenance or at-sea electronic maintenance capability, as may be approved by the Administration, taking into account the I'ecommendations of the Organization"""".
However, crafts operating solely between ports where adequate facilities for shore-based maintenance of the radio installations are available and provided no journey between two such ports exceeds six hours, then the Administration may exempt such crafts from the requirement to use at least two maintenance methods. For such crafts at least one maintenance method should be used.
* Refer to the Recommendation on general requirements for shipborne radio equipment forming part of the global maritime distress and safety system and for electronic navigational aids , adopted by the Organization by resolution A.694(11).
** Administrations should take account of the Recommendations on radio maintenance guidelines for the Global Maritime Distress and Safety System

---CHUNK---

SOURCE: MSC.36(63).pdf
and for electronic navigational aids , adopted by the Organization by resolution A.694(11).
** Administrations should take account of the Recommendations on radio maintenance guidelines for the Global Maritime Distress and Safety System (GMDSS) related to sea areas A3 and A4 , a.dopted by the Organization by resolution A.102(11)
W/1681n/pp/EWP
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY
FOR HIGH SPEED CRAFT 14.14.9
14.15
14.16
MSC 62/23/Add.2
ANNEX 18
Page 145
While all reasonable steps should be taken to maintain the equipment in efficient working order to ensure compliance with all the

functional requirements specified in 14.4, malfunction of the equipment for providing the general radiocommunications, required by 14.4.8, should not be considered as making a craft unseaworthy or as a reason for delaying the craft in ports where repair facilities are not readily available, provided the craft is capable of performing all distress and safety functions.
Radio pers~
Every craft should carry personnel qualified for distress and safety radiocommunication purposes to the satisfaction of the

---CHUNK---

SOURCE: MSC.36(63).pdf
not readily available, provided the craft is capable of performing all distress and safety functions.
Radio pers~
Every craft should carry personnel qualified for distress and safety radiocommunication purposes to the satisfaction of the
Administration. The personnel should be holders of certificates specified in the Radio Regulations as appropriate, anyone of whom should be designated to have primary responsibility for radiocommunications during distress incidents.
Radio records
A record should be kept, to the satisfaction of the Administration and as required by the Radio Regulations, of all incidents connected with the radiocommunication service which appear to be of importance to safety of life at sea.
W/l687n/pp/EWP
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY
FOR HIGH SPEED CRAFT MSC 62/23/Add.2
ANNEX 18
Page 146
15.1
15.1.1
15.1. 2
15.1. 3
15.1. 4
15.2
15.3
15.3.1
15.3.2
15.3.3
15.3.4
CHAPTER 15 - OPERATING COMPARTMENT LAYOUT
Definitions
"Operating area" is the operating compartment and those parts of the craft on both sides of, and close to, the operating compartment

---CHUNK---

SOURCE: MSC.36(63).pdf
15.1. 4

15.2
15.3
15.3.1
15.3.2
15.3.3
15.3.4

CHAPTER 15 - OPERATING COMPARTMENT LAYOUT

Definitions

"Operating area" is the operating compartment and those parts of the craft on both sides of, and close to, the operating compartment which extend to the craft's side.

"Workstation" is a position at which one or several tasks constituting a particular activity are carried out.

"Docking workstation" is a place equipped with necessary means for docking the craft.

"Primary controls" are all control equipment necessary for the safe operation of the craft when it is underway, including those required in an emergency situation.

General

The design and layout of the compartment from which the crew operate the craft should be such as to permit operating crew members to perform their duties in a correct manner without unreasonable difficulty, fatigue or concentration, and to minimize the likelihood of injury to operating crew members in both normal and emergency conditions.

Field of vision from the operating compartment

The operating station should be placed above all other superstructures so that the operating crew are able to gain a view

---CHUNK---

SOURCE: MSC.36(63).pdf

conditions.

Field of vision from the operating compartment

The operating station should be placed above all other superstructures so that the operating crew are able to gain a view all round the horizon from the navigating workstation. Where it is impractical to meet the requirements of this paragraph from a single navigating workstation, the operating station should be designed so that an all-round view of the horizon is obtained using two navigating workstations combined or any other means to the satisfaction of the Administration.

Blind sectors should be as few and as small as possible, and not adversely affect the keeping of a safe lookout from the operating station. If stiffners between windm-rs are to be covered, this should not cause further obstruction inside the wheelhouse.

The total arc of blind sectors from right ahead to 22.5° abaft the beam on either side should not exceed 20°. Each individual blind sector should not exceed 5°. The clear sector between two blind sectors should not be less than 10°.

Where it is considered necessary by the Administration, the field of vision from the navigating workstation should permit the navigators

---CHUNK---

SOURCE: MSC.36(63).pdf
sector should not exceed 5°. The clear sector between two blind sectors should not be less than 10°.
Where it is considered necessary by the Administration, the field of vision from the navigating workstation should permit the navigators from this position to utilize leading marks astern of the craft for track monitoring.
W/l687n/pp/EWP
(
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY FOR HIGH SPEED CRAFT 15.3.5
15.3.6
15.4
15.4.1
15.4.2
15.4.3
15.4.4
15.4.5
15.4.6
15.4.1