---CHUNK---

SOURCE: MSC.38(63).pdf
l~~~' ----------RD PROrli.E: VI~iO
Figure 13-4 - Helideck obstacle limitation sector
180 0 for moderate climate
to
e
RESOLUTION MSC.38(63)
(adopted on 19 May 1994)
ADOPTION OF AMENDMENTS TO THE CODE FOR THE CONSTRUCTION AND EQUIPMENT
OF MOBILE OFFSHORE DRILLING UNITS, 1989 MSC 63/23/Add.l
ANNEX 20
Page 22
1'"-·';
1
I
I
1.00,1
---_ .. - - _ .. ---
:\
0.30
"
. ~,jt
" .. . ~ "
white perimeter marking
.... ---0'-'--
NCYl'E: The Chevron marking shown
is applicable to adverse climates.
For moderate climates this should
be repla.ced by a straight bar.
-..;-.
---- ----
1.00 ~ \
; \ \ tlarJc
I \"" ....,
~ Take-off and approach
; area markipg
I ..-.... \()
I \ O·
.r . _. ~' __ ...;
60 em
_____ white perimeter marking
Figure 13-5 _ Obstacle-free sector marking

)0
RESOLUTION MSC.38(63)
(adopted on 19 May 1994)
ADOPTION OF AMENDMENTS TO THE CODE FOR THE CONSTRUCTION AND EQUIPMENT
OF MOBILE OFFSHORE DRILLING UNITS, 1989 RESOLUTION MSC.38(63)
(adopted on 19 May 1994)
ADOPTION OF AMENDMENTS TO THE CODE FOR THE CONSTRUCTION AND EQUIPMENT
OF MOBILE OFFSHORE DRILLING UNITS, 1989

---CHUNK---

SOURCE: MSC.39(63).pdf
RESOLUTION MSC.39(63)
(adopted on 19 May 1994)
ADOPTION OF AMENDMENTS TO THE CODE ON
ALARMS AND INDICATORS ANNEX 23
RESOLUTION MSC.39(63)
(adopted on 19 May 1994)
MSC 63/23/Add.1
ADOPTION OF AMENDMENTS TO THE CODE ON ALARMS AND INDICATORS
THE MARITIME SAFETY COMMITTEE,
RECALLING Article 28(b) of the Convention on the International Maritime Organization concerning the functions of the Committee,
RECALLING ALSO that the Assembly, at its seventeenth session, when adopting resolution A.686(17) on the Code on alarms and indicators, authorized the Committee to amend or extend the Code as may be necessary,
RECOGNIZING the need for extension of the above Code to cover the Code for the Construction and Equipment of Mobile Offshore Drilling Units, 1989 (1989 MODU Code) and the Code of Safety for Diving Systems, with a view to ensuring their uniform application,
HAVING CONSIDERED at its sixty-third session the text of proposed amendments to the Code on alarms and indicators, developed by the Sub-Committee on Ship Design and Equipment,
1. ADOPTS amendments to the Code on alarms and indicators, the text of which is set out in the Annex to the present resolution;

---CHUNK---

SOURCE: MSC.39(63).pdf
amendments to the Code on alarms and indicators, developed by the Sub-Committee on Ship Design and Equipment,
1. ADOPTS amendments to the Code on alarms and indicators, the text of which is set out in the Annex to the present resolution;
2. RECOMMENDS Governments to take appropriate steps to give effect to the said amendments.
W/1649n/EWP
RESOLUTION MSC.39(63)
(adopted on 19 May 1994)
ADOPTION OF AMENDMENTS TO THE CODE ON
ALARMS AND INDICATORS MSC 63/23/Add.1
ANNEX 23
Page 2
ANNEX
AMENDMENTS TO THE CODE ON ALARMS AND INDICATORS
TO COVER THE 1989 MODU CODE AND THE CODE
OF SAFETY FOR DIVING SYSTEMS
1 Add a new paragraph 5.6 to section 5 of the Code:
' ..
"5.6 On MODUs, where supplemental visual alarms are installed for general emergency alarms, the colour of these supplemental alarms may be amber, provided they flash with a pulse frequency of at least 4 Hz."
2 In paragraph 9.1, replace "9.1.8" by "9.1.9".

3 In the box containing notes below paragraph 9.2, replace "9.1.8" by "9.1.9".

4 Add the following to Table 9.1.1 - Location: navigating bridge

Priority	IHO Instrument	1989 MODU Code
S		7.4.1
S		7.4.2.5
P		8.5.5
P		7.4.2.7
P		7.4.2.8
P		
P		
P		

---CHUNK---

SOURCE: MSC.39(63).pdf

"9.1.9".

4 Add the following to Table 9.1.1 - Location: navigating bridge

Priority	IHO Instrument	1989 MODU Code
S		7.4.1
S		7.4.2.5
P		8.5.5
P		7.4.2.7
P		7.4.2.8
P		7.4.2.9
P		7.5.1.17
P		7.6.1
		7.6.3
Fund ion		
Propeller pitch indicator		
Propulsion station in control indication		
Propulsion machinery		

remote control failure
Propell er speed/
direction/pitch
Low starting air
pressure
Rudder angle indicator
Steering gear running
Steering gear phase
failure/overload alarm
* Cross reference to SOLAS regulation
W/1649n/EWP
Type
I
I
A,V
HI
A,V
A,V
I
A,V
Notes
Column 2, table 8.1
Columns 1&3, table 8.2