---CHUNK---

SOURCE: MSC.197(80).pdf
Annex6A
Annex 6B
Annex 7
Annex 8
Annex 9
Annex 10
Annex II
Annex 12
Requirements for close-up survey at renewal surveys
Requirements for thickness measurements at renewal surveys
Requirements for tank pressure testing at renewal surveys
Requirements for extent of thickness measurements at areas of substantial corrosIOn
Owner's inspection report
Survey programme
Survey planning questionnaire
Procedures for certification of a company engaged 10 thickness measurement of hull structures
Survey reporting principles
Condition evaluation report
Recommended procedures for thickness measurements
Guidelines for technical assessment in conjunction with the planning of enhanced surveys for oil tankers
Criteria for longitudinal strength of hull girder for oil tankers"
2 Throughout the Guidelines:
.1 the words "enhanced survey during the periodical survey", "periodical survey" and "enhanced survey" are replaced with the words "renewal survey";
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)-9-

---CHUNK---

SOURCE: MSC.197(80).pdf
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)-9-
.2 the words "enhanced survey during annual survey" are replaced with the words "annual survey";
.3 the words "intermediate enhanced survey" are replaced with the words "intermediate survey"; and
.4 the words "is to be" and "are to be" are replaced with the words "should be".
ANNEXA
GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
3 A new paragraph 1.1.1 is added as follows:
" 1.1.1 The Guidelines should apply to all self-propelled bulk carners of 500 gross

tonnage and above."
Existing paragraphs 1.1.1 and 1.1.2 are renumbered as paragraphs 1.1.2 and 1.1.3.
4 In new paragraph 1.1.2 (existing paragraph 1.1.1), in the second sentence, the words "regulation 1110 of' are inserted between "by" and "the 1974 SOLAS Convention".
5 In paragraph 1.2.14, the words "Intermediate enhanced survey is an enhanced survey" are replaced by "Intermediate survey is a survey".

---CHUNK---

SOURCE: MSC.197(80).pdf
"regulation 1110 of' are inserted between "by" and "the 1974 SOLAS Convention".
5 In paragraph 1.2.14, the words "Intermediate enhanced survey is an enhanced survey" are replaced by "Intermediate survey is a survey".
6 In existing paragraph 1.2.15, the words "condition of classification" are replaced by "condition of classification or recommendation".
7 A new paragraph 1.2.17 is added as follows:
"1.2.17 Specially considered means sufficient close-up inspection and thickness measurements are taken to confirm the actual average condition of the structure under coating."
8 The word "significant" in paragraph 1.3.2 is deleted.
9 The following new paragraph 1.4 is added:
"1.4 Surveyors
For bulk carriers of 20,000 tons deadweight and above, two surveyors should jointly carry out the first scheduled renewal survey after the bulk carrier passes 10 years of age, and all subsequent renewal surveys and intermediate surveys. If the surveys are carried out by a recognized organization, the surveyors should be exclusively employed by such recognized organizations."
10 The words "thickness measurement and" in paragraph 2.1.2 are deleted.
II Paragraph 2.2.4 is deleted.

---CHUNK---

SOURCE: MSC.197(80).pdf
recognized organization, the surveyors should be exclusively employed by such recognized organizations."
10 The words "thickness measurement and" in paragraph 2.1.2 are deleted.
II Paragraph 2.2.4 is deleted.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 10 -
12 The references to a footnote regarding "specially considered" in paragraphs 2.3.1, 2.6.4, 3.4.1.1 and 3.4.2.1 are deleted.
13 In paragraph 3.1, the word "annual" is inserted before the word "survey".
14 Existing paragraphs 3.3.2, 3.3.4,3.3.5 and 3.3.6 are deleted.
15 The following new paragraphs 3.3.2 to 3.3.7 are added after existing paragraph 3.3.1:
"3.3.2 A thorough survey of cargo hatch covers and coamings is only possible by examination in the open as well as closed positions and should include verification of proper opening and closing operation. As a result, the hatch cover sets within the forward 25% of the ship's length and at least one additional set, such that all sets on the ship are

---CHUNK---

SOURCE: MSC.197(80).pdf
proper opening and closing operation. As a result, the hatch cover sets within the forward 25% of the ship's length and at least one additional set, such that all sets on the ship are assessed at least once in every 5-year period, should be surveyed open, closed and in operation to the full extent in each direction at each annual survey, including:
.1 stowage and securing in open condition;
.2 proper fit and efficiency of sealing in closed condition; and
.3 operational testing of hydraulic and power components, wires, chains and link drives.
The closing of the covers should include the fastening of all peripheral, and cross joint cleats or other securing devices. Particular attention should be paid to the condition of hatch covers in the forward 25% of the ship's length, where sea loads are normally greatest.
3.3.3 If there are indications of difficulty in operating and securing hatch covers, additional sets above those required by 3.3.2, at the discretion of the surveyor, should be tested in operation.
3.3.4 Where the cargo hatch securing system does not function properly, repairs should

---CHUNK---

SOURCE: MSC.197(80).pdf
additional sets above those required by 3.3.2, at the discretion of the surveyor, should be tested in operation.
3.3.4 Where the cargo hatch securing system does not function properly, repairs should be carried out under the supervision of the Administration. Where hatch covers or coamings undergo substantial repairs, the strength of securing devices should be upgraded to comply with annex 13.
3.3.5 For each cargo hatch cover set, at each annual survey, the following items should be surveyed:
.1 cover panels, including side plates, and stiffener attachments that may be accessible in the open position by close-up survey (for corrosion, cracks, deformation);
.2 sealing arrangements of perimeter and cross joints (gaskets for condition and permanent deformation, flexible seals on combination carriers, gasket lips, compression bars, drainage channels and non return valves);
.3 clamping devices, retaining bars, cleating (for wastage, adjustment, and condition of rubber components);
.4 closed cover locating devices (for distortion and attachment);
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED

---CHUNK---

SOURCE: MSC.197(80).pdf
condition of rubber components);
.4 closed cover locating devices (for distortion and attachment);
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 11 -
.5 chain or rope pulleys;
.6 guides;

.7 guide rails and track wheels;
.8 stoppers;
.9 wires, chains, tensioners and gypsies;
.10 hydraulic system, electrical safety devices and interlocks; and
. I I end and interpanel hinges, pins and stools where fitted.
3.3.6 At each hatchway, at each annual survey, the coamings, with plating, stiffeners and brackets should be checked for corrosion, cracks and deformation, especially of the coaming tops.
3.3.7 Where considered necessary, the effectiveness of sealing arrangements may be proved by hose or chalk testing supplemented by dimensional measurements of seal compressing components."
16 Existing paragraph 3.3.3 is renumbered as 3.3.8.
I 7 Existing paragraph 5 .1. I is replaced by the following:
"5.1.1 A specific survey programme should be worked out in advance of the renewal

---CHUNK---

SOURCE: MSC.197(80).pdf
compressing components."
16 Existing paragraph 3.3.3 is renumbered as 3.3.8.
I 7 Existing paragraph 5 .1. I is replaced by the following:
"5.1.1 A specific survey programme should be worked out in advance of the renewal survey by the owner in co-operation with the Administration. The survey programme