Ship side in way of cargo
holds
Plating
Side frames webs
Side frames flanges
Upper brackets webs
Upper brackets flanges
Lower brackets webs
Lower brackets flanges
Longitndinal bulkhead if
applicable
Plating
Longitudinals, if applicable
Longitudinal girders,
if applicable
Transverse bulkheads
Plating
Stiffeners, if applicable
Upper stool plating
Upper stool stiffeners
Lower stool plating
Lower stool stiffeners
Transverse web frames in
topside tanks
Plating
Flanges
Stiffeners
Transverse web frames in
hopper tanks
Plating
Flanges
Stiffeners
Hatch covers
Plating
Stiffeners
Hatch coamings
Plating
Stiffeners
Note: The wastage allowance tables should be attached to the survey programme.
11 Thickness measurement company
This section of the survey programme should identify changes, if any, relating to the information on the thickness measurement company provided in the Survey Planning Questionnaire.
12 Damage experience related to the ship
This section of the survey programme should, using the tables provided below, provide

---CHUNK---

information on the thickness measurement company provided in the Survey Planning

Questionnaire.
12 Damage experience related to the ship
This section of the survey programme should, using the tables provided below, provide details of the hull damages for at least the last three years in way of the cargo holds, ballast tanks and void spaces within the cargo length area. These damages are subject to survey.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)Cargo hold, tank or space number or area
Cargo hold, tank or space number or area

Hull damages sorted by location for this ship
Possible cause, Description Location Repair if known of the damages
Hull damages for sister or similar ships (if available)
in the case of design related damage
Possible cause, Description Location Repair if known of the damages
13 Areas identified with substantial corrosion from previous surveys
Date of repair
Date of repair
This section of the survey programme should identifY and list the areas of substantial

---CHUNK---

SOURCE: MSC.197(80).pdf
if known of the damages
13 Areas identified with substantial corrosion from previous surveys
Date of repair
Date of repair
This section of the survey programme should identifY and list the areas of substantial corrosion from previous surveys.
14 Critical structural areas and suspect areas
This section of the survey programme should identify and list the critical structural areas and the suspect areas, when such information is available.
15 Other relevant comments and information
This section of the survey programme should provide any other comments and information relevant to the survey.

(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 20-
Appendices
Appendix 1 - List of plans
Paragraph 5.1.3.2 requires that main structural plans of cargo holds and ballast tanks (scantling drawings), including information on regarding use of high tensile steel (HTS) should be available. This Appendix of the survey programme should identify and list the main structural plans which form part of the survey programme .

---CHUNK---

SOURCE: MSC.197(80).pdf
(scantling drawings), including information on regarding use of high tensile steel (HTS) should be available. This Appendix of the survey programme should identify and list the main structural plans which form part of the survey programme .
Appendix 2 - Survey Planning Questionnaire
The Survey Planning Questionnaire (annex 4B), which has been submitted by the owner, should be appended to the survey programme .
Appendix 3 - Other documentation
This part of the survey programme should identify and list any other documentation that forms part of the plan.
Prepared by the owner in co-operation with the Administration for compliance with 5.1.3:
Date: ....
Date: ....
(name and signature of authorized owner's representative)
(name and signature of authorized r epresentative of the Administration)"
37 The following new Annex 4B is added after Annex 4A:
"ANNEX4B
SURVEY PLANNING QUESTIONNAIRE
I The following information will enable the owner in co-operation with the Administration to develop a Survey Plan complying with the requirements of the

---CHUNK---

SOURCE: MSC.197(80).pdf
"ANNEX4B
SURVEY PLANNING QUESTIONNAIRE
I The following information will enable the owner in co-operation with the Administration to develop a Survey Plan complying with the requirements of the Guidelines. It is essential that the owner provides, when completing the present questionnaire, up-to-date information. The present questionnaire, when completed, should provide all information and material required by the Guidelines.
Particulars
Ship's name:
IMO number:
Flag State:
Port of registry:
Owner :
Recognized organization:
Gross tonnage:
Deadweight (metric tonnes):

Date of delivery:
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 21 -
Information on access provision for close-up surveys and thickness measurement
2 The owner should indicate, in the table below, the means of access to the
structures subject to close-up survey and thickness measurement. A close-up survey is an
examination where the details of structural components are within the close visual

---CHUNK---

SOURCE: MSC.197(80).pdf
structures subject to close-up survey and thickness measurement. A close-up survey is an
examination where the details of structural components are within the close visual
inspection range of the attending surveyor, i.e. preferably within reach ofhand.
Holdrrank Structure Temporary Rafts Ladders Direct Other
No. staging access means
(please
specify)
F.P. Fore peak
A.P. Aft peak