to the hatchway coarnings, decks or covers. Individual securing devices on each cover are to have approximately the same stiffness characteristics .
. 6 Where rod cleats are fitted, resilient washers or cushions should be incorporated .
. 7 Where hydraulic cleating is adopted, a positive means should be provided to ensure that it remains mechanically locked in the closed position in the event offailure of the hydraulic system.
2 Stoppers
2.1 Nos.l and 2 hatch covers should be effectively secured, by means of stoppers, against the transverse forces arising from a pressure of 175 kN/m 2
2.2 No.2 hatch covers should be effectively secured, by means of stoppers, against the longitudinal forces acting on the forward end arising from a pressure of 175 kN/m2
2.3 No.1 hatch cover should be effectively secured, by means of stoppers, against the longitudinal forces acting on the forward end arising from a pressure of 230 kN/m2 This pressure may be reduced to 175 kN/m2 if a forecastle is fitted.

---CHUNK---

SOURCE: MSC.197(80).pdf
2.3 No.1 hatch cover should be effectively secured, by means of stoppers, against the longitudinal forces acting on the forward end arising from a pressure of 230 kN/m2 This pressure may be reduced to 175 kN/m2 if a forecastle is fitted.
2.4 The equivalent stress in stoppers and their supporting structures and calculated in the throat of the stopper welds is not to exceed the allowable value of 0.8 (Jy.
3 Materials and welding
Where stoppers or securing devices are fitted to comply with this annex, they should be manufactured of materials, including welding electrodes, to the satisfaction of the Administration. "
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 28-
ANNEXB
GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF OIL TANKERS
42 The text of existing Annex B is replaced by a new part A with the title:
"Part A
GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF DOUBLE HULL OIL TANKERS "
and a new part B with the title:
"Part B

---CHUNK---

SOURCE: MSC.197(80).pdf
42 The text of existing Annex B is replaced by a new part A with the title:
"Part A
GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF DOUBLE HULL OIL TANKERS "
and a new part B with the title:
"Part B
GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF OIL TANKERS OTHER THAN DOUBLE HULL OIL

TANKERS"
43 The text of the new part A is as follows:
"Part A
GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS
DURING SURVEYS OF DOUBLE HULL OIL TANKERS
1 General
1.1 Application
1.1.1 The Guidelines should apply to all self-propelled double hull oil tankers of 500 gross tonnage and above.
1.1.2 The Guidelines should apply to surveys of hull structure and piping systems in way of cargo tanks, pump-rooms, cofferdams, pipe tunnels, void spaces within the cargo area and all ballast tanks. The surveys should be carried out during the surveys prescribed by regulation 1/10 of the 1974 SOLAS Convention, as amended.
1.1.3 The Guidelines contain the extent of examination, thickness measurements and tank testing. The survey should be extended when substantial corrosion and/or structural

---CHUNK---

SOURCE: MSC.197(80).pdf
prescribed by regulation 1/10 of the 1974 SOLAS Convention, as amended.
1.1.3 The Guidelines contain the extent of examination, thickness measurements and tank testing. The survey should be extended when substantial corrosion and/or structural defects are found and include additional close-up survey when necessary.
1.2 Definitions
1.2.1 Double hull oil tanker is a ship which is constructed primarily for the carriage of oil in bulk, which have the cargo tanks protected by a double hull which extends for the entire length of the cargo area, consisting of double sides and double bottom spaces for the carriage of water ballast or void spaces.
1.2.2 A ballast tank is a tank which is used solely for water ballast.
1.2.3 Overall survey is a survey intended to report on the overall condition of the hull structure and determine the extent of additional close-up surveys.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 29-
1.2.4 Close-up survey is a survey where the details of structural components are within

---CHUNK---

SOURCE: MSC.197(80).pdf
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 29-
1.2.4 Close-up survey is a survey where the details of structural components are within the close visual inspection range ofthe surveyor, i.e. preferably within reach of hand.
1.2.5 Transverse section includes all longitudinal members such as plating, longitudinals and girders at the deck, sides, bottom, inner bottom and longitudinal bulkheads.
1.2.6 Representative tanks are those which are expected to reflect the condition of other tanks of similar type and service and with similar corrosion protection systems. When selecting representative tanks account should be taken of the service and repair history on board and identifiable critical and/or suspect areas.
1.2.7 Suspect areas are locations showing Substantial Corrosion and/or are considered

by the surveyor to be prone to rapid wastage.
1.2.8 Substantial corrosion is an extent of corrosion such that assessment of corrosion pattern indicates a wastage in excess of 75% of allowable margins, but within acceptable limits.

---CHUNK---

SOURCE: MSC.197(80).pdf
by the surveyor to be prone to rapid wastage.
1.2.8 Substantial corrosion is an extent of corrosion such that assessment of corrosion pattern indicates a wastage in excess of 75% of allowable margins, but within acceptable limits.
1.2.9 Corrosion prevention system is normally considered either:
.1 a full hard coating, or
.2 a full hard coating supplemented by anodes.
Protective coating should usually be epoxy coating or equivalent. Other coating systems may be considered acceptable as alternatives provided that they are applied and maintained in compliance with the manufacturer's specification.
Where soft coatings have been applied, safe access should be provided for the surveyor to verify the effectiveness of the coating and to carry out an assessment of the condition of internal structures which may include spot removal of the coating. When safe access cannot be provided, the soft coating should be removed.
1.2.10 Coating condition is defined as follows:
GOOD
FAIR
POOR
condition with only minor spot rusting,
condition with local breakdown of coating at edges of stiffeners and weld connections and/or light rusting over 20% or more of

---CHUNK---

SOURCE: MSC.197(80).pdf
1.2.10 Coating condition is defined as follows:
GOOD
FAIR
POOR
condition with only minor spot rusting,
condition with local breakdown of coating at edges of stiffeners and weld connections and/or light rusting over 20% or more of
areas under consideration, but less than as defined for POOR condition,
condition with general breakdown of coating over 20% or more of areas or hard scale at 10% or more of areas under consideration.
1.2.11 Critical structural areas are locations which have been identified from calculations to require monitoring or from the service history of the subject ship or from similar or sister ships to be sensitive to cracking, buckling or corrosion which would impair the structural integrity ofthe ship.
1.2.12 Cargo area is an area as defined in regulation II-2/3.6 of the 1974 SOLAS Convention, as amended.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS

AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 30-
1.2.13 Intermediate survey is a survey carried out either at the second or the third annual surveyor between these surveys.

---CHUNK---

SOURCE: MSC.197(80).pdf
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 30-
1.2.13 Intermediate survey is a survey carried out either at the second or the third annual surveyor between these surveys.
1.2.14 A prompt and thorough repair is a permanent repair completed at the time of survey to the satisfaction of the Surveyor, therein removing the need for the imposition of any associated condition of classification or recommendation.
1.2.15 Specially considered means sufficient close-up inspection and thickness measurements are taken to confirm the actual average condition of the structure under coating.
1.3 Repairs
1.3.1 Any damage in association with wastage over the allowable limits (including buckling, grooving, detachment or fracture), or extensive areas of wastage over the allowable limits, which affects or, in the opinion of the Administration, will affect the ship's structural, watertight or weathertight integrity, should be promptly and thoroughly (see 1.2.14) repaired. Areas to be considered include: