.1 bottom structure and bottom plating;
.2 side structure and side plating;
.3 deck structure and deck plating;

---CHUNK---

SOURCE: MSC.197(80).pdf
(see 1.2.14) repaired. Areas to be considered include:
.1 bottom structure and bottom plating;
.2 side structure and side plating;
.3 deck structure and deck plating;
.4 inner bottom structure and inner bottom plating;
.5 inner side structure and inner side plating;
.6 longitudinal buJkhead(s) structure and longitudinal bulkhead(s) plating, where fitted;
.7 transverse watertight or oiltight bulkheads structure and transverse watertight or oiltight bulkheads plating;
.8 hatch covers or hatch coamings, where fitted; and
.9 items in paragraph 3.3.
Where adequate repair facilities are not available, the Administration may allow the ship to proceed directly to a repair facility. This may require discharging the cargo and/or temporary repairs for the intended voyage.
1.3.2 Additionally, when a survey results in the identification of corrosion or structural defects, either of which, in the opinion of the Administration, will impair the ship's fitness for continued service, remedial measures should be implemented before the ship continues in service.
1.4 Surveyors
For tankers of 20,000 tons deadweight and above, two surveyors should jointly carry out

---CHUNK---

SOURCE: MSC.197(80).pdf
fitness for continued service, remedial measures should be implemented before the ship continues in service.
1.4 Surveyors
For tankers of 20,000 tons deadweight and above, two surveyors should jointly carry out the first scheduled renewal survey after the tanker passes 10 years of age, and all subsequent renewal surveys and intermediate surveys. If the surveys are carried out by a

recognized organization, the surveyors should be exclusively employed by such recognized organizations.
2 Renewal survey
2.1 General
2.1.1 The renewal survey may be commenced at the fourth annual survey and be progressed during the succeeding year with a view to completion by the fifth anniversary date.
2.1.2 As part of the preparation for the renewal survey the survey programme should be dealt with in advance of the renewal survey. The thickness measurement should not be carried out before the fourth annual survey.

---CHUNK---

SOURCE: MSC.197(80).pdf
fifth anniversary date.
2.1.2 As part of the preparation for the renewal survey the survey programme should be dealt with in advance of the renewal survey. The thickness measurement should not be carried out before the fourth annual survey.
2.1.3 The survey should include, in addition to the requirements of the annual survey, examination, tests and checks of sufficient extent to ensure that the hull and related piping as required in 2.1.5 is in a satisfactory condition and is fit for its intended purpose for the new period of validity of the Cargo Ship Safety Construction Certificate, subject to proper maintenance and operation and to periodical surveys being carried out.
2.1.4 All cargo tanks, ballast tanks, pump-rooms, pipe tunnels, cofferdams and void spaces bounding cargo tanks, decks and outer hull should be examined, and this examination should be supplemented by thickness measurement and testing as deemed necessary, to ensure that the structural integrity remains effective. The examination should be sufficient to discover substantial corrosion, significant deformation, fractures, damages or other structural deterioration.

---CHUNK---

SOURCE: MSC.197(80).pdf
necessary, to ensure that the structural integrity remains effective. The examination should be sufficient to discover substantial corrosion, significant deformation, fractures, damages or other structural deterioration.
2.1.5 Cargo piping on deck, including crude oil washing (COW) piping, and cargo and ballast piping within the above tanks and spaces should be examined and operationally tested to working pressure to attending surveyor's satisfaction to ensure that tightness and condition remain satisfactory. Special attention should be given to any ballast piping in cargo tanks and cargo piping in ballast tanks and void spaces, and surveyors should be advised on all occasions when this piping, including valves and fittings, are open during repair periods and can be examined internally.
2.2 Dry-dock survey
2.2.1 A survey in dry-dock should be a part of the renewal survey. There should be a minimum of two inspections of the outside of the ship's bottom during the five-year period ofthe Safety Construction Certificate. In all cases, the maximum interval between bottom inspections should not exceed 36 months.

---CHUNK---

SOURCE: MSC.197(80).pdf
minimum of two inspections of the outside of the ship's bottom during the five-year period ofthe Safety Construction Certificate. In all cases, the maximum interval between bottom inspections should not exceed 36 months.
2.2.2 For ships of 15 years of age and over, inspection of the outside of the ship's bottom should be carried out with the ship in dry-dock. For ships ofless than 15 years of age, alternate inspections of the ship's bottom not conducted in conjunction with the renewal survey may be carried out with the ship afloat. Inspection of the ship afloat should only be carried out when the conditions are satisfactory and the proper equipment and suitably qualified staff is available.
2.2.3 If a survey in dry-dock is not completed in conjunction with the renewal surveyor if the 36 month maximum interval referred to in 2.2.1 is not complied with, the Cargo Ship Safety Construction Certificate should cease to be valid until a survey in dry-dock is completed.

---CHUNK---

SOURCE: MSC.197(80).pdf
completed.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 32-
2.3 Tank corrosion prevention system
Where provided, the condition of the corrosion prevention system of cargo tanks should be examined. A ballast tank where a protective coating is found in POOR condition and it is not renewed, or where soft coating has been applied, or where a protective coating has not been applied from the time of construction, the tank in question should be examined at annual intervals. Thickness measurement should be carried out as deemed necessary by the surveyor.
2.4 Extent of overall and close-up surveys
2.4.1 An overall survey of all integral tanks and spaces should be carried out at the renewal survey.
2.4.2 The requirements for close-up surveys at the renewal survey are given in annex 1.
2.4.3 The surveyor may extend the scope of the close-up survey as deemed necessary taking into account the maintenance of the tanks under survey, the condition of the corrosion prevention system and also in the following cases:

---CHUNK---

SOURCE: MSC.197(80).pdf
2.4.3 The surveyor may extend the scope of the close-up survey as deemed necessary taking into account the maintenance of the tanks under survey, the condition of the corrosion prevention system and also in the following cases:
.1 in particular, tanks having structural arrangements or details which have suffered defects in similar tanks or on similar ships according to available information;
.2 in tanks which have structures with reduced scantlings in association with a corrosion prevention system approved by the Administration.
2.4.4 For areas in tanks where coatings are found to be in GOOD condition as defined in 1.2.10, the extent of close-up surveys according to annex 1 may be specially considered by the Administration.
2.5 Extent of thickness measurements
2.5.1 The requirements for thickness measurements at the renewal survey are given in annex 2.
2.5.2 Where substantial corrosion as defined in 1.2.8 is found, the extent of thickness measurements should be increased in accordance with the requirements of annex 4.
2.5.3 The surveyor may extend the thickness measurements as deemed necessary.

---CHUNK---

SOURCE: MSC.197(80).pdf

2.5.2 Where substantial corrosion as defined in 1.2.8 is found, the extent of thickness measurements should be increased in accordance with the requirements of annex 4.
2.5.3 The surveyor may extend the thickness measurements as deemed necessary.
2.5.4 For areas in tanks where coatings are found to be in GOOD condition as defined in 1.2.10, the extent of thickness measurements according to annex 2 may be specially considered by the Administration.
2.5.5 Transverse sections should be chosen where the largest reductions are suspected to occur or are revealed from deck plating measurements.
2.5.6 In cases where two or three sections are to be measured, at least one should include a ballast tank within O.SL amidships.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 33 -
2.6 Extent of tank pressure testing
2.6.1 The requirements for tank pressure testing at the renewal survey are given in annex 3.
2.6.2 The surveyor may extend the tank pressure testing as deemed necessary.

---CHUNK---

SOURCE: MSC.197(80).pdf