2.6 Extent of tank pressure testing
2.6.1 The requirements for tank pressure testing at the renewal survey are given in annex 3.
2.6.2 The surveyor may extend the tank pressure testing as deemed necessary.
2.6.3 Generally, the pressure should correspond to a water level to the top of access hatches for cargo tanks, or top of air pipes for ballast tanks.
3 Annual survey
3.1 General
The annual survey should consist of an examination for the purpose of ensuring, as far as practicable, that the hull and piping are maintained in a satisfactory condition and should take into account the service history, condition and extent of the corrosion prevention system of ballast tanks and areas identified in the survey report file.
3.2 Examination of the hull
3.2.1 Examination of the hull plating and its closing appliances should be carried out as far as can be seen.
3.2.2 Examination of watertight penetrations should be carried out as far as practicable.
3.3 Examination of weather decks
3.3.1 Examination of cargo tank openings including gaskets, covers, coammgs and flame screens.
3.3.2 Examination of cargo tank pressure/vacuum valves and flame screens.

---CHUNK---

SOURCE: MSC.197(80).pdf
3.3 Examination of weather decks
3.3.1 Examination of cargo tank openings including gaskets, covers, coammgs and flame screens.
3.3.2 Examination of cargo tank pressure/vacuum valves and flame screens.
3.3.3 Examination of flame screens on vents to all bunker and oily slop tanks.
3.3.4 Examination of cargo, crude oil washing, bunker and vent piping systems, including vent masts and headers.
3.4 Examination of cargo pump-rooms and pipe tunnels
3.4.1 Examination of all bulkheads for signs of oil leakage or fractures and, m particular, the sealing arrangements of all penetrations of bulkheads.
3.4.2 Examination of the condition of all piping systems and pipe tunnels.
3.5 Examination of ballast tanks
3.5.1 Examination of ballast tanks should be carried out when required as a consequence of the results of the renewal survey and intermediate survey. When extensive corrosion is found, thickness measurements should be carried out.
3.5.2 Where substantial corrosion as defined in 1.2.8 is found, the extent of thickness measurements should be increased in accordance with the requirements in annex 4.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)

---CHUNK---

SOURCE: MSC.197(80).pdf
3.5.2 Where substantial corrosion as defined in 1.2.8 is found, the extent of thickness measurements should be increased in accordance with the requirements in annex 4.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 34-

3.5.3 Double hull oil tankers exceeding 15 years of age
3.5.3.1 All ballast tanks adjacent to (i.e. with a common plane boundary) a cargo or fuel tank with any means of heating should be examined internally. When considered necessary by the surveyor, thickness measurement should be carried out and if the results of these thickness measurements indicate that substantial corrosion is found, the extent of thickness measurements should be increased in accordance with annex 4.
3.5.3.2 Ballast tanks which were found, at the previous intermediate or renewal survey, to have no substantial corrosion within the tank and which were found in compliance with either of the following conditions:
.1 coating in GOOD condition; or
.2 coating of the common boundary, including adjacent structures, in GOOD

---CHUNK---

SOURCE: MSC.197(80).pdf
to have no substantial corrosion within the tank and which were found in compliance with either of the following conditions:
.1 coating in GOOD condition; or
.2 coating of the common boundary, including adjacent structures, in GOOD condition and the coating of the remaining parts of the tank in FAIR condition,
may be specially considered by the Administration.
4 Intermediate survey
4.1 General
4.1.1 Items that are additional to the requirements of the annual survey may be surveyed either at the second or third annual surveyor between these surveys.
4.1.2 The survey extent of cargo and ballast tanks dependent on the age of the ship is specified in 4.2, 4.3 and 4.4 and shown in annex 5.
4.1.3 For weather decks, an examination as far as applicable of cargo, crude oil washing, bunker, ballast, steam and vent piping systems as well as vent masts and headers. If upon examination there is any doubt as to the condition of the piping, the piping may be required to be pressure tested, thickness measured or both.
4.2 Oil tankers of 5 to 10 years of age
4.2.1 The requirements of 4.1.3 apply.

---CHUNK---

SOURCE: MSC.197(80).pdf
headers. If upon examination there is any doubt as to the condition of the piping, the piping may be required to be pressure tested, thickness measured or both.
4.2 Oil tankers of 5 to 10 years of age
4.2.1 The requirements of 4.1.3 apply.
4.2.2 For tanks used for salt water ballast, an overall survey of representative tanks selected by the surveyor should be carried out. If the overall survey of salt water ballast tanks reveals no visible structural defects, the examination may be limited to verification that the protective coatings remain efficient.
4.2.3 Where POOR coating condition, corrosion or other defects are found in salt water ballast tanks or where a protective coating was not applied from the time of construction, the examination should be extended to other ballast tanks of the same type.
4.2.4 In salt water ballast tanks where a protective coating is found in POOR condition and it is not renewed, where soft coating has been applied, or where a protective coating was not applied from the time of construction, the tanks in question should be examined and thickness measurements carried out as considered necessary at annual intervals.

---CHUNK---

SOURCE: MSC.197(80).pdf
was not applied from the time of construction, the tanks in question should be examined and thickness measurements carried out as considered necessary at annual intervals.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 35 -
4.3 Oil tankers of 10 to 15 years of age
4.3.1 The requirements of 4.2 apply.
4.3.2 An overall survey of at least two representative cargo tanks should be carried out.
4.3.3 For ballast tanks, where fitted, an overall survey of all such tanks should be carried out. If such survey reveals no visible structural defects, the survey may be limited to a verification that the protective coatings remain efficient.
4.3.4 Extent of close-up survey
Ballast tanks: to the same extent as previous renewal survey;
Cargo tanks: the extent of survey should be based on the record of the previous renewal survey and repair history of the tanks, and be applied to two cargo tanks after the second renewal survey.
The minimum requirements of close-up surveys are given in annex 5. The extent of

---CHUNK---

SOURCE: MSC.197(80).pdf
survey and repair history of the tanks, and be applied to two cargo tanks after the second renewal survey.
The minimum requirements of close-up surveys are given in annex 5. The extent of close-up surveys may be extended as stated in 2.4.3. For areas in tanks where coatings are found to be in GOOD condition, the extent of the close-up surveys according to annex 5 may be specially considered by the Administration.
4.3.5 Extent of thickness measurements
The extent of thickness measurements is also given in annex 5. The mllllmum requirements for thickness measurements at the intermediate survey are areas found to be suspect areas according to 1.2.7 at the previous renewal survey. Where substantial corrosion as defined in 1.2.8 is found, the extent of the thickness measurements according to annex 5 should be increased in accordance with the requirements of annex 4.
4.4 Oil tankers exceeding 15 years of age
The requirements of the intermediate survey should be to the same extent as the previous renewal survey as required in 2 and 5.1. However, pressure testing of cargo and ballast tanks is not required unless deemed necessary by the attending surveyor.

---CHUNK---

SOURCE: MSC.197(80).pdf
renewal survey as required in 2 and 5.1. However, pressure testing of cargo and ballast tanks is not required unless deemed necessary by the attending surveyor.
5 Preparations for survey
5.1 Survey programme
5.1.1 A specific survey programme should be worked out in advance of the renewal survey by the owner in co-operation with the Administration. The survey programme should be in a written format based on the information in annex 6A. The survey should not commence until the survey programme has been agreed.

5.1.1.1 Prior to the development of the survey progra=e , the survey planning questionnaire should be completed by the owner based on the information set out in annex 6B, and forwarded to the Administration.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 36-
5.1.2 In developing the survey programme, the following documentation should be collected and consulted with a view to selecting tanks, areas, and structural elements to be examined:
.1 survey status and basic ship information;

---CHUNK---

SOURCE: MSC.197(80).pdf
5.1.2 In developing the survey programme, the following documentation should be collected and consulted with a view to selecting tanks, areas, and structural elements to be examined:
.1 survey status and basic ship information;
.2 documentation on board, as described in 6.2 and 6.3;
.3 main structural plans of cargo and ballast tanks (scantlings drawings), including information regarding use of high-tensile steels (HTS);