.4 Condition Evaluation Report, according to annex 9;
.5 relevant previous damage and repair history;
.6 relevant previous survey and inspection reports from both the recognized organization and the owner;
.7 cargo and ballast history for the last 3 years, including carriage of cargo under heated conditions;
.8 details of the inert gas plant and tank cleaning procedures;
.9 information and other relevant data regarding conversion or modification of the ship's cargo and ballast tanks since the time of construction;
.10 description and history of the coating and corrosion protection system (including anodes and previous class notations), if any;
.11 inspections of the Owner's personnel during the last 3 years with reference

---CHUNK---

SOURCE: MSC.197(80).pdf
.10 description and history of the coating and corrosion protection system (including anodes and previous class notations), if any;
.11 inspections of the Owner's personnel during the last 3 years with reference to structural deterioration in general, leakages in tank boundaries and piping and condition of the coating and corrosion protection system (including anodes), if any. A guidance for reporting is shown in annex 6C;
.12 information regarding the relevant maintenance level during operation including port state control reports of inspection containing hull-related deficiencies , Safety Management System non-conformities relating to hull maintenance, including the associated corrective action(s); and
.13 any other information that will help identify suspect areas and critical structural areas.
5.1.3 The submitted survey programme should account for and comply, as a minimum, with the requirements of annexes 1, 2 and 3 and paragraph 2.6 for close-up survey, thickness measurement and tank testing, respectively, and should include relevant information including at least:
.1 basic ship information and particulars;

---CHUNK---

SOURCE: MSC.197(80).pdf
with the requirements of annexes 1, 2 and 3 and paragraph 2.6 for close-up survey, thickness measurement and tank testing, respectively, and should include relevant information including at least:
.1 basic ship information and particulars;
.2 main structural plans of cargo and ballast tanks (scantling drawings), including information regarding use of high tensile steels (HTS);
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 37 -
.3 arrangement of tanks ;
.4 list of tanks with information on their use, extent of coatings and corrosion protection systems;
.5 conditions for survey (e.g., information regarding tank cleaning , gas freeing, ventilation, lighting, etc.);

.6 provisions and methods for access to structures;
.7 equipment for surveys;
.8 identification of tanks and areas for close-up survey (see 2.4) ;
.9 identification of areas and sections for thickness measurement (see 2.5);
.10 identification of tanks for tank testing (see 2.6);
.11 identification of the thickness measurement company;

---CHUNK---

SOURCE: MSC.197(80).pdf
.9 identification of areas and sections for thickness measurement (see 2.5);
.10 identification of tanks for tank testing (see 2.6);
.11 identification of the thickness measurement company;
.12 damage experience related to the ship in question; and
.13 critical structural areas and suspect areas, where relevant.
5.1.4 The Administration will advise the owner of the maximum acceptable structural corrosion diminution levels applicable to the ship.
5.1.5 Use may also be made of the Guidelines for technical assessment in conjunction with the planning of enhanced surveys for tankers, contained in annex II. These Guidelines are a recommended tool which may be invoked at the discretion of the Administration, when considered necessary and appropriate, in conjunction with the preparation of the required survey programme.
5.2 Conditions for survey
5.2.1 The owner should provide the necessary facilities for a safe execution of the survey.
5.2.1.1 In order to enable the attending surveyors to carry out the survey, provisions for proper and safe access should be agreed between the owner and the Administration.

---CHUNK---

SOURCE: MSC.197(80).pdf
survey.
5.2.1.1 In order to enable the attending surveyors to carry out the survey, provisions for proper and safe access should be agreed between the owner and the Administration.
5.2.1.2 Details of the means of access should be provided in the survey planning questionnaire.
5.2.1.3 In cases where the provisions of safety and required access are judged by the attending surveyors not to be adequate, the survey of the spaces involved should not proceed.
5.2.2 Tanks and spaces should be safe for access. Tanks and spaces should be gas free and properly ventilated. Prior to entering a tank, void or enclosed space, it should be verified that the atmosphere in that space is free from hazardous gas and contains sufficient oxygen .
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 38-
5.2.3 Tanks and spaces should be sufficiently clean and free from water, scale, dirt, oil residues, sediments, etc., to reveal corrosion, deformation, fractures, damages or other

---CHUNK---

SOURCE: MSC.197(80).pdf

AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 38-
5.2.3 Tanks and spaces should be sufficiently clean and free from water, scale, dirt, oil residues, sediments, etc., to reveal corrosion, deformation, fractures, damages or other structural deterioration as well as the condition of the coating. In particular this applies to areas which are subject to thickness measurement.
5.2.4 Sufficient illumination should be provided to reveal corrosion, deformation, fractures, damages or other structural deterioration as well as the condition ofthe coating.
5.2.5 The surveyor(s) should always be accompanied by at least one responsible person, assigned by the owner, experienced in tank and enclosed spaces inspection. In addition a backup team of at least two experienced persons should be stationed at the hatch opening of the tank or space that is being surveyed. The back-up team should continuously observe the work in the tank or space and should keep lifesaving and evacuation equipment ready for use.
5.2.6 A communication system should be arranged between the survey party in the tank or space being examined, the responsible officer on deck and, as the case may be, the

---CHUNK---

SOURCE: MSC.197(80).pdf
equipment ready for use.
5.2.6 A communication system should be arranged between the survey party in the tank or space being examined, the responsible officer on deck and, as the case may be, the navigation bridge. The communication arrangements should be maintained throughout the survey.
5.3 Access to structures
5.3.1 For overall surveys, means should be provided to enable the surveyor to examine the structure in a safe and practical way.
5.3.2 For close-up surveys, one or more of the following means for access, acceptable to the surveyor, should be provided:
.1 permanent staging and passages through structures;
.2 temporary staging and passages through structures;
.3 lifts and moveable platforms;
.4 boats or rafts;
.5 portable ladders;
.6 other equivalent means.
5.4 Equipment for survey
5.4.1 Thickness measurement should normally be carried out by means of ultrasonic test equipment. The accuracy of the equipment should be proven to the surveyor as required.
5.4.2 One or more of the following fracture detection procedures may be required if deemed necessary by the surveyor:
.1 radiographic equipment;
.2 ultrasonic equipment;
RESOLUTION MSC.197(80)

---CHUNK---

SOURCE: MSC.197(80).pdf
required.
5.4.2 One or more of the following fracture detection procedures may be required if deemed necessary by the surveyor:
.1 radiographic equipment;
.2 ultrasonic equipment;
RESOLUTION MSC.197(80)

(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 39-
.3 magnetic particle equipment;
.4 dye penetrant; and
.5 other equivalent means.
5.4.3 Explosimeter, oxygen-meter, breathing apparatus, lifelines, riding belts with rope and hook and whistles together with instructions and guidance on their use should be made available during the survey. A safety checklist should be provided.
5.4.4 Adequate and safe lighting should be provided for the safe and efficient conduct of the survey.
5.4.5 Adequate protective clothing should be made available and used during the survey (e.g., safety helmet, gloves, safety shoes, etc.).
5.5 Surveys at sea or at anchorage
5.5.1 Surveys at sea or at anchorage may be accepted provided the surveyor(s) is given the necessary assistance from the personnel on board. Necessary precautions and

---CHUNK---

SOURCE: MSC.197(80).pdf
5.5 Surveys at sea or at anchorage
5.5.1 Surveys at sea or at anchorage may be accepted provided the surveyor(s) is given