audited in order to ascertain that the company is duly organized and managed in accordance with the documents submitted and is capable of conducting thickness measurement of the hull structure of ships.
2.3 Certification is conditional upon an on-board demonstration of thickness measurement as well as satisfactory reporting.
3 Certification
3.1 Upon satisfactory results of both the audit of the company referred to in 2.2 and the demonstration tests referred to in 2.3, the Administration or organization recognized by the Administration should issue a certificate of approval as well as a notice to the effect that the thickness measurement operation system of the company has been

---CHUNK---

SOURCE: MSC.197(80).pdf
by the Administration should issue a certificate of approval as well as a notice to the effect that the thickness measurement operation system of the company has been certified.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 66-
3.2 Renewal/endorsement of the certificate should be carried out at intervals not exceeding three years by verification that original conditions are maintained.
4 Report of any alteration to the certified thickness measurement operation system
In case any alteration to the certified thickness measurement operation system of the company is made, such alteration should be immediately reported to the organization recognized by the Administration. A re-audit should be carried out where deemed necessary by the organization recognized by the Administration.
5 Withdrawal of certification
The certification may be withdrawn in the following cases:
.1 where the measurements were improperly carried out or the results were improperly reported;

---CHUNK---

SOURCE: MSC.197(80).pdf
5 Withdrawal of certification
The certification may be withdrawn in the following cases:
.1 where the measurements were improperly carried out or the results were improperly reported;
.2 where the surveyor found any deficiencies in the approved thickness measurement operation system of the company;
.3 where the company failed to report any alteration referred to in 4 to the organization recognized by the Administration as required.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 67-
ANNEX 8
SURVEY REPORTING PRINCIPLES
As a principle, for oil tankers subject to the Guidelines, the surveyor should include the

following contents in his report for survey of hull structure and piping systems, as relevant for the survey.
1 General
1.1 A survey report should be generated in the following cases:
. I in connection with commencement , continuation and/or completion of periodical hull surveys, i.e. annual, intermediate and renewal surveys, as relevant;
.2 when structural damages/defects have been found;

---CHUNK---

SOURCE: MSC.197(80).pdf
. I in connection with commencement , continuation and/or completion of periodical hull surveys, i.e. annual, intermediate and renewal surveys, as relevant;
.2 when structural damages/defects have been found;
.3 when repairs, renewals or modifications have been carried out; and
.4 when condition of class (recommendation) has been imposed or deleted.
1.2 The reporting should provide:
.1 evidence that prescribed surveys have been carried out in accordance with applicable requirements;
.2 documentation of surveys carried out with findings, repairs carried out and condition of class (recommendation) imposed or deleted;
.3 survey record s, including actions taken, which should form an auditable documentary trail. Survey reports should be kept in the survey report file required to be on board;
.4 information for planning of future surveys; and
.5 information which may be used as input for maintenance of classification rules and instructions .
1.3 When a survey is split between different survey stations, a report should be made for each portion of the survey. A list of items surveyed, relevant findings and an

---CHUNK---

SOURCE: MSC.197(80).pdf
rules and instructions .
1.3 When a survey is split between different survey stations, a report should be made for each portion of the survey. A list of items surveyed, relevant findings and an indication of whether the item has been credited , should be made available to the next attending surveyor, prior to continuing or completing the survey. Thickness measurement and tank testing carried out should also be listed for the next surveyor.
2 Extent of the survey
2.1 Identification of compartments where an overall survey has been carried out.
2.2 Identification of locations, in each tank, where a close-up survey has been carried out, together with information of the means of access used.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 68-
2.3 Identification of locations, in each tank, where thickness measurement has been carried out.
Note: As a minimum, the identification of location of close-up survey and thickness measurement should include a confirmation with description of individual

---CHUNK---

SOURCE: MSC.197(80).pdf
carried out.
Note: As a minimum, the identification of location of close-up survey and thickness measurement should include a confirmation with description of individual structural members corresponding to the extent of requirements stipulated in this part of Annex B based on type of periodical survey and the ship's age.
Where only partial survey is required, i.e. one web frame ring/one deck transverse, the identification should include location within each ballast tank and cargo hold by reference to frame numbers.
2.4 For areas in tanks where protective coating is found to be in good condition and the extent of close-up survey and/or thickness measurement has been specially considered , structures subject to special consideration should be identified.
2.5 Identification of tanks subject to tank testing.
2.6 Identification of piping systems on deck, including crude oil washing (COW) piping , and ballast piping within cargo and ballast tanks, pipe tunnels, cofferdams and void spaces where:
.1 examination including internal examination of piping with valves and fittings and thickness measurement, as relevant, has been carried out; and

---CHUNK---

SOURCE: MSC.197(80).pdf
void spaces where:
.1 examination including internal examination of piping with valves and fittings and thickness measurement, as relevant, has been carried out; and
.2 operational test to working pressure has been carried out.
3 Result of survey
3.1 Type, extent and condition of protective coating in each tank, as relevant (rated GOOD, FAIR or POOR), including identification of tanks fitted with anodes.
3.2 Structural condition of each compartment with information on the following, as relevant:
.1 Identification of findings, such as:
.1.1 corrosion with description oflocation, type and extent;
.1.2 areas with substantial corrosion ;
.1 .3 cracks/fractures with description of location and extent;
.1.4 buckling with description ofloca tion and extent; and
.1.5 indents with description of location and extent.
.2 Identification of compartments where no structural damages/defects are found. The report may be supplemented by sketches/photos .
. 3 Thickness measurement report should be verified and signed by the surveyor controlling the measurements on board.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED

---CHUNK---

SOURCE: MSC.197(80).pdf
. 3 Thickness measurement report should be verified and signed by the surveyor controlling the measurements on board.
RESOLUTION MSC.197(80)

(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 69-
.4 Evaluation result of longitudinal strength of the hull girder of oil tankers of
130 m in length and upwards and over 10 years of age. The following data
should be included, as relevant:
.4.1 measured and as-built transverse sectional areas of deck and
bottom flanges;
.4.2 diminution of transverse sectional areas of deck and bottom
flanges; and
.4.3 details of renewals or reinforcements carried out, as relevant
(see 4.2).
4 Actions taken with respect to findings
4.1 Whenever the attending surveyor is of the opinion that repairs are required, each item to be repaired should be identified in a numbered list. Whenever repairs are carried out, details of the repairs effected should be reported by making specific reference to relevant items in the numbered list.
4.2 Repairs carried out should be reported with identification of:
.1 compartment;

---CHUNK---