---CHUNK---

SOURCE: MSC.197(80).pdf
programme .
3.2.2.4 The various tanks and spaces should be listed with the corrosion risks nominated accordingly. Special attention should be given to the areas where the double hull tanker is particularly exposed to corrosion. To this end, the specific aspects addressing corrosion in double hull tankers indicated in 3.4 (Corrosion trends) of reference I should be taken into account.
3.2.3 Locations for close-up survey and thickness measurement
3.2.3.1 On the basis of the table of corrosion risks and the evaluation of design experience, the locations for initial close-up survey and thickness measurement (sections) may be nominated.
3.2.3.2 The sections subject to thickness measurement should normally be nominated in tanks and spaces where corrosion risk is judged to be the highest.
3.2.3.3 The nomination of tanks and spaces for close-up survey should, initially , be based on highest corrosion risk and should always include ballast tanks. The principle for the selection should be that the extent is increased by age or where information is insufficient or umeliable.
REFERENCES
Tanker Structure Co-operative Forum (TSCF), "Guidelines for the Inspection and

---CHUNK---

SOURCE: MSC.197(80).pdf
for the selection should be that the extent is increased by age or where information is insufficient or umeliable.
REFERENCES
Tanker Structure Co-operative Forum (TSCF), "Guidelines for the Inspection and
Maintenance of Double Hull Tanker Structures , 1995"
2 Tanker Structure Co-operative Forum (TSCF), "Guidance Manual for Tanker Structures, 1997"
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)Input:
raWln1f," Reports , D
A
A
ccepta Ie Corrosion
llowance
Design Related Risk
t
Analyse :
Hull Damage
Thi. Ship
AnalyseHuU
Damage for
Similar Ship.
Where Available
Hull Damage : : I
General Experience

Present Areas where
Damage has been found
and Risks considered
high, Mark Sketches or
Drawings
- 100 -
Collection of Information
Coating Co
Anode Con
nditlon
dltion .-.
nks : UsageofTa
Corrosion Risk
t
Coating condition
Anodes Condition
Usage of Tanks
Corrosion Damage
This Ship
Corrosion Damage
Similar Ship where
Available

Location for Thickness Measurement and Close-Up Survey

---CHUNK---

SOURCE: MSC.197(80).pdf
dltion .-.
nks : UsageofTa
Corrosion Risk
t
Coating condition
Anodes Condition
Usage of Tanks
Corrosion Damage
This Ship
Corrosion Damage
Similar Ship where
Available

Location for Thickness Measurement and Close-Up Survey
~
Survey Programme
1 .

~----------
_____ J
Survey
FIGURE 1:. TECHNICAL ASSESSMENT AND THE SURYEY PLANNING PROCESS
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS

AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)LOCATION:
EXAMPLE No.1:
- 101 -
Connection of longitudinals to transverse webs
Web and flat bar fractures at cut·outs for longitudinal stiffener
connections
TYPICAL DAMAGE PROPOSED REPAIR
*FRACTURE
FULL COLIAR IF FRACTURES IN
WEB PLATE ARE SMALL AND
ARE REPAIRED BY WELDING
SHELL PIATING
OR LONGITUDINAL
BULKHEAD
FRACTURED
WELDIWEB
VIEW A-A
SIDE SHELL OR
BULKHEAD
LONGITUDINAL
A
WEB PIATING
WEB FLAT BAR
STIFFENER
LUG
VIEW A·A
NOTE *ONE OR MORE FRACTURES
MAY OCCUR
WEB AND FLAT BAR CROPPED
AND PART RENEWED OR
ALTERNATIVELY WELDED
FACTORS CONTRIBUTING TO DAMAGE

---CHUNK---

SOURCE: MSC.197(80).pdf
VIEW A-A
SIDE SHELL OR
BULKHEAD
LONGITUDINAL
A
WEB PIATING
WEB FLAT BAR
STIFFENER
LUG
VIEW A·A
NOTE *ONE OR MORE FRACTURES
MAY OCCUR
WEB AND FLAT BAR CROPPED
AND PART RENEWED OR
ALTERNATIVELY WELDED
FACTORS CONTRIBUTING TO DAMAGE
1. Asynunetrical colUlection of flat bar stiffener resulting in high peak stresses at the heel of
the stiffener under fatigue loading.

2. Insufficient area of connection of loogitudinal to web plate.
3. Defective weld at return around the plate thickness.
4. High localised corrosion at areas of stress concentratioo such BS flat bar stiffener connections, comera of cut-<lut for the longitudinal and connection of web to shell at cut-<luts.
5 High stress in the web of the transverse.
6. Dynamic sea way load/ship motions.
RGURE
1
TANKER STRUCTURE CO-OPERATIVE FORUM
SUBJECT: CATALOGUE OF STRUCTURAL DETAILS
FIGURE 2: TYPICAL DAMAGE AND REPAIR EXAMPLE
(REPRODUCED FROM REF. 2)
FIGURE
1
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 102-
ANNEX 12

---CHUNK---