---CHUNK---

SOURCE: MSC.197(80).pdf
amidships. However, in special cases, based on consideration of type of ship, hull form and loading conditions, the scantlings may be gradually reduced towards the end of O.4L part, bearing in mind the desire not to inhibit the ship's loading flexibility.
3 However, the above standard may not be applicable to ships of unusual type or design, e.g. for ships of unusual main proportions andlor weight distributions.
Appendix 3
Sampling method of thickness measurements for longitudinal strength evaluation and repair methods
1 Extent of longitudinal strength evaluation
Longitudinal strength should be evaluated within O.4L amidships for the extent ofthe hull girder length that contains tanks therein and within 0.5L amidships for adjacent tanks which may extend beyond O.4L amidships, where tanks means ballast tanks and cargo tanks.
2 Sampling method of thickness measurement
2.1 Pursuant to the requirements of section 2.5, transverse sections should be chosen such that thickness measurements can be taken for as many different tanks in corrosive environments as possible, e.g. ballast tanks sharing a common plane boundary with cargo

---CHUNK---

SOURCE: MSC.197(80).pdf
such that thickness measurements can be taken for as many different tanks in corrosive environments as possible, e.g. ballast tanks sharing a common plane boundary with cargo tanks fitted with heating coils, other ballast tanks, cargo tanks permitted to be filled with seawater and other cargo tanks. Ballast tanks sharing a common plane boundary with cargo tanks fitted with heating coils and cargo tanks permitted to be filled with seawater should be selected where present.
2.2 The minimum number of transverse sections to be sampled should be in accordance with annex 2. The transverse sections should be located where the largest thickness reductions are suspected to occur or are revealed from deck and bottom plating measurements prescribed in 2.3 and should be clear of areas which have been locally renewed or reinforced.
2.3 At least two points should be measured on each deck plate andlor bottom shell plate required to be measured within the cargo area in accordance with the requirements of annex 2.
2.4 Within 0.1D (where D is the ship's moulded depth) of the deck and bottom at each transverse section to be measured in accordance with the requirements of annex 2,

---CHUNK---

SOURCE: MSC.197(80).pdf
of annex 2.
2.4 Within 0.1D (where D is the ship's moulded depth) of the deck and bottom at each transverse section to be measured in accordance with the requirements of annex 2, every longitudinal and girder should be measured on the web and face plate, and every plate should be measured at one point between longitudinals.
2.5 For longitudinal members other than those specified in 2.4 to be measured at each transverse section in accordance with the requirements of annex 2, every longitudinal and girder should be measured on the web and face plate, and every plate should be measured at least in one point per strake.

(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- \06-
2.6 The thickness of each component should be determined by averaging all of the measurements taken in way of the transverse section on each component.
3 Additional measurements where the longitudinal strength is deficient
3.1 Where one or more of the transverse sections are found to be deficient in respect

---CHUNK---

SOURCE: MSC.197(80).pdf
measurements taken in way of the transverse section on each component.
3 Additional measurements where the longitudinal strength is deficient
3.1 Where one or more of the transverse sections are found to be deficient in respect of the longitudinal strength requirements given in this annex, the number of transverse sections for thickness measurement should be increased such that each tank within the O.5L amidships region has been sampled. Tank spaces that are partially within, but extend beyond, the O.5L region, should be sampled.
3.2 Additional thickness measurements should also be performed on one transverse section forward and one aft of each repaired area to the extent necessary to ensure that the areas bordering the repaired section also comply with the requirements of the Guidelines.
4 Effective repair methods
4.1 The extent of renewal or reinforcement carried out to comply with this annex should be in accordance with 4.2.
4.2 The minimum continuous length of a renewed or reinforced structural member should be not less than twice the spacing of the primary members in way. In addition, the

---CHUNK---

SOURCE: MSC.197(80).pdf
should be in accordance with 4.2.
4.2 The minimum continuous length of a renewed or reinforced structural member should be not less than twice the spacing of the primary members in way. In addition, the thickness diminution in way of the butt joint of each joining member forward and aft of the replaced member (plates, stiffeners, girder webs and flanges, etc.) should not be within the substantial corrosion range (75% of the allowable diminution associated with each particular member). Where differences in thickness at the butt joint exceed 15% of the lower thickness, a transition taper should be provided.
4.3 Alternative repair methods involving the fitting of straps or structural member modification should be subject to special consideration. In considering the fitting of straps, it should be limited to the following conditions:
.1 to restore and/or increase longitudinal strength;
.2 the thickness diminution of the deck or bottom plating to be reinforced should not be within the substantial corrosion range (75% of the allowable diminution associated with the deck plating);
.3 the alignment and arrangement, including the termination of the straps, is

---CHUNK---

SOURCE: MSC.197(80).pdf
should not be within the substantial corrosion range (75% of the allowable diminution associated with the deck plating);
.3 the alignment and arrangement, including the termination of the straps, is

in accordance with a standard recognized by the Administration;
.4 the straps are continuous over the entire O.5L amidships length; and
.5 continuous fillet welding and full penetration welds are used at butt welding and, depending on the width of the strap, slot welds. The welding procedures applied should be acceptable to the Administration.
4.4 The existing structure adjacent to replacement areas and in conjunction with the fitted straps, etc., should be capable of withstanding the applied loads, taking into account the buckling resistance and the condition of welds between the longitudinal members and hull envelope plating."
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 107 -
Part B
GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF OIL TANKERS OTHER THAN DOUBLE HULL OIL TANKERS

---CHUNK---

SOURCE: MSC.197(80).pdf
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 107 -
Part B
GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF OIL TANKERS OTHER THAN DOUBLE HULL OIL TANKERS
44 The text of the new Part B is the text of existing Annex B subject to the following amendments.
45 The existing paragraph 1.1.1 is replaced with the following:
"1.1.1 The Guidelines should apply to self-propelled oil tankers of 500 gross tonnage and above other than double hull oil tankers, as defined in 1.2.1 of Part A of Annex B."
46 Paragraph 1.1.2 is deleted and paragraphs 1.1.3 and 1.1.4 are renumbered as paragraphs 1.1.2 and 1.1.3.
47 At the end of the new paragraph 1.1.2 (existing paragraph 1.1.3), the following sentence is added:
"The surveys should be carried out during the surveys prescribed by regulation 1/10 of the 1974 SOLAS Convention, as amended."
48 In paragraph 1.2.ll, the reference "II-2/3.32" is replaced with "II-2/3.6".
49 In paragraph 1.2.12, the words "Intermediated enhanced survey is an enhanced survey" are replaced by "Intermediate survey is a survey".

---CHUNK---

SOURCE: MSC.197(80).pdf
48 In paragraph 1.2.ll, the reference "II-2/3.32" is replaced with "II-2/3.6".
49 In paragraph 1.2.12, the words "Intermediated enhanced survey is an enhanced survey" are replaced by "Intermediate survey is a survey".
50 In paragraph 1.2.l3, the words "condition of classification" are replaced by "condition of classification or recommendation".
51 A new paragraph 1.2.14 is added as follows:
"1.2.14 Specially considered means sufficient close-up inspection and thickness measurements are taken to confirm the actual average condition of the structure under coating."
52 A new subitem ".6 items in 3.3." is added in paragraph 1.3.1.

53 The word "significant" in paragraph 1.3.2 is deleted.
54 The following new paragraph 1.4 is added:
"1.4 Surveyors
For tankers of 20,000 tons deadweight and above, two surveyors should jointly carry out the first scheduled renewal survey after the tanker passes 10 years of age, and all subsequent renewal surveys and intermediate surveys. If the surveys are carried out by a recognized organization, the surveyors should be exclusively employed by such recognized organizations."

---CHUNK---

SOURCE: MSC.197(80).pdf
subsequent renewal surveys and intermediate surveys. If the surveys are carried out by a recognized organization, the surveyors should be exclusively employed by such recognized organizations."
55 The words "thickness measurement and" in paragraph 2.1.2 are deleted.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 108 -
56 The words "Cargo Ship Safety Construction" are inserted between the words "the" and "Certificate" in paragraphs 2.1.3 and 2.2.1.