57 The words "issued to oil tankers referred to in paragraph 1.1.1 and/or the International Oil Pollution Prevention Certificate, as appropriate, issued to oil tankers referred to in paragraph 1.1.2" in paragraph 2.2.3 are deleted.
58 Paragraph 2.2.4 is deleted.
59 The references to a footnote regarding "specially considered" in paragraphs 2.4.4 and 2.5.4 are deleted.
60 The words "or as specified ill planning document as described III annex 6" III paragraph 2.5.2 are deleted.
61 In paragraph 3.1, the word "annual" is inserted before the word "survey".

---CHUNK---

SOURCE: MSC.197(80).pdf
2.5.4 are deleted.
60 The words "or as specified ill planning document as described III annex 6" III paragraph 2.5.2 are deleted.
61 In paragraph 3.1, the word "annual" is inserted before the word "survey".
62 The words ", oily ballast" are deleted in paragraph 3.3.3.
63 In paragraph 3.5.3, the words "a cargo tank" are replaced by "a cargo or fuel tank".
64 The words "For tanks used for salt water ballast including combined cargolballast tanks" in paragraph 4.3.3 are replaced by "For ballast tanks".
65 Existing paragraph 5.1.1 is replaced by the following:
"5.1.1 A specific survey programme should be worked out in advance of the renewal survey by the owner in co-operation with the Administration. The survey programme should be in a written format based on the information in Annex 6A. The survey should not commence until the survey programme has been agreed.
5.1.1.1 Prior to the development of the survey programme, the survey planning questionnaire should be completed by the owner based on the information set out in Annex 6B, and forwarded to the Administration."
66 The existing paragraph 5.1.2 is replaced with the following:

---CHUNK---

SOURCE: MSC.197(80).pdf
questionnaire should be completed by the owner based on the information set out in Annex 6B, and forwarded to the Administration."
66 The existing paragraph 5.1.2 is replaced with the following:
"5.1.2 In developing the survey programme, the following documentation should be collected and consulted with a view to selecting tanks, areas, and structural elements to be examined:
.1 survey status and basic ship information;
.2 documentation on board, as described in 6.2 and 6.3;
.3 main structural plans of cargo and ballast tanks (scantlings drawings), including information regarding use of high-tensile steels (HTS);
.4 Condition Evaluation Report, according to annex 9;
.5 relevant previous damage and repair history;
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 109-
.6 relevant previous survey and inspection reports from both the recognized organization and the owner;
.7 cargo and ballast history for the last 3 years, including carriage of cargo

under heated conditions;

---CHUNK---

SOURCE: MSC.197(80).pdf
.6 relevant previous survey and inspection reports from both the recognized organization and the owner;
.7 cargo and ballast history for the last 3 years, including carriage of cargo under heated conditions;
.8 details of the inert gas plant and tank cleaning procedures;
.9 information and other relevant data regarding conversion or modification of the ship's cargo and ballast tanks since the time of construction;
.10 description and history of the coating and corrosion protection system (including anodes and previous class notations), if any;
.11 inspections of the Owner's personnel during the last 3 years with reference to structural deterioration in general, leakages in tank boundaries and piping and condition of the coating and corrosion protection system (including anodes), if any. A guidance for reporting is shown in annex 5;
.12 information regarding the relevant maintenance level during operation including port state control reports of inspection containing hUll related deficiencies, Safety Management System non-conformities relating to hull maintenance, including the associated corrective action(s); and

---CHUNK---

SOURCE: MSC.197(80).pdf
including port state control reports of inspection containing hUll related deficiencies, Safety Management System non-conformities relating to hull maintenance, including the associated corrective action(s); and
.13 any other information that will help identifY suspect areas and critical structural areas."
67 The existing paragraph 5.1.3 is replaced with the following:
"5.1.3 The submitted survey programme should account for and comply, as a minimum , with the requirements of 2.6 and annexes 1, 2 and 3 for close-up survey, thickness measurement and tank testing, respectively, and should include relevant information including at least:
.1 basic ship information and particulars;
.2 main structural plans of cargo and ballast tanks (scantling drawings), including information regarding use of high tensile steels (HTS);
.3 arrangement of tanks;
.4 list of tanks with information on their use, extent of coatings and corrosion protection systems;
.5 conditions for survey (e.g., information regarding tank cleaning, gas freeing, ventilation, lighting, etc.);
.6 provisions and methods for access to structures;
.7 equipment for surveys;
RESOLUTION MSC.197(80)

---CHUNK---

SOURCE: MSC.197(80).pdf
protection systems;
.5 conditions for survey (e.g., information regarding tank cleaning, gas freeing, ventilation, lighting, etc.);

.6 provisions and methods for access to structures;
.7 equipment for surveys;
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 110-
.8 identification of tanks and areas for close-up survey (see 2.4);
.9 identification of areas and sections for thickness measurement (see 2.5);
.10 identification of tanks for tank testing (see 2.6);
.11 identification of the thickness measurement company;
.12 damage experience related to the ship in question; and
.13 critical structural areas and suspect areas, where relevant."
68 Paragraph 5.1.4 is deleted, and paragraphs 5.1.5 and 5.1.6 are renumbered as 5.1.4 and 5.1.5.
69 The following new paragraphs 5.2.1.1 to 5.2.1.3 are added after existing paragraph 5.2.1:
"5.2.1.1 In order to enable the attending surveyors to carry out the survey, provisions for proper and safe access should be agreed between the owner and the Administration.

---CHUNK---

SOURCE: MSC.197(80).pdf
"5.2.1.1 In order to enable the attending surveyors to carry out the survey, provisions for proper and safe access should be agreed between the owner and the Administration.
5.2.1.2 Details of the means of access should be provided in the survey planoing questionoaire.
5.2.1.3 In cases where the provisions of safety and required access are judged by the attending surveyors not to be adequate, the survey of the spaces involved should not proceed."
70 Existing paragraphs 5.2.2 to 5.2.4 are replaced by the following:
"5.2.2 Tanks and spaces should be safe for access. Tanks and spaces should be gas free and properly ventilated. Prior to entering tank, void or enclosed space, it should be verified that the atmosphere in that space is free from hazardous gas and contains sufficient oxygen.
5.2.3 Tanks and spaces should be sufficiently clean and free from water, scale, dirt, oil residues, sediments, etc., to reveal corrosion, deformation, fractures, damages or other structural deterioration as well as the condition of the coating. In particular this applies to areas which are subject to thickness measurements.

---CHUNK---

SOURCE: MSC.197(80).pdf
residues, sediments, etc., to reveal corrosion, deformation, fractures, damages or other structural deterioration as well as the condition of the coating. In particular this applies to areas which are subject to thickness measurements.
5.2.4 Sufficient illumination should be provided to reveal corrosion, deformation, fractures, damages or other structural deterioration as well as the condition of the coating."
71 The following new paragraphs 5.2.5 and 5.2.6 are added:
"5.2.5 The surveyor(s) should always be accompanied by at least one responsible person, assigned by the owner, experienced in tank and enclosed spaces inspection. In addition a backup team of at least two experienced persons should be stationed at the hatch opening of the tank or space that is being surveyed. The back-up team should continuously observe the work in the tank or space and should keep lifesaving and evacuation

---CHUNK---

SOURCE: MSC.197(80).pdf
equipment ready for use.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- III -
5.2.6 A communication system should be arranged between the survey party in the tank or space being examined, the responsible officer on deck and, as the case may be, the navigation bridge. The communication arrangements should be maintained throughout the survey."

72 In existing paragraph 5.3.2, between the fourth and fifth subitems, a new subitem "portable ladders" is inserted.

73 The six subitems in paragraph 5.3.2 are numbered from ".1" to ".6" and the five subitems