MARPOL requirements for port reception facilities

Dr. Nikos Mikelis
Head, Marine Pollution Prevention and Ship Recycling Section
International Maritime Organization

III Hemispheric Conference on Environmental Port Management
Montevideo, 22-24 May 2012

MARPOL REQUIREMENTS FOR PORT RECEPTION FACILITIES (PRFS)

1 HISTORIC REVIEW OF IMO'S WORK ON PRFS

2 WHAT IS AN "ADEQUATE PRF"?

3 OBLIGATIONS OF PARTIES TO REPORT & OF IMO TO DISSEMINATE INFORMATION ON PRFS

4 IMO'S ACTION PLAN TO TACKLE INADEQUACY OF PRFS

1 HISTORIC REVIEW OF IMO'S WORK ON PRFS

MARPOL (International Convention for the Prevention of Pollution from Ships) was established, amongst other things, to prevent the pollution of the marine environment by discharges into the sea of harmful substances, or effluents containing such substances, from ships.

The term “harmful substance” is defined in Article 2 of the Convention as meaning “*any substance which, if introduced into the sea, is liable to create hazards to human health, to harm living resources and marine life, to damage amenities or to interfere with other legitimate uses of the sea, and includes any substance subject to control by the present Convention*”.

The six technical Annexes of MARPOL contain detailed regulations with respect to the handling on board ships and in respect to any discharge into the sea or release into the atmosphere of six main groups of harmful substances:

Petroleum in any form (Annex I);

Noxious Liquid Substances (NLS) carried in bulk (Annex II);

Harmful substances carried in packaged form (Annex III);

Sewage (Annex IV);

Garbage (Annex V); and

Air emissions (Annex VI)

MARPOL imposes numerous operational and technical requirements on ships.

MARPOL also imposes one important obligation to the Government of each Party, which is to ensure the provision for reception of ship-generated residues and garbage that cannot be discharged into the sea.

MARPOL requires that residues that cannot be discharged into the sea in accordance with relevant requirements shall be delivered to port reception facilities. It also requires that port States shall ensure the provision of reception facilities which must be *adequate* to meet the needs of ships, *without causing undue delay to them*.

The relevant regulations on port reception facilities are:

Oily residues (from ER or from cargo): Annex I, regulation 38;

NLS residues: Annex II, regulation 18;

Sewage: Annex IV, regulation 12;

Garbage: Annex V, regulation 7; and

Annex VI wastes & residues: regulation 17.

The subject of port reception facilities appeared very early in the agenda of IMO's Marine Environment Protection Committee (MEPC).

MEPC 2, in November 1974, discussed submissions on port reception facilities by USA, Japan, the International Chamber of Shipping (ICS) and the Oil Companies International Marine Forum *(*OCIMF).

MEPC 3, in July 1975, "noted that certain States had reported difficulties in accepting and implementing the 1973 Convention particularly with regard to the provision of the necessary reception facilities..."

MEPC 3 established its first working group on reception facilities to study "the requirements and limitations imposed by the 1973 Convention with respect to the provision of reception facilities for wastes containing oil, noxious chemical substances, sewage and garbage from ships."

MEPC 3 "took note of the report of the working group and agreed that it should be used as a basis for further work during the intersessional period."

In the 37 years since MEPC 3, the subject of port reception facilities has been in the agenda of virtually all meetings of MEPC.

Allegations of inadequacies of port reception facilities continue to exist and no doubt the problem will continue in the future. MEPC therefore maintains its watch and involvement on the subject.

Furthermore, on 1 January 2013 the revised Annex V of MARPOL is expected to enter into force. According to the revised regulations no discharges are permitted anywhere, with the only exceptions being food wastes and non-harmful dry cargo residues. The requirements of the revised Annex V will put further pressure to the need for adequate port reception facilities.

2 WHAT IS AN “ADEQUATE PRF”?

What are “adequate port reception facilities”?

MEPC 42 in 1998 agreed that, to achieve "adequate reception facilities“, the port should have regard to the operational needs of users and provide reception facilities for the type and quantities of waste from ships normally using the port without causing undue delay for the ships.

MEPC 44 in 2000 adopted resolution MEPC.83(44) which stated that adequate facilities can be defined as those which:

- mariners use;
- fully meet the needs of the ships regularly using them;
- do not provide mariners with a disincentive to use them;
- contribute to the improvement of the marine environment;
- meet the needs of the ships normally using the port; and
- allow for the ultimate disposal of ships’ wastes to take place in an environmentally appropriate way.

Also note the following statement which appears in the *Comprehensive Manual on Port Reception Facilities, IMO, 1999 Edition*:

"MARPOL provisions require the government of each party to ensure the provision of adequate port reception facilities without causing undue delay. A port reception facility is anything which can receive shipboard residues and mixtures containing oil, noxious liquids, or garbage. Type and size of the facility depend on the needs of the ships visiting a port.

Where a simple garbage bin may suffice in a small port, another will need larger capacity."

The reporting of alleged inadequacies

MEPC 56 in 2007 issued circular MEPC/Circ.469/Rev.1 providing the latest amended form for reporting alleged inadequacies in reception facilities (the very first format had been issued by MEPC 26 in 1988 as MEPC/Circ.215). The new format has been disseminated widely and can also be downloaded from GISIS (IMO's "Global Integrated Shipping Information System").

According to the reporting procedure, following the completion of a report on inadequacies by a ship's Master, the ship's flag State is required to inform the port State of the alleged inadequacies and also to notify IMO, "for transmission to the Parties concerned".

Port States should respond to reports of inadequacies, informing the reporting flag State and IMO of the outcome of their investigation.

In the last four complete years, IMO Secretariat has received an average of 26 reports of alleged inadequacies per year (over 40% of these being issued by a single flag State).

With over 50,000 ships of more than 500GT in the world fleet, and assuming an average of at least 10 port calls per ship per year, we have more than half a million port calls per year.

If five percent of port calls gave rise to a complaint on inadequacy (25,000) and if only one percent of these complaints resulted in a formal report we should have expected 250 reports annually, which is ten times the number of reports we are receiving.

It would appear that we are only seeing the tip of the iceberg.

3 Obligations of Parties to report & of IMO to disseminate information on PRFs

MARPOL Article 11

Communication of information

(1)The Parties to the Convention undertake to communicate to the Organization:

…….

(d) a list of reception facilities including their location, capacity and available facilities and other characteristics;

and also,

Annex I, reg. 38; Annex II, reg. 18; Annex IV, reg. 12; Annex V, reg. 7; and Annex VI reg. 17 all require each Party to notify the Organization, for transmission to the Parties concerned, of all cases where the facilities provided under these regulations are alleged to be inadequate.

With the aim of promoting the effective implementation of MARPOL, IMO, since 1983, had been collecting and disseminating information on the availability of port facilities for the reception of oily wastes and of noxious liquid substances, through two annual hard copy publications (MEPC.3 and MEPC.4 circular series).

Dissemination through hard-copy circulars however was cumbersome and impractical to the end-users.

In June 2004, IMO's Flag State Implementation Sub-Committee (FSI 13) instructed the Secretariat to develop the Port Reception Facilities Database (PRFD) as a module of GISIS; to allow Member States to update online the PRFD via a log-in password; and also to allow the public to access all the information on a view-only basis.

FSI 13 also agreed that reported cases of alleged inadequacy of reception facilities and the follow-up response by the port States should be posted on the PRFD as publicly available information three months after receipt of the notification.

Furthermore, it was agreed that contact details (and email addresses) of the national Authorities responsible for handling reports on alleged inadequacies should be made publicly available on the IMO PRFD.

At the same time provisions were to be made for the dissemination of information for Annex IV, Annex V and Annex VI port reception facilities.

The PRFD became available to the public on 1 March 2006 (see http://gisis.imo.org/public/). Member States enter data on reception facilities for their own ports directly into the web-based system (see IMO Circular letters No.2683 and No.2892).

IMO Member States continue populating the PRFD, which offers to its users the following main services:

- search for available facilities (by waste category) in a port or a country;
- obtain contact information of the port State or flag State authorities responsible for handling reports on alleged inadequacies of PRF; and
- identify any reported alleged inadequacies for a given port or over a period of time.

Development of data population by category of PRF

Development of data population by category of PRF	05/2006	02/2007	12/2008	03/2010	10/2011	04/2012
Annex I Oily Bilge Water	1128	1163	1377	2811	3088	3146
Annex I Oily Residues (Sludge)	885	928	1181	2511	2955	2996
Annex I Oily Water Washings (Slops)	747	777	908	1545	1832	1892
Annex I Dirty Ballast Water	780	812	893	1514	1757	1782
Annex I Scale and Sludge	608	641	766	1122	1392	1420
Annex I Oily mixtures containing chemicals	589	620	746	993	1281	1315
Annex II	n.a.	783	876	1161	1354	1364
Annex IV	102	130	372	623	894	947
Annex V	140	184	488	3824	3840	3908
Annex VI Ozone depleting substances	10	11	32	68	214	241
Annex VI Exhaust Gas cleaning substances	22	22	48	83	243	246
Flag State contact points	6	10	22	33	48	52
Port State contact points	3	5	16	26	41	43

A brief overview of the Port Reception Facilities module of GISIS




INTERNATIONAL MARITIME ORGANIZATION
GISIS: Port Reception Facilities
Feedback | Log Out
User: nmikelis
Public Home > Port Reception Facilities > Facilities by Port
Browse Facilities in a Port
Search for Facilities
Alleged Inadequacies
Contact Points
Reception Facilities Listing by Port
Please select a country or territory and then a port to view available reception facilities.
Country/territory:
Australia
Port:
Dampier (AUDAM)
Abbot Point (AUABP)
Adelaide (AUADL)
Airlie Island (AU054)
Albany (AUALH)
Ardrossan (AUARD)
Barrow Island (AUBWB)
Bell Bay (AUBEL)
Bing Bong (AUBBG)
Brisbane (AUBNE)
Broome (AUBME)
Bunbury (AUBUY)
Bundaberg (AUBDB)
Burnie (AUBWT)
Cairns (AUCNS)
Cape Cuvier (AUCCU)
Cape Flattery (AUCQP)
Carnarvon (AUCVQ)
Dampier (AUDAM)
Darwin (AUDRW)
Devonport (AUDPO)
Eden (AUQDN)
Esperance (AUEPR)
Fremantle (AUFRE)
Geelong (AUGEX)
Geraldton (AUGET)
Gladstone (AUGLT)
Gove (AUGOV)
Hastings (AUHAS)
Haypoint (AUHPT)
Hobart (AUHBA)
of alleged inadequacies,
d above.
©2011 International Maritime
f Use]

Waste category:

- All Annexes (I, II, IV, V, VI)
  - Oily bilge water (Annex I)
  - Oily residues (sludge) (Annex I)
  - Oily tank washings (slops) (Annex I)
  - Dirty ballast water (Annex I)
  - Scale and sludge from tanker cleaning (Annex I)
  - Oily mixtures containing chemicals (Annex I)
  - Chemical/NLS (Annex II)
  - Sewage (Annex IV)
  - Garbage (Annex V)
  - Ozone-depleting substances (Annex VI)
  - Exhaust gas-cleaning residues (Annex VI)

Updated: **2010-09-03**

⚠ Alleged inadequacies have been reported for facilities at this port.

Port Reception Facilities
Dampier, Australia (AUDAM)

Port details ▲

Facility 1 of 7

Oily residues (sludge) (Annex I)

Service provider

Transpacific-Cleanaway

Address:
Lot 471, King Bay Rd, Dampier, WA 6713

Phone: (08) 9185 6111
Fax:
Telex:

Email:
Web:

Type of facility

- Tr (tank truck/portable tank)

Discharge restriction/limitations

Minimum quantity (m³):	
Maximum quantity (m³):	12
Maximum discharge rate (m³/h):	
Other:	

Availability of the reception facility:	
Minimum prior notice required (hours):	24
Charging system:	
Additional information:	

©2011 International Maritime Organization [Disclaimer | Terms of Use]


INTERNATIONAL MARITIME ORGANIZATION
GISIS: Port Reception Facilities
Feedback | Log Out
User: nmikelis
Public Home > Port Reception Facilities > Facilities b
Browse Facilities in a Port
Search for Facilitie
Waste category:
All Annexes (I, II, IV, V, VI)
Oily bilge water (Annex I)
Oily residues (sludge) (Annex I)
Oily tank washings (slops) (Annex I)
Dirty ballast water (Annex I)
Scale and sludge from tanker cleaning (Annex I)
Oily mixtures containing chemicals (Annex I)
Chemical/NLS (Annex II)
Sewage (Annex IV)
Garbage (Annex V)
Ozone-depleting substances (Annex VI)
Exhaust gas-cleaning residues (Annex VI)
Updated: 2010-09
Alleged ina
Port Recep
Dampier,
Facility 1 of 7
Oily residue
Service provi
Transpacific-Cle
Address:
Lot 471, King B
Phone: (08) 918
Fax:
Telex:
Email:
Web:
Port details ▲
©2011 International Maritime Organization [Disclaim
Port Reception Facilities » Port Details - Microsoft Internet Explorer provided by International Mar...
Port Details
Port: Dampier, Australia (AUDAM)
Port Authority or Harbour Master Details
Name: Dampier Port Authority
Address: King Bay, Burrup Peninsula Dampier WA 6713 VHF Channel 11 and 16
Telephone: (08) 9159 6555
E-mail: info@dpa.wa.gov.au
Web Resources
Port website:
Port Waste Management Plan:
Assessment of Port Reception Facilities
Unavailable.
Close
Done
Local intranet | Protected Mode: Off
100%

Reported Cases of Alleged Inadequacy of Reception Facilities and the Follow-up Response by Port States

Showing 1-5 of 5

Date of occurrence / *Date of receipt of notification by IMO*	Reporting flag State	Port State and port involved	Waste categories for which the inadequacy was alleged	Nature of alleged inadequacies	Date of receipt of port State's response	Summary of the outcome of the port State's investigation
28/04/2011 / *31/05/2011*	Bahamas	Dampier, Australia (AUDAM)	Garbage (Annex V)	No facility available at Whitnell Bay, LPG Jetty, Dampier Port, to dispose of 1.2m3 garbage: ground paper products, rags, glass , metal, bottles, crockery etc.		
03/11/2005 / *09/11/2005*	Antigua and Barbuda	Dampier, Australia (AUDAM)	Garbage (Annex V)	No facility available (but ship had not given prior notification).	16/05/2006	NOTE BY IMO SECRETARIAT: The original report was sent by the master of the reporting vessel directly to the Australian authorities. The master did not notify IMO, and therefore IMO first heard of this case when the port State notified IMO in its reply to the flag State. Data for: "Date of receipt of notification by IMO" and for "Reporting flag State" have been input by IMO. The subject vessel arrived at the Dampier Cargo Wharf, Dampier, Australia, on 3 November 2005 and departed the same day. The report, which was submitted by the master of the vessel to Australia, the port State in this case, claims that there was no reception facility available for 1m3 of plastic and 0.3m3 of food waste. The report also stated that prior notification was not given in accordance with port requirements (paragraph 3.4 of MEPC/Circ.469). The Australian Maritime Safety Authority (AMSA) and Maritime New Zealand jointly publish a booklet containing contact details for all port waste reception facilities in Australia and New Zealand, including those at Dampier. This booklet is distributed through the Association of Australian Ports and Marine Authorities. The contact details for Australian ports are also published on AMSA's website. At Dampier Cargo Wharf the shipping agent is responsible for arranging waste disposal for berthed vessels using these contacts. The procedure is explained in the Dampier Cargo Wharf terminal manual distributed to all local shipping agents. AMSA's investigation has demonstrated that facilities would have been provided had the necessary prior notification been given.
22/10/2005 / *01/11/2005*	Netherlands	Dampier, Australia (AUDAM)	Garbage (Annex V)	Ship charged more money than expected	16/05/2006	NOTE BY IMO SECRETARIAT: The original report was sent by the master of the reporting vessel directly to the Australian authorities. The master did not notify IMO, and therefore IMO first heard of this case when the port State notified IMO in its reply to the flag State. Data for: "Date of receipt of notification by IMO" and for "Reporting flag State" have been input by IMO. The subject vessel arrived at the Dampier Cargo Wharf, in the Port of Dampier, Australia, on 17 October 2005 and departed 22 October 2005. Arrangements at Dampier Cargo Wharf are for a skip to be delivered to the wharf and removed once the vessel has completed waste disposal; however, in this case it appears that after the ship's departure, the skip remained on the wharf longer than necessary and the agent was charged for this extra time. The Australian Maritime Safety Authority (AMSA) wrote to Dampier Port Authority on 4 November 2005 and an AMSA officer visited the Dampier Cargo Wharf on 1 December 2005 to investigate the matter. The shipping agent is responsible for arranging waste disposal from berthed vessels and procedures are detailed in the Dampier Cargo Wharf terminal manual distributed to all shipping agents. In this case AMSA's investigation has demonstrated a lack of effective communication between the agent and the waste service contractor resulting in the delay in the contractor retrieving the skip. AMSA has emphasised the need to ensure the proper procedures are followed in a more timely manner in future.
15/10/2005 / *16/10/2005*	Panama	Dampier, Australia (AUDAM)	Garbage (Annex V)	No facility available at Parkar Point, Port of Dampier.	16/05/2006	NOTE BY IMO SECRETARIAT: The original report was sent by the master of the reporting vessel directly to the Australian authorities. The master did not notify IMO, and therefore IMO first heard of this case when the port State notified IMO in its reply to the flag State. Data for: "Date of receipt of notification by IMO" and for "Reporting flag State" have been input by IMO. The subject vessel arrived at Parkar Point, in the Port of Dampier, Australia, on 15 October 2005 and departed 16 October 2005. The Australian Maritime Safety Authority (AMSA) wrote to Dampier Port Authority on 25 October 2005 in order to investigate this matter. AMSA actively encourages all Australian port operators to recognise the importance of providing waste reception facilities. Parkar Point is a private berth operated by Pilbara Iron and supervised by Dampier Port Authority.

Procedure for Reporting Alleged Inadequacies of Reception Facilities

Reporting format

Use this format to report alleged inadequacies of port reception facilities to the Administration of the flag State, and, if possible, to the Authorities of the port State.

Click below to save the reporting form to your computer for completion.

File: MEPC.1-Circ.469-Rev.1.doc
Size: 79 KB
Description: Form for reporting cases of alleged inadequacy of reception facilities

File: MEPC.1-Circ.469-R...rench).doc
Size: 90 KB
Description: Formulaire révisé de notification de l'inadéquation présumée des installations de réception portuaires

File: MEPC.1-Circ.469-R...anish).doc
Size: 82 KB
Description: Nuevo formulario refundido para notificar supuestas deficiencias de las instalaciones portuarias de recepción

Contact points

For contact details of the national Authorities responsible for handling reports on alleged inadequacy of reception facilities, please check the section on Contact Points.

ORGANIZACIÓN MARÍTIMA INTERNACIONAL
4 ALBERT EMBANKMENT
LONDRES SE1 7SR

Teléfono: 0207 735 7611
Fax: 0207 587 3210

OMI

S

Ref.: T5/1.01

MEPC.1/Circ.469/Rev.1
13 julio 2007

NUEVO FORMULARIO REFUNDIDO PARA NOTIFICAR SUPUESTAS DEFICIENCIAS DE LAS INSTALACIONES PORTUARIAS DE RECEPCION

1 La capacidad de los buques para cumplir las prescripciones sobre descargas del Convenio MARPOL depende en gran parte de la disponibilidad de instalaciones de recepción adecuadas en los puertos, particularmente en las "zonas especiales". La falta de instalaciones de recepción en muchos puertos de todo el mundo supone una amenaza grave de contaminación para el medio marino.

2 Conforme al Convenio MARPOL, los Gobiernos de las Partes se comprometen a:

.1 garantizar que las instalaciones de recepción sean adecuadas para atender a las necesidades de los buques que las utilicen sin que éstos tengan que sufrir demoras innecesarias; y

.2 notificar a la OMI cualquier caso de supuestas deficiencias en las instalaciones para transmitir esa información a las Partes interesadas.

3 Habida cuenta de que la posibilidad de mejorar las instalaciones de recepción depende, por lo menos en parte, de que se reciba información suficiente sobre las supuestas deficiencias, y con objeto de facilitar un formulario normalizado para el proceso de comunicación, en su 26º periodo de sesiones (septiembre de 1988), el Comité de Protección del Medio Marino aprobó el formulario refundido para notificar supuestas deficiencias de las instalaciones portuarias de recepción de desechos oleosos (Anexo I del MARPOL), sustancias nocivas líquidas (Anexo II del MARPOL) y basuras (Anexo V del MARPOL) mediante la circular MEPC/Circ.215. Dicho formulario fue revisado posteriormente por el MEPC 42 (noviembre de 1998) a fin de hacerlo más fácil de usar y se distribuyó por medio de la circular MEPC/Circ.349.

4 Tras haber examinado la recomendación formulada por el Subcomité de Implantación por el Estado de Abanderamiento en su 13º periodo de sesiones, el Comité de Protección del Medio Marino, en su 53º periodo de sesiones (julio de 2005), aprobó el nuevo formulario refundido para notificar supuestas deficiencias de las instalaciones portuarias de recepción, que figura en el anexo, de modo que se incluyan referencias a las aguas sucias (Anexo IV del MARPOL), las sustancias que agotan la capa de ozono y los residuos del sistema de limpieza de los gases de escape (Anexo VI del MARPOL); dicho formulario se distribuyó mediante la circular MEPC/Circ.469.

5 En su 56º periodo de sesiones (julio de 2007), el Comité de Protección del Medio Marino aprobó la recomendación hecha por el Subcomité de Implantación por el Estado de Abanderamiento en su 15º periodo de sesiones de que volviera a publicarse la circular MEPC/Circ.469 mediante una circular MEPC/Circ.469/Rev.1, incluyendo los cambios resultantes de la entrada en vigor, el 1 de enero de 2007, del Anexo II revisado del MARPOL y de la introducción de la nuevas categorías X, Y y Z de sustancias nocivas líquidas.

6 Se ruega a los Estados de abanderamiento que:

.1 distribuyan este nuevo formulario a los buques e insten a los capitanes a que lo utilicen para notificar las supuestas deficiencias de las instalaciones portuarias de recepción a la Administración del Estado de abanderamiento y, de ser posible, a las autoridades del Estado rector del puerto;

.2 notifiquen a la OMI cualquier caso de supuestas deficiencias en las instalaciones para transmitir esa información a las Partes interesadas; y

.3 informen al Estado rector del puerto de las supuestas deficiencias.

Para notificar las supuestas deficiencias se enviará el formulario cumplimentado, junto con una copia del informe del capitán y cualquier documento justificativo, a la mayor brevedad posible.

7 Los Estados rectores de puertos deberían adoptar las medidas necesarias para examinar los informes sobre deficiencias y responder de manera eficaz a los mismos, e informar de los resultados de sus investigaciones a la OMI y al Estado de abanderamiento que realiza la notificación.

8 Se debería alentar a las compañías navieras a que incorporen las disposiciones de la presente circular en sus procedimientos para las operaciones de a bordo prescritos de conformidad con la sección 7 del Código IGS.

9 Se invita a los Gobiernos Miembros a que pongan esta circular en conocimiento de todas las partes interesadas.

10 La presente circular sustituye a la circular MEPC/Circ.469.

***

ANEXO

NUEVO FORMULARIO REFUNDIDO PARA NOTIFICAR SUPUESTAS DEFICIENCIAS DE LAS INSTALACIONES PORTUARIAS DE RECEPCIÓN[1]

El capitán de un buque que se enfrente con dificultades para descargar desechos en instalaciones de recepción deberá presentar la información que se pide más abajo, acompañada de cualquier documento justificativo, a la Administración del Estado de abanderamiento y, de ser posible, a las autoridades competentes del Estado rector del puerto. El Estado de abanderamiento comunicará el suceso al Estado rector del puerto. El Estado rector del puerto debería examinar el informe y responder oportunamente informando de los resultados de su investigación a la OMI y al Estado de abanderamiento que realiza la notificación.

1 PORMENORES DEL BUQUE

1.1 Nombre del buque: _____
1.2 Propietario o armador: _____
1.3 Número o letras distintivos: _____
1.4 Número IMO[2]: _____
1.5 Arqueo bruto: _____
1.6 Puerto de matrícula: _____
1.7 Estado de abanderamiento[3]: _____
1.8 Tipo de buque:
☐ Petrolero ☐ Buque tanque químiquero ☐ Granelero
☐ Otro buque de carga ☐ Buque de pasaje ☐ Otro (especifíquese) _____

2 PORMENORES DEL PUERTO

2.1 País: _____
2.2 Nombre del puerto o de la zona: _____
2.3 Nombre de la localidad/terminal: _____
(por ejemplo, atraque/terminal/pantalán)
2.4 Nombre de la compañía encargada de la instalación de recepción (si procede): _____
2.5 Tipo de operación portuaria:
☐ Puerto de descarga ☐ Puerto de carga ☐ Astillero
☐ Otros (especifíquense) _____
2.6 Fecha de llegada: __/__/____(día/mes/año)
2.7 Fecha del suceso: __/__/____(día/mes/año)
2.8 Fecha de salida: __/__/____(día/mes/año)

[1] El presente formulario se aprobó en el 53º período de sesiones del Comité de Protección del Medio Marino, celebrado en julio de 2005.

[2] De conformidad con el sistema de asignación de un número de la OMI a los buques para su identificación adoptado por la Organización mediante la resolución A.600(15) de la Asamblea.

[3] El nombre del Estado cuyo pabellón tiene derecho a enarbolar el buque.

3 DEFICIENCIAS DE LAS INSTALACIONES

3.1 Tipo y cantidad de desechos para los que fue deficiente la instalación portuaria de recepción y naturaleza de los problemas a los que se hizo frente.

Tipo de desecho	Cantidad para descarga (m^3)	Cantidad no aceptada (m^3)	**Problemas experimentados** Señálense los problemas experimentados con una o varias de estas letras, según proceda. A No hay instalaciones disponibles B Demora indebida C El uso de la instalación no fue viable D Lugar inconveniente E El buque tuvo que cambiar de atracadero, lo que ocasionó demoras y costes adicionales F Tarifas excesivas por el uso de las instalaciones G Otros (indíquese en el párrafo 3.2)
Desechos relacionados con el Anexo I del MARPOL Tipo de desecho oleoso:			
Agua de sentina			
Residuos oleosos (fango)			
Aguas oleosas procedentes del lavado de tanques (residuos)			
Agua de lastre sucia			
Depósitos y fangos procedentes de la limpieza de tanques			
Otros (especifíquese .....)			
Desechos relacionados con el Anexo II del MARPOL Categoría de residuo de sustancia nociva líquida[4]/mezcla de agua para descarga en la instalación de recepción procedente del lavado de tanques:			
Sustancia de categoría X			
Sustancia de categoría Y			
Sustancia de categoría Z			
Desechos relacionados con el Anexo IV del MARPOL Aguas sucias			
Desechos relacionados con el Anexo V del MARPOL Tipo de basura:			
Plástico			
Tablas de estiba, soleras y materiales de embalaje flotantes			
Productos triturados de papel, trapos, vidrio, metales, botellas, loza, etc.			
Residuos de la carga, productos de papel, trapos, vidrio, metales, botellas, loza, etc.			
Restos de alimentos			
Cenizas de incineradores			
Otros (especifíquese .....)			
Desechos relacionados con el Anexo VI del MARPOL			
Sustancias que agotan la capa de ozono y equipo que contenga tales sustancias			
Residuos de la limpieza de los gases de escape			

[4] Indíquese en el párrafo 3.2 el nombre de expedición correcto de la sustancia nociva líquida en cuestión y si dicha sustancia está clasificada como "a punto de solidificarse" o "de viscosidad elevada", de conformidad con la regla 1, párrafos 15.1 y 17.1, respectivamente, del Anexo II del Convenio MARPOL.


INTERNATIONAL MARITIME ORGANIZATION
GISIS: Port Reception Facilities
Feedback | Log Out
User: nmikelis
Public Home > Port Reception Facilities > Contact Points
Browse Facilities in a Port
Search for Facilities
Alleged Inadequacies
Contact Points
Contact Points
Please select below to view details of contact points of the national authorities responsible for handling reports on alleged inadequacy of reception facilities.
Note: Only authorities for which contact details are available are listed below.
Flag or port Administration:
-- Please select --
-- Please select --
Antigua and Barbuda
Australia
Bahamas
Belgium
Brazil
Cayman Islands (United Kingdom)
Chile
China
Colombia
Cuba
Cyprus
Denmark
DIS (Denmark)
Dominica
Ecuador
Finland
France
Greece
Guatemala
Honduras
Hong Kong, China
Iran (Islamic Republic of)
Ireland
Jamaica
Kiribati
Latvia
Lithuania
Maldives
Marshall Islands
©2011 International Maritime Organization [

Updated: **2010-03-18**

Contact Points

Please select below to view details of contact points of the national authorities responsible for handling reports on alleged inadequacy of reception facilities.

Note: Only authorities for which contact details are available are listed below.

Flag or port Administration: Colombia

Contact point of the authorities of the flag State

Name:	Contralmirante Leonardo Santamaría Gaitán
Organization:	Dirección General Marítima de Colombia
Address:	Cra 54 No. 26-50 CAN. Bogotá, Colombia
Telephone:	+(571) 2200490
Telex:	
Fax:	+(571) 2225152
Email:	dimar@dimar.mil.co
Website:	http://www.dimar.mil.co

Contact point of the authorities of the port State

Name:	Carmen Antonia Martin Bacci
Organization:	Superintendencia de Puertos y Transporte
Address:	Calle 13 No. 18-24 "Estación de La Sabana", Bogotá, Colombia.
Telephone:	+(571) 3526700
Telex:	
Fax:	+(571) 3526700
Email:	joseolaya@supertransporte.gov.co
Website:	http://www.supertransporte.gov.co

©2011 International Maritime Organization [Disclaimer | Terms of Use]

4 IMO'S ACTION PLAN TO TACKLE INADEQUACY OF PRFS

Action Plan to tackle the inadequacy of port reception facilities

In a renewed effort to tackle the problem of inadequacies of port reception facilities worldwide, and this way to contribute to the effective implementation of MARPOL, MEPC 55 in 2006 approved *"the Action Plan for tackling the alleged inadequacy of port reception facilities"*. The Plan was developed by IMO's FSI Sub-Committee on the basis of input from the Industry "Port Reception Facilities Forum".

As instructed by MEPC, FSI 15 commenced work on the Action Plan in 2007; correspondence groups continued work in three intersessional periods; and FSI 18 completed its work in July 2010. Also MEPC 63 in March 2012 completed work on the last item of the Action Plan.

Ten issues considered as challenges for the Action Plan

Garbage segregation and waste receptacle identification;

The establishment of a standardized methodology to facilitate the smooth delivery of garbage to the PRF;

To consider whether new technical problems arise from new ship designs, and from new waste management technologies and equipment;

Assessment of the type and amount of wastes generated on board ships, in order to calculate ships' needs for delivery of wastes ashore;

Uniform methodology for the estimation of the required capacity of a PRF;

Waste management downstream from PRF in developing countries;

Regional arrangements for PRF and guidelines;

Revision of the IMO Comprehensive Manual on Port Reception Facilities;

Development of a guide to good practice for port reception facilities; and

Development of assistance and training programme for PRFs to be delivered at national or regional levels.

The Plan that was devised to address the key challenges contained 13 work items grouped in the following six categories, all of which are generally applicable to some or all of the categories of wastes and residues covered by MARPOL and to the requirement for adequate PRFs:

1. standardized reporting
2. information on port reception facilities
3. equipment technology
4. types and amount of wastes
5. regulatory matters
6. technical cooperation and assistance

Outcome of the Action Plan (1/2)

MEPC 55 agreed to recognize regional arrangements. Amendments to Annexes I, II, IV and V of MARPOL were adopted by MEPC 63 in 2012 by resolution MEPC.216(63). The arrangements are applicable only to Small Island Developing States (SIDS). They are expected to enter into force on 1 August 2013 . MEPC 63 also adopted resolution MEPC.221(63), *2012 Guidelines for the development of a regional reception facilities plan*.

MEPC 58 in 2008 approved the “Standard format for the advance notification form for waste delivery to port reception facilities” and issued it as MEPC.1/Circ.644

Also, MEPC 58 in 2008 approved the “Standard format for the waste delivery receipt following a ship’s use of port reception facilities” and issued it as MEPC.1/Circ.645

MEPC 59 in 2009 approved the “Guide to Good Practice for Port Reception Facilities” and issued it as MEPC.1/Circ.671

Outcome of the Action Plan (2/2)

MEPC 61 agreed to the proposals for the revision of the *IMO Comprehensive Manual on Port Reception Facilities, IMO, 1999* under the Integrated Technical Co-operation Programme.

MEPC 61 in 2010 also approved the Plan of Assistance and Training on Port Reception Facilities for Developing Countries and endorsed it as a priority theme for the ITCP biennium 2012-2013. Two major events are planned.

ISO 21070, Management and handling of shipboard garbage, published in 2011, addressed the requirements of several work items including the segregation of garbage on-board ships. Members of the FSI correspondence group contributed to the work of ISO. ISO further proposed to develop a standard for the receipt in ports of garbage that has been segregated on-board.

Finally, ISO, with input from individual delegates of FSI, is contributing a new standard for the design, construction, equipping, management and operation of PRFs. *ISO/DIS 16304, Arrangement and management of port reception facilities*.

thank you for your attention

Any views expressed in this presentation are those of its author