rformance standards for float-free release
and activation arrangements for emergency radio equipment .
. 14 Resolution A.699(17): System performance standard for the
promulgation and co-ordination of maritime safety information using
high-frequency narrow-band direct-printing .
. 15 Resolution A.700(17): Performance standards for narrow-band
direct-printing telegraph equipment for the reception of
navigational and meteorological warnings and urgent information to
ships (MSI) by HF.
W/1687n/pp/EWP
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY
FOR HIGH SPEED CRAFT MSC 62/23/Add.2
ANNEX 18
Page 144
14.14
14.14.1
14.14.2
14.14.3
14.14.4
14.14.5
14 .14.6
14.14.1
14.14.8
Maint e nance requ irements
Equipment should be so designed that the main units can be replaced
readily without elaborate recalibration or readjustment.
Where applicable, equipment should be so constructed and installed
that it is readily accessible for inspection and on-board
maintenance purposes.
Adequate information should be provided to enable the equipment
-
Where applicable, equipment should be so constructed and installed
that it is readily accessible for inspection and on-board
maintenance purposes.
Adequate information should be provided to enable the equipment
to be properly operated and maintained, taking into account the
recommendations of the Organization*.
Adequate tools and spares should be provided to enable equipment to
be maintained .
The Administration should ensure that radio equipment required by
this chapter is maintained to provide the availability of the
functional requirements specified in 14.4 and to meet the

recommended performance standards of such equipment.

On crafts engaged on voyages in sea areas Al and A2, the availability should be ensured by using such methods as duplication of equipment, shore-based maintenance or at-sea electronic maintenance capability, or a combinat5 .on of these, as may be approved by the Administration.

On crafts engaged on voyages in sea areas A3 and A4, the availability should be ensured by using a combination of at least two methods such as duplication of equipment, shore-based maintenance or at-sea electronic maintenance capability, as may

-

On crafts engaged on voyages in sea areas A3 and A4, the availability should be ensured by using a combination of at least two methods such as duplication of equipment, shore-based maintenance or at-sea electronic maintenance capability, as may be approved by the Administration, taking into account the I'ecommendations of the Organization"""".

However, crafts operating solely between ports where adequate facilities for shore-based maintenance of the radio installations are available and provided no journey between two such ports exceeds six hours, then the Administration may exempt such crafts from the requirement to use at least two maintenance methods. For such crafts at least one maintenance method should be used.

* Refer to the Recommendation on general requirements for shipborne radio equipment forming part of the global maritime distress and safety system and for electronic navigational aids , adopted by the Organization by resolution A.694(11).

** Administrations should take account of the Recommendations on radio maintenance guidelines for the Global Maritime Distress and Safety System

-

and for electronic navigational aids , adopted by the Organization by resolution A.694(11).

** Administrations should take account of the Recommendations on radio maintenance guidelines for the Global Maritime Distress and Safety System (GMDSS) related to sea areas A3 and A4 , a.dopted by the Organization by resolution A.102(11)

W/1681n/pp/EWP

RESOLUTION MSC.36(63)

(adopted on 20 May 1994)

ADOPTION OF THE INTERNATIONAL CODE OF SAFETY FOR HIGH SPEED CRAFT 14.14.9

14.15

14.16

MSC 62/23/Add.2

ANNEX 18

While all reasonable steps should be taken to maintain the equipment in efficient working order to ensure compliance with all the functional requirements specified in 14.4, malfunction of the equipment for providing the general radiocommunications, required by 14.4.8, should not be considered as making a craft unseaworthy or as a reason for delaying the craft in ports where repair facilities are not readily available, provided the craft is capable of performing all distress and safety functions.

Radio pers~

Every craft should carry personnel qualified for distress and safety radiocommunication purposes to the satisfaction of the

-

not readily available, provided the craft is capab