# Ex.No.4.2 Cut sections of solids

## Aim:

To create the solid model from given drawing and section the solid model.


## Requirements:

1. Autodesk fusion 360
2. Windows 10
3. 16 GB of RAM (integrated graphics recommend 1 GB or more)
4. 2.5 Mbps or faster download; 500 Kbps or faster upload


## Procedure:

1. Open new file and then select sketch icon.
2. Select the front view for sketching.
3. Draw a vertical line of length 1.501mm.
4. Draw a circle of radius 2.113mm.
5. Use the coincident tool to join the circle and the line.
6. Draw a circle of radius 2.261mm from same centre.
7. Draw a horizontal line of length 1.366mm.


8. At distance of 0.123mm, draw a line parallel to the y axis.





9. Draw a line joining end of horizontal line and vertical line at a height of 0.148mm.



10. Trim the excess.





11. After finishing the sketch use finish sketch option to finalize the sketch.
12. Use revolve option to convert 2D to 3D.




13. After finishing the sketch switch to drawing mode to plot the sketch in ISO standard.

# Output:




# Result:

Thus, the cut section for solid model is created.