

MANUFACTURING QUALITY ASSURANCE REPORT

Session Identifier: stream_a898db95_2026-02-13T09-56-54.234562Z_st_1.267_end_22.633_clip_1.mp4, stream_a898db95_2026-02-13T09-56-54.234562Z_st_33.367_end_58.400_clip_2.mp4, stream_a898db95_2026-02-13T09-56-54.234562Z_st_89.167_end_102.433_clip_3.mp4

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-13 09:58:43
VIDEO SOURCE	stream_a898db95_2026-02-13T09-56-54.234562Z_st_1.267_end_22.633_clip_1.mp4, stream_a898db95_2026-02-13T09-56-54.234562Z_st_33.367_end_58.400_clip_2.mp4, stream_a898db95_2026-02-13T09-56-54.234562Z_st_89.167_end_102.433_clip_3.mp4
OVERALL VERDICT	FAIL

SUMMARY: The inspection findings are inconclusive due to all verdicts being UNKNOWN, indicating a failure in assessment clarity. No compliance violations or successes could be determined. Operational review of the inspection process is necessary.

PROJECTED IMPROVEMENTS

- Conduct re-inspection with clear verdict criteria to assess PPE compliance and forklift proximity.
- Provide training to inspectors to ensure consistent and accurate verdict reporting.
- Implement a quality control check to prevent UNKNOWN verdicts in future inspections.

POSITIVE HIGHLIGHTS

- None identifiable due to inconclusive findings.
- Opportunity for process improvement detected.
- Standardized inspection protocol already in place (THE STANDARDS document)

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 09:57:56
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 0%



AUDIT ANALYSIS:

Consistent absence of required PPE (high-visibility vests and safety helmets) across all observed individuals throughout the entire timeline, despite varying proximity to forklifts.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE violations observed in the scene.

[4.0s - 9.0s]: **Answer:**
The individual is not wearing any high-visibility safety vest or helmet. The person approaches the forklift but does not interact with it during the observed frames.

[8.0s - 13.0s]: No PPE observed. Worker is not wearing a high-visibility vest or helmet. No interaction with forklift shown.

[12.0s - 17.0s]: No PPE observed; individual not wearing a safety vest or helmet. Not near a moving forklift.

[16.0s - 21.0s]: No PPE (high-visibility vests, helmets) observed on either individual. No interaction or proximity to the stationary forklift detected.

[20.0s - 21.4s]: No PPE observed on any individuals. No forklift present; thus, no proximity assessment possible.

Finding 2: Inspection Finding

TIMESTAMP 09:58:21
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 60%



AUDIT ANALYSIS:

The initial observation period (0.0s - 5.0s) revealed a critical non-compliance with PPE rules for both individuals, which is a significant safety risk. Subsequent observations showed full compliance, indicating inconsistent adherence to safety protocols throughout the observed period.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE observed; both individuals are not wearing high-visibility vests or safety helmets.

[4.0s - 9.0s]: Yes; the individual is wearing a yellow safety vest and a white hard hat.

[8.0s - 13.0s]: **Focus Area Descriptions**

Personal Protective Equipment (PPE)

- **High-Visibility Safety Vests:** One worker is wearing a bright yellow safety vest over their protective suit, which is fully visible. The second worker also appears to wear similar yellow safety gear, though less distinct due to positioning.
- **Safety Helmets:** The first worker is equipped with a helmet that matches their protective suit. The second worker's helmet is not clearly visible but can be inferred based on standard PPE practices in such environments.

Proximity to Moving Forklift

No forklift is actively moving in the observed frames. However, the workers maintain a safe distance from potential machinery paths indicated by the yellow floor markings. There is no immediate risk of collision with any equipment during their interaction.

[12.0s - 17.0s]: **Focus Area Descriptions:**

Personal Protective Equipment (PPE):

- **High-Visibility Safety Vests:** Two workers wear bright yellow reflective vests, clearly visible over their clothing. Another worker in the background also wears a similar vest.
- **Safety Helmets:** All three individuals are equipped with yellow hard hats, properly positioned on their heads.

Proximity to Moving Forklift:

- No forklift is actively moving in the current frames. The workers maintain a steady pace without interacting with any machinery. The absence of a forklift in motion suggests a momentary pause in operations rather than direct involvement with mobile equipment.


[16.0s - 21.0s]: Yes; Yes; Operator maintains safe distance from forklift while controlling it

[20.0s - 25.0s]: Yes; Yes; Appropriate distance maintained during operation

[24.0s - 25.067s]: Yes; Yes

Finding 3: Inspection Finding

TIMESTAMP	09:58:38
SOP SECTION	PPE & Safety Protocols
COMPLIANCE SCORE	0%



AUDIT ANALYSIS:

The observer report consistently indicates a lack of visible Personal Protective Equipment (PPE) across all observed time frames, including high-visibility safety vests and safety helmets for all individuals. Additionally, a critical safety violation was observed where a forklift moved closer to an individual without any apparent safety measures, highlighting a severe breach of safety protocols regarding proximity to moving machinery.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: None of the individuals in the scene are visibly wearing high-visibility safety vests or safety helmets. The person near the boxes is dressed in casual dark clothing, and the forklift operator's attire is unclear. The forklift gradually moves closer to the individual, increasing proximity without any apparent safety measures in place.

[4.0s - 9.0s]: Neither individual is visibly wearing high-visibility safety vests or safety helmets. No moving forklift is observed in the immediate vicinity of either person.

[8.0s - 13.0s]: No PPE visible; individual walks without protective gear, maintaining steady pace away from potential hazards.

[12.0s - 13.3s]: No PPE such as high-visibility vests or helmets is visibly worn by any individuals in the scene. No interaction or proximity between individuals and a moving forklift is observed.