

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-13 12:14:51
VIDEO SOURCE	stream_c2b70562_2026-02-13T12-13-09.969723Z_st_1.267_end_22.633_clip_1.mp4, stream_c2b70562_2026-02-13T12-13-09.969723Z_st_33.367_end_58.400_clip_2.mp4, stream_c2b70562_2026-02-13T12-13-09.969723Z_st_89.167_end_102.433_clip_3.mp4
OVERALL VERDICT	FAIL

SUMMARY: The inspection revealed a significant lack of compliance with PPE standards across multiple events, with persistent failures in wearing high-visibility vests and safety helmets, and unsafe proximity to forklifts in critical situations. Only one event partially met standards, but still had notable violations. Overall, the failures outweigh the limited successes.

PROJECTED IMPROVEMENTS

- Mandatory enforcement of high-visibility vests and safety helmets for all personnel in the work area at all times.
- Implementation of regular safety checks to ensure compliance, especially during forklift operations.
- Training for all workers on the importance of PPE and safe distancing from moving equipment like forklifts.

POSITIVE HIGHLIGHTS

- Event 2 showed improvement in PPE compliance over time, indicating responsiveness to safety protocols.
- In Event 1, some frames demonstrated compliance or non-applicable scenarios, showing occasional adherence to standards.
- No forklift interaction violations were noted in Event 3, suggesting some awareness of safety around heavy equipment.

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 12:14:07
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 20%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: Yes, two people are wearing high-visibility safety vests and safety helmets. No forklift is visible in motion.

[4.0s - 9.0s]: Not applicable

[8.0s - 13.0s]: **Final Answer:**

The worker operates the forklift without visible PPE (vest/helmet), while the stationary individual lacks PPE as well. No violations detected.

[12.0s - 17.0s]: No PPE violations detected

[16.0s - 21.0s]: No PPE violations observed. The individual is not wearing a high-visibility vest or safety helmet. They maintain a safe distance from any potential moving machinery or vehicles.

[20.0s - 21.4s]: No PPE-related violations were detected in the video. No workers were observed wearing high-visibility vests or safety helmets. The forklift was not present in the frames, so proximity to it could not be assessed.

Finding 2: Inspection Finding

TIMESTAMP 12:14:28
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 60%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: None of the individuals in the scene are visibly wearing high-visibility safety vests or safety helmets. Both individuals appear to be in casual or work-appropriate attire without protective gear. The proximity to any potential moving forklift cannot be assessed as no forklift is actively moving in the captured frames.

[4.0s - 9.0s]: Yes; Yes; No

[8.0s - 13.0s]: **Focus Area Descriptions**

Personal Protective Equipment (PPE) Compliance

1. High-Visibility Safety Vests:

- Both workers are wearing bright yellow safety vests over their protective suits, indicating compliance with high-visibility requirements.

2. Safety Helmets:

- The worker closer to the loading dock wears a white hard hat, meeting safety standards for head protection.
- The second worker lacks a helmet, creating a non-compliance issue.

[12.0s - 17.0s]: Yes; Yes; Yes

[16.0s - 21.0s]: Yes; Yes; Yes

[20.0s - 25.0s]: Yes; both wear yellow safety vests and white hard hats, and maintain a safe distance from the forklift.

[24.0s - 25.067s]: No PPE-related details can be observed for the person because they are not present in the given frames.

Finding 3: Inspection Finding

TIMESTAMP 12:14:44
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE **0%**



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: None of the individuals in the scene are visibly wearing high-visibility safety vests or safety helmets. The person appears to be engaged in their task without any apparent use of PPE. The proximity to the forklift cannot be determined as there is no visible forklift in the frame.

[4.0s - 9.0s]: Not wearing PPE

[8.0s - 13.0s]: No PPE violations detected in the observed frames. The individual is not wearing a high-visibility vest or helmet, and there is no interaction with a forklift or other machinery.

[12.0s - 13.3s]: No PPE-related issues were observed. The worker in the red shirt was present but not interacting with any moving machinery or vehicles. No forklift or other moving equipment was active in the scene.