

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-17 11:56:33
VIDEO SOURCE	stream_205d7fb7_2026-02-17T11-55-08.664652Z_st_0.000_end_17.940_clip_1.mp4
OVERALL VERDICT	FAIL

SUMMARY: The inspection revealed a critical failure in safety compliance, with no Personal Protective Equipment (PPE) observed during the entire period, violating all specified standards. This poses a significant risk to individual safety. Immediate corrective action is required.

PROJECTED IMPROVEMENTS

- Ensure all individuals in the scene wear high-visibility safety vests at all times.
- Mandate the use of safety helmets for all personnel in areas where forklifts are operational.
- Establish and enforce a safe distance protocol for individuals around moving forklifts.

POSITIVE HIGHLIGHTS

- None observed during this inspection due to the complete lack of PPE compliance.
- Opportunity for comprehensive safety training was identified.
- Potential for immediate improvement through policy enforcement.

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 11:56:28
SOP SECTION Safety Protocols
COMPLIANCE SCORE 0%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 29.933s]: No PPE-related items were observed.