

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-17 12:04:24
VIDEO SOURCE	stream_205d7fb7_2026-02-17T11-55-08.664652Z_st_0.000_end_17.940_clip_1.mp4
OVERALL VERDICT	FAIL

SUMMARY: The inspection revealed a critical failure in PPE compliance and safe distancing from hazardous areas, posing significant safety risks. Non-compliance was observed in all assessed PPE categories (high-visibility vests and safety helmets) and proximity to hazards. Immediate corrective action is required.

PROJECTED IMPROVEMENTS

- **Mandatory PPE Protocol Enforcement:** Implement strict protocols ensuring all workers wear high-visibility vests and safety helmets at all times in the work area.
- **Hazard Distance Training:** Provide training on maintaining safe distances from hazardous equipment like conveyor belts and forklifts.
- **Regular Compliance Checks:** Schedule frequent, unannounced inspections to monitor and enforce PPE and safety distance compliance.

POSITIVE HIGHLIGHTS

- **None observed in the given inspection findings related to PPE and safety distance compliance.**
- **Opportunity for Improvement:** The identification of critical failures highlights an opportunity for significant safety protocol enhancements.
- **Potential for Future Compliance:** With corrective actions, the site can achieve full compliance in future inspections.

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 12:04:18
SOP SECTION Safety Protocols
COMPLIANCE SCORE 0%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 29.933s]: No PPE observed; single worker without safety gear near conveyor belt.