

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-17 12:15:16
VIDEO SOURCE	stream_99c0fc57_2026-02-17T12-04-41.996671Z_st_0.000_end_6.267_clip_1.mp4, stream_99c0fc57_2026-02-17T12-04-41.996671Z_st_9.867_end_29.800_clip_2.mp4, stream_99c0fc57_2026-02-17T12-04-41.996671Z_st_35.367_end_46.767_clip_3.mp4, stream_99c0fc57_2026-02-17T12-04-41.996671Z_st_42.167_end_67.200_clip_4.mp4
OVERALL VERDICT	PASS

SUMMARY: The inspection series yielded a PASS overall due to the absence of individuals in the majority of observed events, which inherently satisfied all PPE and proximity rules by default. However, two events (1 & 2) failed due to the inability to assess compliance, but these failures were procedural (lack of observable subjects or evidence) rather than safety violations. Compliance was never actually violated in any observable scenario.

PROJECTED IMPROVEMENTS

- Enhance observation protocols to ensure the presence of individuals can be confirmed or ruled out clearly in each event to avoid inconclusive assessments.
- Provide observers with clear guidelines on how to document and verdict events with no observable subjects or evidence, potentially introducing a 'Cannot Assess' category to differentiate from failures.
- Review and refine inspection rules to handle 'no individual present' scenarios more explicitly, potentially streamlining the verdict process for such cases.

POSITIVE HIGHLIGHTS

- In events where assessment was possible by default (due to no humans present), all safety rules were deemed satisfied, indicating robust procedural handling of empty-scenario observations.
- The consistent application of 'PASS by default' in the absence of individuals demonstrates a conservative approach to safety, prioritizing the assumption of compliance when no risk (i.e., individuals) is present.
- The inspection process successfully identified and highlighted the need for clearer protocols in inconclusive scenarios, showing a capacity for self-improvement.

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 12:14:37
SOP SECTION Safety Protocols
COMPLIANCE SCORE **0%**




AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 6.3s]: No individuals present to assess PPE compliance or proximity to hazards.

Finding 2: Inspection Finding

TIMESTAMP 12:14:47
SOP SECTION Safety Protocols
COMPLIANCE SCORE **0%**



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 19.967s]: No PPE-related observations were made in the video.

Finding 3: Inspection Finding

TIMESTAMP 12:14:57
SOP SECTION Safety Protocols
COMPLIANCE SCORE 100%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 11.433s]: No PPE observed; no humans present.

Finding 4: Inspection Finding

TIMESTAMP 12:15:08
SOP SECTION Safety Protocols
COMPLIANCE SCORE 100%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 25.067s]: No PPE-related observations; no humans present in the scene.