

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-17 12:24:04
VIDEO SOURCE	stream_bb004dd6_2026-02-17T12-22-22.814418Z_st_1.367_end_22.867_clip_1.mp4, stream_bb004dd6_2026-02-17T12-22-22.814418Z_st_33.367_end_58.400_clip_2.mp4, stream_bb004dd6_2026-02-17T12-22-22.814418Z_st_89.167_end_102.433_clip_3.mp4
OVERALL VERDICT	FAIL

SUMMARY: The inspection revealed significant PPE compliance failures across multiple events, with two out of three events failing due to the absence of high-visibility vests and safety helmets. Only one event demonstrated substantial compliance. Overall, the site failed to meet the required safety standards.

PROJECTED IMPROVEMENTS

- Mandatory enforcement of high-visibility safety vests and safety helmets for all individuals in the scene at all times.
- Regular audits to ensure compliance with PPE rules, focusing on events where forklifts are in operation or anticipated to be present.
- Training or refresher courses for personnel to emphasize the importance and requirements of PPE in the workplace.

POSITIVE HIGHLIGHTS

- Event 2 demonstrated excellent PPE compliance for the majority of the observed time, showcasing the capability to meet safety standards when adhered to.
- In Event 2, appropriate distancing from the moving forklift was maintained, indicating effective understanding of forklift safety protocols.
- The brief non-compliant period in Event 2 did not involve forklift interaction, suggesting some level of risk awareness.

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 12:23:19
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 0%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No high-visibility safety vests or safety helmets are visibly worn by any individuals in the scene.

[4.0s - 9.0s]: Not applicable

[8.0s - 13.0s]: **Final Answer:**
No instances of non-compliance detected. Both individuals are not wearing high-visibility safety vests or safety helmets. No forklift is visible in motion, so proximity violations cannot be assessed.


[12.0s - 17.0s]: No PPE violations observed. The individual is not wearing a safety vest or helmet. They remain outside the immediate proximity of the forklift throughout the sequence.

[16.0s - 21.0s]: No PPE visible; individual is not wearing a high-visibility vest or safety helmet.

[20.0s - 21.533s]: No PPE-related elements were observed in the provided frames.

Finding 2: Inspection Finding

TIMESTAMP 12:23:40
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 95%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE observed; no forklift interaction noted.

[4.0s - 9.0s]: Yes, there is one person with protective equipment (yellow safety vest and helmet). They approach a stationary forklift but do not interact with it during the observed frames.

[8.0s - 13.0s]: **Answer:**

The person wearing a yellow safety vest is located near the loading dock on the left side of the frame. This individual is standing close to the dock and appears to be interacting with something near the ground. Another person, also wearing a yellow safety vest, is positioned slightly further away from the dock, facing towards it. Both individuals are clearly identifiable due to their bright yellow attire, which stands out against the more muted colors

[12.0s - 17.0s]: Yes; Yes; Appropriate distance maintained


[16.0s - 21.0s]: Yes; Both forklift operators wear yellow safety vests and hard hats, maintaining proper distance from the forklift during operation. The third worker in the background also wears safety gear, indicating full PPE compliance.

[20.0s - 25.0s]: Yes; both wear yellow safety vests and white hard hats, and there is no immediate proximity to the forklift.

[24.0s - 25.067s]: No instances of non-compliance were observed.

Finding 3: Inspection Finding

TIMESTAMP 12:23:57
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE **0%**



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE is visible in the scene.

[4.0s - 9.0s]: **Answer:**

The two individuals are not wearing high-visibility safety vests or safety helmets. No forklift is present in the immediate vicinity of the individuals.

[8.0s - 13.0s]: Not applicable

[12.0s - 13.3s]: No, the worker is not wearing any PPE.