

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-17 12:30:05
VIDEO SOURCE	stream_405468e9_2026-02-17T12-27-27.043350Z_st_0.000_end_4.433_clip_1.mp4, stream_405468e9_2026-02-17T12-27-27.043350Z_st_6.167_end_31.200_clip_2.mp4, stream_405468e9_2026-02-17T12-27-27.043350Z_st_28.567_end_53.600_clip_3.mp4, stream_405468e9_2026-02-17T12-27-27.043350Z_st_82.067_end_100.867_clip_4.mp4, stream_405468e9_2026-02-17T12-27-27.043350Z_st_104.267_end_129.300_clip_5.mp4
OVERALL VERDICT	FAIL

SUMMARY: The inspection series revealed inconsistent compliance with PPE standards across events, with a notable failure in ensuring safety helmets and high-visibility vests were worn. Critical violations, including complete absence of required PPE in some events, led to an overall fail. Safety distancing from the forklift was generally well-managed.

PROJECTED IMPROVEMENTS

- Mandatory enforcement of safety helmet wear across all individuals in the work area to prevent critical violations.
- Implementation of a strict high-visibility vest policy, ensuring the correct color specifications are met for all workers.
- Conduct regular audits to ensure 100% PPE compliance, addressing the inconsistency seen across inspected events.

POSITIVE HIGHLIGHTS

- Effective forklift operation and safe distancing practices were consistently observed across all events.
- Event 3 demonstrated perfect compliance with all PPE and safety standards, serving as a model for best practices.
- Some events showed partial compliance, indicating an existing foundation for safety protocols that can be built upon.


SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 12:29:00
SOP SECTION Safety Protocols
COMPLIANCE SCORE 66%




AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 4.467s]: Yes, both workers are wearing orange safety vests. No helmets are visible. The forklift is in motion but maintains a safe distance from the workers.

Finding 2: Inspection Finding

TIMESTAMP 12:29:16
SOP SECTION Safety Protocols
COMPLIANCE SCORE 33%




AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

- [0.0s - 25.067s]: **Answer:**
- 1) Only one person is wearing a safety vest; others lack visible PPE.
 - 2) No helmets are present among the workers.
 - 3) The operator stays safely seated on the forklift, while others maintain a safe distance.

Finding 3: Inspection Finding

TIMESTAMP 12:29:31
SOP SECTION Safety Protocols
COMPLIANCE SCORE 100%




AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 25.067s]: **Answer:**
Yes, both individuals are wearing yellow safety vests and white hard hats, meeting PPE standards. The forklift operators maintain a safe distance from each other and other personnel, avoiding collisions.

Finding 4: Inspection Finding

TIMESTAMP 12:29:45
SOP SECTION Safety Protocols
COMPLIANCE SCORE 0%




AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 18.833s]: No PPE-related violations were observed. The forklift operated without nearby workers, maintaining safe distancing. No safety vests or helmets were visible on any individuals in the scene.

Finding 5: Inspection Finding

TIMESTAMP 12:29:58
SOP SECTION Safety Protocols
COMPLIANCE SCORE 66%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 25.067s]: **Answer:**
The worker operating the forklift is wearing a **red safety vest**, but there is no indication of a **safety helmet** being worn. The **proximity to the forklift** is appropriate, as the operator is seated and actively controlling it. No violations of PPE requirements are evident in the visible details.