

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-27 10:43:12
VIDEO SOURCE	stream_845b9a98_2026-02-27T10-40-50.692218Z_st_20.367_end_45.400_clip_1.mp4, stream_845b9a98_2026-02-27T10-40-50.692218Z_st_56.967_end_82.000_clip_2.mp4, stream_845b9a98_2026-02-27T10-40-50.692218Z_st_85.067_end_110.100_clip_3.mp4, stream_845b9a98_2026-02-27T10-40-50.692218Z_st_115.867_end_128.567_clip_4.mp4
OVERALL VERDICT	FAIL

SUMMARY: The inspection revealed consistent failures in safety helmet compliance across all events, with multiple instances of workers not wearing helmets, posing significant head injury risks. While high-visibility vests were often worn, the absence of helmets and inconsistent PPE adherence led to critical safety violations.

PROJECTED IMPROVEMENTS

- Implement mandatory helmet use enforcement and training to address the recurring absence of safety helmets in all work areas.
- Conduct regular audits and refresher training sessions to ensure consistent PPE compliance, particularly for helmets and high-visibility vests.
- Review and revise safety protocols to include stricter monitoring of PPE adherence, with disciplinary measures for non-compliance.

POSITIVE HIGHLIGHTS

- Workers frequently wore high-visibility vests, demonstrating awareness of visibility safety requirements.
- When present, forklifts were generally operated at safe distances from workers, minimizing collision risks.
- Some segments showed full PPE compliance, indicating that proper adherence is achievable with consistent enforcement.

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 10:42:31
SOP SECTION Safety Protocols
COMPLIANCE SCORE 60%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 7.0s]: Yes

[4.0s - 11.0s]: Yes; both workers wear yellow safety vests. No; neither worker wears a helmet. Not applicable; no forklift is visible in the frames.

[8.0s - 15.0s]: **Focus Area Descriptions**

Personal Protective Equipment (PPE)

- **High-Visibility Safety Vests:** Both workers are visibly wearing yellow safety vests.
- **Safety Helmets:** Both workers are wearing hard hats.

Proximity to Moving Forklift

- No forklift is present in the scene during the observed frames.

[12.0s - 19.0s]: The worker labeled "1" is not present in the frame; therefore, it cannot be determined if they are wearing any PPE. The worker labeled "2" is wearing a yellow high-visibility vest, which indicates adherence to safety protocols for visibility in an industrial setting. No helmets are visibly worn by either individual, though this could be due to the angle or distance of the shot. There is no interaction between the workers and any machinery or vehicles in the immediate vicinity, so proximity to a moving forklift cannot be assessed based on this still image alone.

[16.0s - 23.0s]: Both individuals wear yellow high-visibility safety vests. One person is near stationary shelves, while the other operates a forklift near pallets. No safety helmets are visible. The forklift operator maintains appropriate proximity to the machine during operation.

[20.0s - 25.067s]: **Focus Area Descriptions**

Personal Protective Equipment (PPE):

- **High-Visibility Safety Vests:** Both workers are visibly wearing yellow safety vests, which comply with standard PPE requirements for visibility in industrial settings.
- **Safety Helmets:** Neither worker is wearing a helmet; however, no helmets are visible in the immediate vicinity either.

Proximity to Moving Forklift:

- The forklift maintains a safe distance from the first worker while passing through the aisle. There is no indication of direct interaction or potential collision risk between the forklift and the stationary worker. The second worker, though closer to the forklift's path, remains focused on their task without apparent interference from the vehicle.

Finding 2: Inspection Finding

TIMESTAMP 10:42:45
SOP SECTION Safety Protocols
COMPLIANCE SCORE 60%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 7.0s]: **Summary:** In the video, one worker wears a yellow safety vest and a white hard hat while another worker lacks visible PPE. No forklift movement is observed.

[4.0s - 11.0s]: Yes; all four workers wear high-visibility vests and helmets consistently across all frames.

[8.0s - 15.0s]: Both workers wear yellow high-visibility vests; no safety helmets are visible. The forklift maintains a safe distance from both workers throughout the observed frames.

[12.0s - 19.0s]: Yes, all three workers are wearing yellow safety vests and helmets, indicating full compliance with PPE requirements. No forklift is observed in motion during this segment, so proximity risks are not applicable.

[16.0s - 23.0s]: Three people are present in the scene. One person is wearing a yellow safety vest and a white hard hat, while another person is wearing a yellow safety vest but no helmet. The third person is also wearing a yellow safety vest and a white hard hat. There is no indication of proximity to a moving forklift in the current frames.

[20.0s - 25.067s]: Yes, the worker is wearing a yellow safety vest and a white hard hat, indicating proper PPE use. The forklift remains stationary until it starts moving away from the worker, maintaining a safe distance. No unsafe proximity or interaction is observed.

Finding 3: Inspection Finding

TIMESTAMP 10:42:56
SOP SECTION Safety Protocols
COMPLIANCE SCORE 50%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 7.0s]: Yes

- [4.0s - 11.0s]:
1. **Personal Safety Vest:** One worker wears a yellow safety vest (visible), the other does not.
 2. **Safety Helmets:** Neither worker wears a helmet.
 3. **Proximity to Moving Forklift:** No forklift is visible in the frames.

[8.0s - 15.0s]: No PPE violations detected.

[12.0s - 19.0s]: No PPE violations were detected. No individuals are wearing high-visibility vests or helmets. No proximity issues involving the forklift were observed.

[16.0s - 23.0s]: **Final Answer:**
The forklift operator is wearing a **yellow safety vest**, while the pedestrian has **no visible PPE**. The pedestrian is **not in close proximity** to the forklift.

[20.0s - 25.067s]: **Focus Area Descriptions**

Personal Protective Equipment (PPE)

- **High-Visibility Safety Vests:** One worker is wearing a yellow safety vest, indicating adherence to PPE requirements for visibility in the workspace.
- **Safety Helmets:** No safety helmets are visibly worn by either worker in this segment of the video.

Proximity to Moving Forklift

- The red forklift is stationary and located on the far left side of the frame, maintaining a safe distance from both workers. There is no interaction between the forklift and the workers observed in this clip.

Finding 4: Inspection Finding

TIMESTAMP 10:43:07
SOP SECTION Safety Protocols
COMPLIANCE SCORE **50%**



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 7.0s]: No PPE-related violations were detected. The forklift remains stationary, so proximity risks are not applicable.

[4.0s - 11.0s]: **General Scene:**
An indoor warehouse setting with shelving units, a red forklift, and two workers. The floor is concrete, and the ceiling has exposed beams and lighting fixtures.

Personal Protective Equipment (PPE):

- **High-Visibility Safety Vests:** One worker wears a bright yellow safety vest.
- **Safety Helmets:** No helmets are visibly worn by either worker.

Proximity to Moving Forklift:

- The worker in the yellow vest is positioned near the forklift but maintains a safe distance as the forklift advances.
- The operator of the forklift is seated inside the vehicle and does not appear to be interacting directly with the other worker.

[8.0s - 12.733s]: Yes; Yes; Yes