

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-03-02 12:49:02
VIDEO SOURCE	stream_93f7252b_2026-03-02T12-46-56.130842Z_st_20.367_end_45.400_clip_1.mp4, stream_93f7252b_2026-03-02T12-46-56.130842Z_st_56.967_end_82.000_clip_2.mp4, stream_93f7252b_2026-03-02T12-46-56.130842Z_st_85.067_end_110.100_clip_3.mp4, stream_93f7252b_2026-03-02T12-46-56.130842Z_st_115.867_end_128.567_clip_4.mp4
OVERALL VERDICT	FAIL

SUMMARY: The inspection revealed consistent failures in PPE compliance, particularly with safety helmets and high-visibility vests, across multiple events. While some individuals adhered to safety protocols, critical violations involving missing PPE were observed, posing significant safety risks in the industrial environment.

PROJECTED IMPROVEMENTS

- Implement mandatory PPE checks at entry points to ensure all workers are equipped with safety helmets and high-visibility vests before starting tasks.
- Conduct regular safety training sessions to reinforce the importance of PPE compliance and the risks associated with non-compliance.
- Establish clear disciplinary actions for repeated PPE violations to encourage adherence to safety protocols.

POSITIVE HIGHLIGHTS

- In some instances, workers were observed wearing both high-visibility vests and safety helmets correctly, demonstrating adherence to safety standards.
- The presence of a stationary forklift in one event did not lead to unsafe proximity issues, indicating some level of awareness regarding vehicle safety.
- There were no reported incidents of workers being in dangerously close proximity to operating forklifts in the majority of observations.

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 12:48:20
SOP SECTION Safety Protocols
COMPLIANCE SCORE 60%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 7.0s]: **Personal Protective Equipment (PPE) Compliance:**

- **High-Visibility Safety Vests:** Both workers are visibly wearing yellow safety vests, which comply with PPE standards for visibility in industrial settings.
- **Safety Helmets:** Neither worker is seen wearing a helmet; only the upper body and arms are visible, so this cannot be confirmed.

Proximity to Moving Forklift: No forklift is visible in the scene, so there is no interaction or risk assessment related to a moving vehicle.

[4.0s - 11.0s]: There are three people in the scene, none of whom are wearing safety helmets. All three are wearing yellow safety vests. None of them are near a forklift.

[8.0s - 15.0s]: Yes; both wear yellow safety vests and white hard hats, meeting PPE standards. No interaction with a moving forklift is observed.

[12.0s - 19.0s]: Yes; No; Sufficient distance maintained

[16.0s - 23.0s]: Specific Focus Areas:


Personal Protective Equipment (PPE):

- **High-Visibility Safety Vests:** Present on both workers. One worker wears a yellow vest, and the other also wears a yellow vest. Both remain stationary throughout the frames.
- **Safety Helmets:** Not visibly worn by either worker during the observed frames.

[20.0s - 25.067s]: Both individuals wear yellow high-visibility vests. One person is not wearing a safety helmet, while the other's headwear is obscured. The forklift approaches the first worker without any apparent risk of collision.

Finding 2: Inspection Finding

TIMESTAMP 12:48:31
SOP SECTION Safety Protocols
COMPLIANCE SCORE 60%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 7.0s]: Two individuals wearing yellow safety vests and hard hats are present; one walks past the other while carrying a box. No forklift is visible in motion.

[4.0s - 11.0s]: Yes; Yes; Appropriate

[8.0s - 15.0s]: Focus Area Descriptions:

Personal Protective Equipment (PPE):

- **High-Visibility Safety Vests:** Both workers are visibly wearing yellow safety vests, complying with standard PPE requirements for visibility in industrial settings.
- **Safety Helmets:** No safety helmets are observed being worn by either worker in the provided frames.

Proximity to Moving Forklift:

- Neither worker is shown in close proximity to the stationary forklift; both remain in separate sections of the aisle, maintaining a safe distance from the machinery.

[12.0s - 19.0s]: Focus Area Descriptions

Personal Protective Equipment (PPE)

- **High-Visibility Safety Vests:** All workers are visibly wearing yellow high-visibility safety vests with reflective stripes.
- **Safety Helmets:** At least two workers are wearing hard hats, while others may have them off but remain within safe zones relative to machinery like forklifts.

Proximity to Moving Forklift

- No immediate interaction between workers and the forklift is evident in these frames. The forklift's presence is implied but not directly observed, so exact distances cannot be confirmed visually.


[16.0s - 23.0s]: Two workers wear high-visibility safety vests; one is near the center-left, and the other is toward the right side. A third worker without a vest walks through the aisle. No forklift is present.

[20.0s - 25.067s]: Answer:

In the video, one person is wearing a yellow safety vest and a white hard hat, while another individual's PPE is unclear. The worker in the yellow vest is near a forklift that appears to be in operation.

Finding 3: Inspection Finding

TIMESTAMP 12:48:44
SOP SECTION Safety Protocols
COMPLIANCE SCORE 60%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[4.0s - 11.0s]: Not applicable

[8.0s - 15.0s]: No PPE detected; no interaction with forklift

[12.0s - 19.0s]: **Focus Area Descriptions**

Personal Protective Equipment (PPE):

- **High-Visibility Safety Vests:** One worker is wearing a bright yellow safety vest, which is clearly visible and covers most of their torso. The vest includes reflective stripes for enhanced visibility.
- **Safety Helmets:** The same worker in the yellow vest is also wearing a matching yellow hard hat, properly secured on their head.

Proximity to Moving Forklift:

- The red forklift is stationary throughout the observed frames and does not move closer to any individuals in the scene. There is no interaction between the forklift and the workers present.

[16.0s - 23.0s]: No PPE detected; individual lacks high-visibility vest or helmet.

[20.0s - 25.067s]: Two individuals wear yellow safety vests and white hard hats, while one worker lacks visible PPE. Two individuals are wearing white hard hats. No forklift is visible in motion.

Finding 4: Inspection Finding

TIMESTAMP 12:48:56
SOP SECTION Safety Protocols
COMPLIANCE SCORE 40%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 7.0s]: Focus Area Descriptions

Personal Protective Equipment (PPE)

- **High-Visibility Safety Vests:** One worker on the right side of the frame is visibly wearing a yellow safety vest, which is appropriate for visibility in an industrial setting. No other individuals are seen wearing similar vests.
- **Safety Helmets:** None of the workers in the scene are wearing safety helmets.

Proximity to Moving Forklift

- The worker interacting with the forklift maintains a safe distance while standing beside it, allowing the forklift to operate without obstruction. There is no indication of unsafe proximity between the two.

[8.0s - 12.733s]: Final Answer:

In the video, one worker (on the right) wears a **yellow safety vest** and a **white hard hat**, meeting PPE standards. The second worker (left) lacks visible PPE. Both remain at a **consistent distance from the stationary forklift** throughout the frames. No violations or unsafe behaviors are evident in their positioning relative to the forklift.