

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-03-02 13:03:25
VIDEO SOURCE	stream_dbfd6ece_2026-03-02T13-01-18.899828Z_st_1.267_end_22.667_clip_1.mp4, stream_dbfd6ece_2026-03-02T13-01-18.899828Z_st_33.367_end_58.400_clip_2.mp4, stream_dbfd6ece_2026-03-02T13-01-18.899828Z_st_89.167_end_102.433_clip_3.mp4
OVERALL VERDICT	FAIL

SUMMARY: The inspection revealed critical safety violations across multiple events, with consistent failures in PPE compliance including the absence of high-visibility vests and safety helmets. While one event demonstrated strong adherence to safety protocols, the recurring lack of essential protective equipment in other events poses significant risks and results in an overall failure.

PROJECTED IMPROVEMENTS

- Implement mandatory PPE checkpoints at entry points to ensure all individuals are equipped with high-visibility vests and safety helmets before entering work areas.
- Conduct regular safety audits and training sessions to reinforce the importance of PPE compliance and address recurring lapses.
- Establish clear disciplinary actions for non-compliance with PPE requirements to emphasize the critical nature of these safety measures.

POSITIVE HIGHLIGHTS

- Event 2 demonstrated exemplary compliance with PPE standards, showing consistent use of high-visibility vests and safety helmets by all individuals.
- In Event 2, safe distances from moving forklifts were maintained, indicating effective awareness of proximity risks.
- The quick rectification of initial PPE lapses in Event 2 highlights responsiveness in correcting safety violations.

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 13:02:58
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 0%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE is observed.

[4.0s - 9.0s]: No PPE violations detected. Person not wearing high-visibility vest or helmet. No interaction with forklift observed.

[8.0s - 13.0s]: Neither individual is wearing high-visibility safety vests or helmets; both are dressed casually. No moving forklift is observed nearby.


[12.0s - 17.0s]: Focus Area 1: Presence of high-visibility safety vests - Not present; the individual is wearing casual clothing without any PPE.
Focus Area 2: Presence of safety helmets - Not present; the individual lacks head protection.
Focus Area 3: Proximity to the moving forklift - The forklift is

[16.0s - 21.0s]: No PPE observed; no forklift present.

[20.0s - 21.433s]: No PPE observed.

Finding 2: Inspection Finding

TIMESTAMP 13:03:10
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 95%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE (high-visibility vests, helmets) observed; no interaction with a moving forklift noted.

[4.0s - 9.0s]: **Focus Area Descriptions**

Personal Protective Equipment (PPE)

- **High-Visibility Safety Vests:** A person is seen wearing a bright yellow safety vest, indicating compliance with PPE standards for visibility in an industrial setting.
- **Safety Helmets:** The same individual wears a hard hat, reinforcing adherence to head protection requirements.

Proximity to Moving Forklift

- No forklift is actively moving in the observed frames; therefore, proximity to a moving forklift cannot be assessed.
- [8.0s - 13.0s]: Yes; No; Inside the forklift cabin
- [12.0s - 17.0s]: Yes; Yes; No other individuals or objects are in close proximity to the forklift during its movement.
- [16.0s - 21.0s]: Yes; Yes; Operator is seated on the forklift, maintaining a steady position as they drive forward. No nearby personnel or objects directly in the immediate vicinity of the forklift's path.
- [20.0s - 25.0s]: Yes; both workers wear yellow safety vests and white hard hats, indicating proper PPE use. They remain within safe proximity to the forklift during the observed period.
- [24.0s - 25.067s]: Yes; Yes; Close proximity to the forklift, but no immediate interaction observed.

Finding 3: Inspection Finding

TIMESTAMP 13:03:20

SOP SECTION PPE & Safety Protocols

COMPLIANCE SCORE **0%**



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

- [0.0s - 5.0s]: No PPE violations observed. Individuals are not wearing safety vests or helmets. No interaction between workers and the forklift is shown.
- [4.0s - 9.0s]: No PPE violations detected.
- [8.0s - 13.0s]: No PPE observed on any individuals. The person in the foreground walks without interacting with the stationary forklift.
- [12.0s - 13.3s]: No PPE is observed in the video.