

Repair Estimate

This is not a registered claim, coverage confirmation, approval, or settlement decision.

Intake summary

Intake reference	INTAKE-2026-001	Current status	Policy reference supplied
Policy number	MOTOR-1001		
Claimant	Aarav	Contact	+91 90000 10001
Vehicle	Maruti Baleno	Registration	DEMO-KA-1001
Incident type	Collision	Incident date	22 September 2026
Location	Hyderabad		

Incident narrative

The vehicle made contact with a concrete pillar while reversing in a parking area. The rear bumper and left tail lamp show visible damage. No injuries or third-party property damage were reported.

Reported damage

Rear bumper dent and scratches; left tail lamp cracked.

Evidence status

Damage photographs available; provisional repair estimate included below.

Provisional repair estimate

Repair item	Scope	Estimated amount
Rear bumper repair and repaint	Dent removal, surface preparation, and paint	INR 12,500
Left tail lamp replacement	Replacement assembly and fitting	INR 6,800
Inspection and labour	Damage inspection and workshop labour	INR 2,200
Estimated total	Before final inspection	INR 21,500

Estimate is indicative and subject to workshop inspection, parts availability, and final assessment.