



The harbor survey began on a cold morning in March. Inspectors walked the length of each dock and noted every cracked piling, loose plank, and rusted cleat. Dock A showed the worst damage along its north side. Tide gauges were checked against the harbor records.



The breakwater held up better than anyone expected. Only two sections needed new stone after the storms. The crew finished the inspection before the evening tide and filed a report with the harbor master that recommended repairs to Dock A before the summer.