```
C:\COS201_Project\.venv\Scripts\python.exe C:\Users\ACER\Downloads\golden_model.py
Data: 10110010
Parity: 0
Error enable: 0
Received data: 10110010
Error flag: 0
PASS
--------------------
Data: 10110010
Parity: 0
Error enable: 1
Received data: 10110110
Error flag: 1
PASS
--------------------
Data: 11111111
Parity: 0
Error enable: 0
Received data: 11111111
Error flag: 0
PASS
--------------------
Data: 11111111
Parity: 0
Error enable: 1
Received data: 11111011
Error flag: 1
PASS
--------------------
Data: 00000000
Parity: 0
Error enable: 0
Received data: 00000000
Error flag: 0
PASS
--------------------

Process finished with exit code 0

```